

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, हिलसा (नालन्दा)।
Email:- ee.hilsa.rwd@gmail.com

पत्र संख्या ...1186(317)

हिलसा/दिनांक ...27-7-2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, हिलसा।

सेवा में,

नोडल पदाधिकारी,
MR 3054,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:-

नई अनुरक्षण निति 2018 शीर्ष के अंतर्गत वित्तीय वर्ष 2021-22 में व्यय हेतु
आवंटन की मांग।

महाशय,

उपर्युक्त विषयक नई अनुरक्षण निति 2018 शीर्ष के अंतर्गत वित्तीय वर्ष 2021-22 में
व्यय हेतु संलग्न विवरणी के अनुसार रू0 246.39846 (रू0 दो करोड़ छियालीस लाख उनचालीस
हजार आठ सौ छियालीस मात्र) रुपये का आवंटन उपलब्ध कराने की कृपा की जा ताकि किये
गये कार्यों का भुगतान किया जा सके।

अनु:- यथोक्त।

विश्वसभाजन

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, हिलसा।

Requisition Formate for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)
Name of Works Division :-Hilsa

SI No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (In km)	Amount of (In Lakh)	Initial Rectification with Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/NA/HIL/19/0002	Dhanawan Path to Shekhpura Rupaspur	NEA220002773	539/08-02-2019	4.512	155.44800	98.73962	46.58258	25/MBD/2019-20	03.04.2020	18.07.21	2860	25.00	5.00	0.00	0.00	98.73962	Surface Work Complete
2	RM/NA/HIL/19/0002	Ekangar Bihar PWD to Dhanbaha Road	NEA220002779	539/08-02-2019	1.222	42.94300	27.63245	12.43379	25/MBD/2019-20	03.04.2020	18.07.21	3085	25.00	5.00	0.00	0.00	27.63245	Surface Work Complete
3	RM/NA/HIL/19/0003	Hilsa fatuha road to gulani	10200802039	1826/24.06.19	0.554	16.37570	9.43098	5.70937	05/MBD/2020-21	27.09.21	18.07.21	2747	25.00	5.00	0.00	0.00	9.43098	Complete
4	RM/NA/HIL/19/0003	hilsa fatuha road to juniyar	10200802040	1826/24.06.19	1.420	61.01000	41.28209	14.69668	05/MBD/2020-21	27.09.21	18.07.21	2641	25.00	5.00	0.00	0.00	41.28209	Complete
5	RM/NA/HIL/19/0003	Teka bihar milki path to makhdumpur	10200901011	1826/24.06.19	1.500	65.85900	44.16840	15.43384	05/MBD/2020-21	27.09.21	18.07.21	3203	25.00	5.00	0.00	0.00	44.16840	Complete
6	RM/NA/HIL/19/0003	Hilsa harbanspur to kurseta	10200802041	1826/24.06.19	0.890	37.88040	25.14492	9.17454	05/MBD/2020-21	27.09.21	18.07.21	2843	25.00	5.00	0.00	0.00	25.14492	Complete
7	RM/NA/HIL/20/0005	Diawan-Berthu Rd. to Khokhana	10200802022	2775/19.08.2020	0.450	22.99200	15.71172	4.67360	21/MBD/2020-21	26.12.21	27.07.21	2245	25.00	5.00	0.00	0.00	15.71172	Surface Work Complete
TOTAL																		246.39846

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.


2 Up-to-date Physical Progress has been uploaded in MIS

- Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
- Up-to-date Physical Progress has been uploaded in MIS.


Executive Engineer
RWD, Works Division, Hilsa

File : F:\18071543.Xls, Section No. : 60, Eqn : $Y = 0 \cdot X^2 + 0.898 \cdot X + 377.8$

Name of Customer : MS Global Solutions, Name of Work/ Road : Ekangar Bihar Road to Dhanbaha, Lab Job number



for
18/12/2018
20


Executive Engineer
Rural Works Department
Works Division, Hilsa

Name of Contractor:-MS Global Solutions

Name of Road:-Ekangar Bihar Road to Dhanbaha Road

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	UIV	CATEGORY ROAD	IRI	Latitude	Longitude	Event
18/7/21	15:40:0	60	0.1	360	0	3600	3610	G	4.75	25.21016	85.386245	Normal
18/7/21	15:40:20	60	0.1	310	20.2	3100	3161	G	4.22	25.211	85.386532	Normal
18/7/21	15:40:20	60	0.1	290	10.1	2900	2982	G	4	25.21111	85.387272	Normal
18/7/21	15:40:55	60	0.1	310	20.2	3100	3161	G	4.22	25.21198	85.387407	Normal
18/7/21	15:41:0	60	0.1	360	30.3	3600	3610	G	4.75	25.21292	85.38734	Normal
18/7/21	15:41:0	60	0.1	300	20.2	3000	3071	G	4.11	25.21375	85.387508	Normal
18/7/21	15:41:31	60	0.1	270	30.3	2700	2802	G	3.79	25.21452	85.387995	Normal
18/7/21	15:41:31	60	0.1	300	20.2	3000	3071	G	4.11	25.21543	85.388298	Speed Breaker
18/7/21	15:42:0	60	0.1	330	20.2	3300	3341	G	4.43	25.21627	85.38843	Normal
18/7/21	15:42:6	60	0.1	260	40.4	2600	2712	G	3.68	25.21713	85.388618	Normal
18/7/21	15:42:6	60	0.1	300	20.2	3000	3071	G	4.11	25.2181	85.388803	Normal
18/7/21	15:42:6	60	0.1	310	20.2	3100	3161	G	4.22	25.219	85.388737	Normal
18/7/21	15:42:41	60	0.022	220	30.3	2200	2353	G	3.24	25.21919	85.388535	Normal
Total			1.222	3920	282.8	39200	40106		53.63			

$Y = 0 * X^2 + 0.898 * X + 377.8$			
X = 13636			
Y = 12622			
(R) RURAL ROAD			
Good	Average	Poor	
<4000	4001-5000	>5001	

for
18/7/2021
28/08/2021

R271717
Executive Engineer
Rural Works Department
Works Division, Hlsa