

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Aurai / Tara Jiwar Koat tola Hote hue to Thaneer
Loso.

(A) For Road:

1. Damage Location/Chainage :- many places.
2. Damage Length :- 0.0332 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor.
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- 0.0332 km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, मुगझरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road TARA JIWAR KOAT TOLA HOTE HUE to JHAUWA L050


District Muzaffarpur

Block Aurai


Division Muzaffarpur East-2

Length of Road (in Km) 1.750 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	10.526
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	10.526
TOTAL COST OF PROJECT IN LACS =		10.526


11/11/21

JE
RWD



11/10/21

AE
RWD


11/11/21

EE
RWD

Technically approved for Rs 10.526 lac
(Rupees Ten lac fifty two thousand six hundred only)


18-11-21
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर