

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT of cost				
(1/1)	Fixing Bench mark pillar				
	V.T.M.B.P. No - (5)				
	item (1) - 2 No				
	at 4078.20/m -				8156.00
(2/1)	Reference pillar				
	V.T.M.B.P. No - (5)				
	item (2) - 6 No				
	at 1884.59/m -				11308.00
(5/2)	cleaning and carrying				
	Road land				
	V.T.M.B.P. No - (5)				
	item (3) - 1.02 ha				
	at 49496.70/ha -				52961.00
(4/3)	cost of embankment				
	with approved section				
	V.T.M.B.P. No - (6)				
	item (4) - 900.76 m ³				
	at 130.86/m ³ -				117873.00
(8/4)	Construction of subgrade				
	and earthen shoulder				
	V.T.M.B.P. No - (6)				
	item (5) - 3278.07 m ³				
	at 176.47/m ³ -				578481.00
(8/1)	P/V and Fixing logo				
	of project				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
V.T.M.B.P.N (6)					
item (6) — 940.56 m ³					
→ 130.86 / m ³ —→ 117873 =					
→ 940.567 / m ³ —→ 18811 =					
(7/5) P/V C.S.P with well graded material					
V.T.M.B.P.N (6)					
item (7) — 1246.59 m ³					
→ 2924.81 / m ³ —→ 3646039 =					
(8/6) providing W.B.M					
Grade - 3					
V.T.M.B.P.N - (8)					
item (8) — 432.81 m ³					
→ 3284.48 / m ³ —→ 1421642 =					
					58,55271 =
less 2.10% below					122961 =
					57,32,310 =
Add C.S.T - 12% —					6,87,877 =
Add 1% less 1% —					57,323 =
					64,77,510 =
Less previous payment					49,04,791 =
					15,72,719 =
A/Cyranay					
01/04/21					
TL					

Continuation

Scanned with CamScanner