

(832) N/W - Temporary Restoration of Road from
Schedule XLV-Form No. 134
6034-6027 Triveni to Bherihosi

(FDR-2020)

Raxaul.

DIVISION

राखौली

SUB-DIVISION

Measurement Book

Name of Work-

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH-2245 (FDR)					
Authority- E.E. RWD, Raxaul.					
Agency- Departmental.					
N/W- Temporary Restoration of Road from L034- L027 T. Diveni to Bherihori					
Date of entry- 21/8/20					
① P/L of Bridge Bats including light summing - all work per CH					

1100-1200	55m	4.05m	0.35m	= 77.963m ³
1250-1450	3m	1.25m	0.30m	= 1.125m ³
2250-2500	5m	1.75m	0.35m	= 3.063m ³
3150-3300	4m	2.10m	0.35m	= 2.940m ³
Total =				85.09m ³

[Signature]
21/8/20
J.E.

[Signature]
AE 21/8/20
Ravi gaur

Continuation

Continuation

कार्यपालक अभियंता का कार्यलय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मोतिहारी।

पत्रांक 2769 (अनु०)

मोतिहारी / दिनांक 28-12-2020

प्रेषक :- कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।

सेवा में,

अधीक्षण अभियंता,
ग्रामीण कार्य विभाग,
कार्य अंचल, मोतिहारी।

विषय :- कार्य प्रमंडल रक्सौल अन्तर्गत वर्ष-2020 में बाढ़ एवं अतिवृष्टि के कारण क्षतिग्रस्त पथों को मोटेरेबुल करने हेतु किए गए कार्यों की जाँच के संबंध में।

प्रसंग :- मु०अ०-04 (मु०) विवेद (कार्य)-23-40/216-2789 पटना, दिनांक-21.08.2020
एवं भवदीय कार्यालय आदेश ज्ञापक-1344 दिनांक-28.08.2020


महोदय,

उपर्युक्त विषयक प्रसांगिक पत्र के अनुपालन में कार्य प्रमंडल, रक्सौल द्वारा उपलब्ध कराये गये मोटेरेबुल पथों की सूची में अंकित पथों का अधोहस्ताक्षरी के द्वारा निरीक्षण किया गया निरीक्षण के दौरान कार्य प्रमंडल, रक्सौल द्वारा प्रतिवेदित सभी पथों में मोटेरेबुल का कार्य कराया गया है एवं वर्तमान यातायात चालू है।

सादर सूचनार्थ एवं अग्रेत्तर कार्यवाई हेतु समर्पित।

अनु:- निरीक्षण किए गए पथों की सूची।

विश्वासभाजन,


28/12/20
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।


28/12/20
र. ए.

List of Road Damaged due to Flood 2020-21

SINO	Division	Road Name	Scheme	Road Status	is Maintenance (Y/N)	is Agreement (Y/N)	Length (in Km.)	Length of Damage Part Due to Flood in M	Actual Restoration Amount : (in Lacs)	Remarks	Start Latitude	Start Longitude	End Latitude	End Longitude	Block
1	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
2	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
3	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
4	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
5	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
6	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
7	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
8	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
9	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
10	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
11	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
12	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
13	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
14	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
15	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
16	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
17	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
18	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
19	Raxaul	1038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	No	No	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa

28/1/21
E.E. (R.D.D.)
Mokherjee