

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर

पत्रांक 1135 अगु दिनांक 02/06/2021

प्रेषक:— कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,
अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:— शीर्ष New Maintenance Policy-2018 मद में आवंटन उपलब्ध कराने के संबंध में।
महाशय,

उपर्युक्त विषयक शीर्ष New Maintenance Policy-2018 मद अन्तर्गत व्यय हेतु
विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की

कृपा की जाये।

अनु०—यथोक्त।

विश्वासभाजन



कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर

2/6/21

FROM GFR 19-A

(See Government of India's Division (I) below Rule- 150)

Form of Utilization Certificate upto 31.05.2021

PIU- E.E., R.W.D. Works Division, Samastipur

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto	152836088.00	Certified that out of Rs.152836088.00 received upto 31.05.2021 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.143462430.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margine for which it was sanctioned and that the balance of Rs. 9373658.00 remaining unutilized at the end of period under report.
			15,28,36,088.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.


Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.


Sr. Divisional Account Officer
R.W.D (W) Division Samastipur


Executive Engineer
Works Division Samastipur
Rural Works Dipartment


Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)


RWD Works Division : Samastipur																		
Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date	Administrative Length (Km)	Administrative Amount (In Lakh)	Agreement Initial Rectification with Surface Renewal	Agreement 5 Year Routine Maintenance	Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (In Lakh)	Upto date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RMSASA M/19/0011	NEA27000667	Khorise Keshopati	2173 & 06.07.2019	4.90	157.17	87.70249	43.35044	01(MBD) 2020-21 06.05.2020	05.02.2021	Complete	3339	25	5.20	0	0	87.702	BT Completed
2	RMSASA M/19/0011	32010102115	Karpurigram Prachayat bhawan se Ramkrishanpur	2173/ 07.06.19	0.55	17.8739	9.27563	5.22978	01(MBD) 2020-21 06.05.2020	05.02.2021	Complete	3660	25	5.2	0	0	9.275	BT Complete
Total						175.04390	96.97812	48.58022							0.000	0.000	96.977	

- 1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
2 Up-to-date Physical Progress has been uploaded in MIS

Sr. Divisional Account Officer
R.W.D (W) Division Samastipur

Executive Engineer
RWD (W) Div. Samastipur

File : D:\bump\Integrator\RWDDiv Samastipur\KARPURIGRAM GRAM PANCHAYAT BHAVAN SE.xlsx. Section No.
Name of Customer : M/S. Ramsagar Rai and co, Name of Work/ Road : Karpurigram panchayat bhavan se



Shantish
25/05/2021
JE


[Signature]
25/5/21
Executive Engineer
R. W. D. Works Division
Samastipur
25/5/21

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event			
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD						
8/5/21	19:28:46	62	0.1	370	0	3100	3635	G	25.86768	85.716363	Curve	$Y = 0 * X^2 + 1.136 * X + 132.5$		
8/5/21	19:29:00	62	0.1	350	10.1	3500	4108	A	25.86818	85.715505	Curve	$Y = 3313$		
8/5/21	19:29:21	62	0.1	330	10.1	3300	3881	G	25.86833	85.714595	Normal			
8/5/21	19:29:21	62	0.1	420	20.2	3600	4103	A	25.86836	85.713618	Curve			
8/5/21	19:30:00	62	0.1	350	20.2	2900	3508	G	25.86819	85.712677	Normal	(R) RURAL ROAD		
8/5/21	19:30:00	62	0.1	330	20.2	3300	3881	G	25.86804	85.711173	Curve	Good	Average	Poor
8/5/21	19:30:32	62	0.1	260	20.2	2600	3086	G	25.86816	85.71079	Normal	<4000	4001-5000	>5001
8/5/21	19:30:32	62	0.1	290	20.2	2900	3426	G	25.86825	85.709763	Normal			
8/5/21	19:31:78	62	0.1	280	10.1	2800	3313	G	25.86868	85.70882	Normal			

Santhosh
25/05/2021
JTC

Santhosh
Executive Engineer
R. V. D. Works
Samastipur
21/6/21

File : D:\bumpE ntegrate\RWD div Samastipur\KHAIRI SE KESHOPATTI.xlsx Section No. :90, Eqn :test
 Name of Customer :M/S Ram sagar ray and co, Name of Work/ Road :khori se Keshoptti, Lab Job number :



[Signature]
 02/06/21
 JE

[Signature]
 2.6.21
 Executive Engineer
 R. W. D. Works Division
 Samastipur
[Signature]
 2/6/21

Date	Time	Section	No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitud	Event	Y = 0 * X ^ 2 + 1.136 * X + 132.5		
1/6/21	9:18:0		90	0.1	350	10.1	2500	3108	G	25.82912	85.78423	Normal			
1/6/21	9:18:16		90	0.1	390	10.1	1900	2562	G	25.82849	85.78357	Normal			
1/6/21	9:19:25		90	0.1	340	0	3400	3994	G	25.82777	85.78306	Normal			
1/6/21	9:20:1		90	0.1	340	10.1	3400	4094	A	25.82712	85.78244	Curve	(R) RURAL ROAD		
1/6/21	9:20:36		90	0.1	460	10.1	2600	3358	G	25.8263	85.78207	Normal	Good	Average	Poor
1/6/21	9:20:36		90	0.1	360	20.2	3600	3922	G	25.82549	85.7818	Normal	<4000	4001-5000	>5001
1/6/21	9:21:0		90	0.1	320	20.2	3500	4067	A	25.82474	85.78145	Curve			
1/6/21	9:21:11		90	0.1	210	20.2	2100	2518	G	25.82412	85.78081	Normal			
1/6/21	9:21:11		90	0.1	190	20.2	1900	2290	G	25.82327	85.7803	Curve			
1/6/21	9:21:46		90	0.1	190	20.2	1900	2290	G	25.82264	85.77975	Normal			
1/6/21	9:22:0		90	0.1	250	30.3	2500	2972	G	25.82201	85.77899	Curve			
1/6/21	9:22:0		90	0.1	450	20.2	3500	4044	A	25.8213	85.77842	Curve			
1/6/21	9:22:22		90	0.1	350	30.3	3100	3708	G	25.82069	85.77781	Normal			
1/6/21	9:22:22		90	0.1	220	30.3	2200	2631	G	25.82007	85.77712	Curve			
1/6/21	9:22:22		90	0.1	180	30.3	1800	2177	G	25.8193	85.77658	Curve			
1/6/21	9:23:0		90	0.1	170	30.3	1700	2063	G	25.81845	85.77628	Curve			
1/6/21	9:23:0		90	0.1	250	20.2	2500	2972	G	25.81788	85.77559	Curve			
1/6/21	9:23:32		90	0.1	330	20.2	3300	3881	G	25.81745	85.77476	Speed Breaker			
1/6/21	9:23:32		90	0.1	300	20.2	3000	3540	G	25.8167	85.77434	Normal			
1/6/21	9:24:8		90	0.1	380	20.2	3800	4449	A	25.81591	85.77386	Normal			
1/6/21	9:24:8		90	0.1	340	10.1	3400	3994	G	25.81519	85.77343	Normal			
1/6/21	9:24:8		90	0.1	200	30.3	2000	2404	G	25.81444	85.77303	Normal			
1/6/21	9:24:43		90	0.1	160	30.3	1600	1950	G	25.81363	85.77256	Normal			
1/6/21	9:25:0		90	0.1	270	20.2	2700	3199	G	25.81286	85.77214	Normal			
1/6/21	9:25:0		90	0.1	190	20.2	1900	2290	G	25.81204	85.772	Curve			
1/6/21	9:25:18		90	0.1	340	10.1	3400	3994	G	25.8112	85.77126	Normal			
1/6/21	9:26:0		90	0.1	310	10.1	3100	3654	G	25.81041	85.77088	Speed Breaker			
1/6/21	9:26:0		90	0.1	270	10.1	2700	3199	G	25.80965	85.77064	Normal			
1/6/21	9:26:29		90	0.1	240	20.2	2400	2858	G	25.8088	85.77037	Normal			
1/6/21	9:26:29		90	0.1	280	20.2	2800	3313	G	25.80789	85.77008	Normal			
1/6/21	9:27:4		90	0.1	250	20.2	2500	2972	G	25.80709	85.76987	Culvert			
1/6/21	9:27:4		90	0.1	350	10.1	2500	3108	G	25.80626	85.76966	Normal			
1/6/21	9:28:0		90	0.1	410	10.1	2100	2790	G	25.80531	85.76951	Normal			
1/6/21	9:28:15		90	0.1	360	10.1	2600	3222	G	25.8045	85.76941	Normal			

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitud	Event	$Y = 0 * X^2 + 1.136 * X + 132.5$		
1/6/21	9:28:50	90	0.1	350	10.1	3500	4108	A	25.80364	85.76906	Speed Breaker			
1/6/21	9:29:25	90	0.1	430	10.1	3200	3817	G	25.80304	85.76833	Normal			
1/6/21	9:29:25	90	0.1	430	10.1	3500	4017	A	25.80258	85.76758	Curve			
1/6/21	9:30:0	90	0.1	430	10.1	3100	3717	G	25.80191	85.76668	Normal			
1/6/21	9:30:36	90	0.1	420	10.1	3200	3803	G	25.80188	85.76593	Normal			
1/6/21	9:31:0	90	0.1	350	10.1	3500	4018	A	25.80192	85.76498	Curve			
1/6/21	9:31:11	90	0.1	370	10.1	3100	3835	G	25.80148	85.76407	Normal			
1/6/21	9:42:0	90	0.1	380	0	3500	4049	A	25.81982	85.78	Curve			
1/6/21	9:42:21	90	0.1	340	10.1	3400	4094	A	25.81944	85.78111	Curve			
1/6/21	9:42:21	90	0.1	270	20.2	2700	3199	G	25.81951	85.78209	Curve			
1/6/21	9:43:0	90	0.1	290	20.2	2900	3426	G	25.81934	85.78295	Curve			
1/6/21	9:43:0	90	0.1	440	20.2	2400	3130	G	25.81892	85.78377	Normal			
1/6/21	9:43:32	90	0.1	270	20.2	2700	3199	G	25.81852	85.78471	Curve			
1/6/21	9:43:32	90	0.1	390	20.2	3100	3862	A	25.81831	85.78561	Curve			
1/6/21	9:44:0	90	0.1	320	20.2	3200	3767	G	25.81809	85.78662	Normal			

[Signature]
02/06/21
JE

[Signature]
2.6.21
Executive Engineer
R. W. D. Works Division
Samastipur
RW
2/6/21