

कार्यालय
कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
टिकारी।

पत्रांक:- 1043 अ-नु० /टिकारी ,

दिनांक:- 14.6.2021

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल
टिकारी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण,पटना।

विषय- 3054/MR New Maintenance Policy-2018 अंतर्गत आवंटित राशि का उपयोगिता
प्रमाण पत्र तथा आवंटन अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि इस प्रमण्डल अंतर्गत 3054/MR New Maintenance Policy-2018 अंतर्गत Tutuki to Usas पथ में चल रहे कार्यों के भुगतान हेतु उपयोगिता प्रमाण पत्र विहित प्रपत्र में संलग्न करते हुए आग्रह है कि माँग पत्र के अनुसार योजना में रुपये 80,75,807.00 (अस्सी लाख पचहत्तर हजार आठ सौ सात रुपये) मात्र का आवंटन उपलब्ध कराने की कृपा की जाय ।

अनु०- यथोक्त।

विश्वासभाजन

14/6/21

कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल, टिकारी।

14/6/2021

**OFFICE OF THE EXECUTIVE ENGINEER,
RURAL WORKS DEPARTMENT, WORKS DIVISION TEKARI.**

Requisition Format for Scheme Head:- MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)																							
Name of Works Division:- Tekari																							
Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up to date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks					
					Length (In Km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)															
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19					
1	MR-N/19-20 tikari/- 07	Tutuki to usas	15221033213	Lt.5546 Dt. 23.10.19	3.100	119.94400	80.75807	30.56434	47/MBD/3054 /MR/2020-21	25.06.2021	-	3184	25 mm	5.07	0.0	0.0	80.75807	RI का गण संलग्न।					
Total																							
Amount in Word:-Eighty Lakh Seventy Five Thousand Eight Hundred Seven Only.																							

14/06/21

Sr. D.A.O.,
RWD, Works Division, Tekari

8/11/21
Executive Engineer
RWD, Works Division, Tekari
14/6/2021

FORM GFR 19-A

(See Government of India's Decision (1) below Rule 150)
Form of Utilization Certificate up to the Month of **09-JUNE-2021**

S. No	Name of Scheme	Sanction No. & Date with Amount (In Rs.lacs)	Amount Received (in Rs.Lacs)	Particulars
1 2 3 4 5 6 7 8 9	Bihar Rural Roads New Maint. Policy 2018	Lt. No. 47/Encl. Dated 24.06.2020 Lt. No. 82/Encl. Dated 13.11.2020 Lt. No. 84/Encl. Dated 26.11.2020 Lt. No. 05/Encl. Dated 12.01.2021 Lt. No. 17/Encl. Dated 26.02.2021 Lt. No. 22/Encl. Dated 24.03.2021 Lt. No. 26/Encl. Dated 15.04.2021 Lt. No. 27/Encl. Dated 15.04.2021 Lt. No. 30/Encl. Dated 21.05.2021	98.21031 148.49067 199.17599 65.81907 10.83516 95.70700 78.50000 334.32100 462.46838	Certified that out of Rs. 1493.52758 Lakh received during the Financial Year 2021-22 (09-JUNE-21) in favour of Executive Engineer, RWD (W) Division, Tekari, Gaya, Bihar out of which a sum of Rs. 1207.56098 Lacs has been utilized for the purpose of New Maintenance Policy 2018 Under MR3054 Scheme as given in the margin for which it was sanctioned and that the balance of Rs. 285.96660 Lacs remaining unutilized at the end of the said period.
			1493.52758	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised :-


- (i) Works have been supervised by Executive Engineers/Superintending Engineer.
- (ii) Periodic inspection has been conducted by Executive Engineer/Superintending Engineer.
- (iii) Construction materials have been tested.
- (iv) Measurements have been recorded in the MBs and test check conducted by the Assistant.
- (v) All other codal formalities have been observed.

Physical Progress achieved :-

- (i) Construction of Road Works
- (ii) Construction of CD Works


Sr. Divisional Accounts Officer,
Rural Works Department,
Works Division, Tekari.


Executive Engineer,
Rural Works Department,
Works Division, Tekari.


09/06/2021

सहायक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य अवर प्रमंडल, कोंच।

पत्रांक:- २५५

दिनांक:- 14/06/21

जाँच प्रतिवेदन

प्रखण्ड का नाम	योजना का नाम	पथ की लम्बाई	S.D.B.C परत की मोटाई	बिटुमिन Content की मात्र	BUMP INTEGRATOR का Reading	अभियुक्ति
Konch	Tutuki to usas	3.100	25MM	5.07%	Reading Attached	Satisfactory


14/06/21
सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, कोंच।

Road Name- TUTUKI TO USAS

CONT.NAME:-ANIL KUMAR

Date	Time Section	Length in km	Bumps in mm	Speed		OR UIV		CATEGORY	Latitude	Longitude	Event
				Rate	mm/km	mm/km	mm/km				
14/6/21	7:59:36	43	220	10.1	2200	2631	G	ROAD	25.3927	84.742288	Normal
14/6/21	8:0:11	43	250	10.1	2500	2972	G		25.39347	84.743332	Normal
14/6/21	8:0:11	43	270	10.1	2700	3199	G		25.39643	84.744258	Normal
14/6/21	8:1:0	43	240	20.2	2400	2858	G		25.3958	84.745252	Normal
14/6/21	8:1:22	43	280	20.2	2800	3313	G		25.3892	84.745505	Normal
14/6/21	8:2:0	43	270	10.1	2700	3199	G		25.38022	84.745387	Normal
14/6/21	8:2:33	43	280	10.1	2800	3313	G		25.37122	84.745353	Normal
14/6/21	8:2:33	43	280	10.1	2800	3313	G		25.36207	84.745353	Normal
14/6/21	8:3:8	43	270	10.1	2700	3199	G		25.35282	84.74547	Normal
14/6/21	8:3:8	43	250	10.1	2500	2972	G		25.34375	84.745302	Normal
14/6/21	8:3:43	43	270	10.1	2700	3199	G		25.33477	84.745202	Normal
14/6/21	8:4:18	43	280	10.1	2800	3313	G		25.32578	84.745	Normal
14/6/21	8:4:18	43	290	10.1	2900	3426	G		25.31677	84.74468	Normal
14/6/21	8:5:0	43	270	10.1	2700	3199	G		25.30788	84.74436	Normal
14/6/21	8:5:29	43	270	20.2	2700	3199	G		25.29943	84.74404	Normal
14/6/21	8:6:0	43	280	20.2	2800	3313	G		25.29053	84.74377	Normal
14/6/21	8:6:4	43	280	10.1	2800	3313	G		25.2816	84.74348	Normal
14/6/21	8:6:40	43	260	20.2	2600	3086	G		25.27263	84.74338	Normal
14/6/21	8:7:15	43	270	20.2	2700	3199	G		25.2635	84.743182	Normal
14/6/21	8:7:15	43	270	20.2	2700	3199	G		25.25877	84.74372	Normal
14/6/21	8:8:0	43	270	10.1	2700	3199	G		25.25668	84.744747	Normal
14/6/21	8:8:25	43	250	10.1	2500	2972	G		25.24942	84.744242	Normal
14/6/21	8:9:1	43	270	10.1	2700	3199	G		25.24085	84.743855	Normal
14/6/21	8:9:1	43	270	20.2	2700	3199	G		25.23165	84.743922	Normal
14/6/21	8:9:36	43	290	20.2	2900	3426	G		25.223	84.743972	Normal
14/6/21	8:10:11	43	290	20.2	2900	3426	G		25.21527	84.74345	Normal
14/6/21	8:10:46	43	240	20.2	2400	2858	G		25.20623	84.74342	Normal
14/6/21	8:11:0	43	270	20.2	2700	3199	G		25.19803	84.74308	Normal
14/6/21	8:11:22	43	270	10.1	2700	3199	G		25.19103	84.743298	Normal
14/6/21	8:12:32	43	270	20.2	2700	3199	G		25.19663	84.743568	Normal
14/6/21	8:13:0	43	290	10.1	2900	3426	G		25.2028	84.744192	Normal
							AVERAGE				
							3184				

04/06/21
J.E.

14/06/21
A.E.

14/06/21
E.E.

$$Y = 0 * X^2 + 1.136 * X + 132.5$$

$$X = 2900$$

$$Y = 3426$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-500 >5001

1631

0	0.1	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9	1	1.1	1.2	1.3	1.4	1.5	1.6	1.7	1.8	1.9	2	2.1	2.2	2.3	2.4	2.5	2.6	2.7	2.8	2.9	3	3.1						
																																	Distance * 1000 m				

12/06/21
A. E.

~~12/11/2019~~

8/16/21
E.E