

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक...962(अ.प्र.)/बाँका

दिनांक 07/06/21

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।


विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 209.15000/-लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन


07-06-21

कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक...../बाँका

दिनांक

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 209.15000/-लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन

ह0/-

कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

ज्ञापांक-...../बाँका दिनांक

प्रतिलिपि :- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

07-06-21
कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

Form GFR 19-A

(See Government of India's Decision (1) below rule-15)
Form of utilization Certificate up to the Month May' 2021
MR/3054(NEW MAINTENANCE POLICY)

PIU-RWD(W), BANKA-2

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural roads under MR/3054(NEW MAINTENANCE POLICY)	विभागीय पत्रांक 37 दिनांक 27.05.2020 45(Encl)/18.06.2020 56(Encl)/12.08.2020 59(Encl)/18.08.2020 61(Encl)/26.08.2020 82(Encl)/13.11.2020 84(Encl)/26.11.2020 86(Encl)/11.12.2020 05(Encl) /12.01.2021 17 (Encl) / 26.02.2021 20 (Encl) /19.03.2021 22(Encl) /24.03.2021 27(Encl) /04.05.2021 30 (Encl) /21.05.2021 32 (Encl) / 28.05.2021	217.86340 30.12339 525.63100 320.50000 6.57325 88.44000 395.49360 368.11196 570.35090 604.70836 361.33115 82.05330 88.60000 58.28940 440.19502	Certified that out of Rs. 4158.26473 Lacs received during the years 2020-21 in favour of Ex. Engineer. RWD Bihar, RWD-2 Banka a sum of Rs. 3624.93652 Lacs has been utilized for the purpose of MR/3054(New Maintenance Policy) schemes as given in the margin for which it was sanctioned and that the balance of Rs 533.32821 remaining unutilized at the end of the period under.
	Total		4158.26473	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.



Kind of Checks exercised :-

- (i) Works have been supervised by Executive Engineer/ Superintending Engineer .
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- (iii) Measurement have been recorded in the MBs.
- (iv) All other code formalities have been observed.

3. Physical progress achieved :


- (i) Construction of Road Works.
- (ii) Construction of CD Works.


Sr. D.A.O.
Works Division Banka-II
Rural Works Department


Executive Engineer
Works Division Banka-II
Rural Works Department


Requisition Format for Scheme Head-MR (3054) Under Bihar Rural Road Maintenance Policy 2018 (Initial Rectification and Surface Renewal)
 Name of Division :- Banka-2

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion (Expected)	Value of IRI (in mm/km)	Thickness of Bitumen layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (in Lac)	Up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial rectification on with Surface renewal (in lac)	5 Years Routine Maintenance (in lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/19-20 Banka-2/16	Repair of Road from Simaramore Simarkola Road To Babbangama under MR/3054	20703502125	6276 02.12.2019	3.180	116.299	78.33736	31.92046	32/MBD/20-21 14.09.20	13.09.21	29.05.21	2441.125	25mm	5%	0.00000	0.00000	78.30000	Completed
2	MR-N/19-20 Banka-2/16	Repair of Road from Bounsi Irrigation Dam Road Ashanaha under MR/3054	20703502047	6276 02.12.2019	1.391	52.134	35.04891	14.39472	32/MBD/20-21 14.09.20	13.09.21	29.05.21	3244.071	25mm	5%	0.00000	0.00000	35.00000	Completed
3	MR-N/19-20 Banka-2/16	Repair of Road from BGP Dumkar Road To Rampurpabra under MR/3054	20703502062	6276 02.12.2019	3.840	143.226	95.95507	38.42796	32/MBD/20-21 14.09.20	13.09.21	29.05.21	3055.256	25mm	5%	0.00000	0.00000	95.85000	Completed
		Total															209.15000	


 Executive Engineer
 R.W.D.(W) Division
 Banka-2
 7/6/21

Lab Job number :7

Date :29-05-2021

Name of Customer :Satish Kumar

Name of Work/ Road :BGP Dumka Road To Rampurpabra


Sr.no	Location of test(in km)	Corrected U.I value(mm/km)	Road catagory
1	0.1	3272	G
2	0.2	3175	G
3	0.3	3659	G
4	0.4	2884	G
5	0.5	2593	G
6	0.6	3853	G
7	0.7	3369	G
8	0.8	2787	G
9	0.9	2400	G
10	1	2593	G
11	1.1	3466	G
12	1.2	3175	G
13	1.3	1528	G
14	1.4	2981	G
15	1.5	2981	G
16	1.6	3466	G
17	1.7	2981	G
18	1.8	3466	G
19	1.9	3659	G
20	2	2981	G
21	2.1	3756	G
22	2.2	3272	G
23	2.3	2787	G
24	2.4	2981	G
25	2.5	3272	G
26	2.6	3562	G
27	2.7	3078	G
28	2.8	3272	G
29	2.9	2981	G
30	3	2981	G
31	3.1	2303	G
32	3.2	2497	G
33	3.3	2109	G
34	3.4	3950	G
35	3.5	3078	G
36	3.6	2787	G
37	3.7	3659	G
38	3.8	3272	G
39	3.9	2289	G

BGP
29.5.21
R.E

Pritam
06.06.21
R.E

Am
06.06.21
EE

File : F:\BANK-2\07\29051324.Xls, Section No. : 7, Eqn : $Y = 0 * X^2 + 0.969 * X + 74.60$
 Name of Customer : Satish Kumar, Name of Work/ Road : BGP Dumka Road To Rampurpabra, Lab Job number : 7



0 0.10.20.30.40.50.60.70.80.9 1 1.11.21.31.41.51.61.71.81.9 2 2.12.22.32.42.52.62.72.82.9 3 3.13.23.33.43.53.63.73.83.9

Distance * 1000 m

[Signature]
 6.06.24
 EE

[Signature]
 Pritam
 06.06.24
 A.E

[Signature]
 06.06.24
 A.E

Name of Customer :

Name of Work/ Road :

Lab Job number :

Date :

Section No. :

Field Data :

Project Name :

Section No. :

Road Type :

Start S.M :

End S.M :

Station :

UTM Range :

Dist Range :

Start Location :


End Location :

Equation :

Print

Redlines Graph

Map View



Ref: 06.06.21
06.06.21
K.E

Ref: 06.06.21
06.06.21
K.E

for
06.06.21
HE

Pritam
06.06.21
A.E

28
12.5.64
B. G.

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR		CATEGORY ROAD	IRI	Latitude	Longitude	Event
						mm/km	UIV					
29/5/21	13:14:0	7	0.1	330	0	3300	3272	G	4.35	24.778945	87.051598	Curve
29/5/21	13:14:31	7	0.1	320	30.3	3200	3175	G	4.23	24.778718	87.05249	Normal
29/5/21	13:14:31	7	0.1	370	30.3	3700	3659	G	4.8	24.77888	87.053502	Culvert
29/5/21	13:15:7	7	0.1	290	10.1	2900	2884	G	3.88	24.77918	87.05441	Curve
29/5/21	13:15:7	7	0.1	260	10.1	2600	2593	G	3.53	24.779273	87.055302	Normal
29/5/21	13:15:42	7	0.1	390	20.2	3900	3853	G	5.03	24.779607	87.056077	Normal
29/5/21	13:15:42	7	0.1	340	30.3	3400	3369	G	4.46	24.779378	87.056968	Normal
29/5/21	13:16:0	7	0.1	280	30.3	2800	2787	G	3.77	24.779225	87.057962	Normal
29/5/21	13:16:17	7	0.1	240	30.3	2400	2400	G	3.3	24.779042	87.058938	Normal
29/5/21	13:16:17	7	0.1	260	20.2	2600	2593	G	3.53	24.779373	87.059645	Curve
29/5/21	13:16:17	7	0.1	350	30.3	3500	3466	G	4.58	24.77913	87.060538	Curve
29/5/21	13:16:52	7	0.1	320	30.3	3200	3175	G	4.23	24.778518	87.061278	Normal
29/5/21	13:17:0	7	0.1	150	40.4	1500	1528	G	2.2	24.778043	87.062053	Curve
29/5/21	13:17:0	7	0.1	300	40.4	3000	2981	G	4	24.777793	87.062962	Curve
29/5/21	13:17:0	7	0.1	300	20.2	3000	2981	G	4	24.778007	87.063922	Curve
29/5/21	13:17:28	7	0.1	350	20.2	3500	3466	G	4.58	24.778622	87.064325	Normal
29/5/21	13:17:28	7	0.1	300	30.3	3000	2981	G	4	24.779435	87.064595	Normal
29/5/21	13:18:0	7	0.1	350	30.3	3500	3466	G	4.58	24.780128	87.065268	Normal
29/5/21	13:18:3	7	0.1	370	30.3	3700	3659	G	4.8	24.780707	87.065958	Curve

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

$$Y = 0 * X^2 + 0.969 * X$$

$$X = 2286$$

$$Y = 2289$$

PA
26.06.21
EE

Pitam
26.06.21
K.E

29/5/21
13:18:3

29/5/21	13:18:3	7	0.1	300	30.3	3000	2981	G	4	24.781132	87.066835	Curve
29/5/21	13:18:3	7	0.1	380	30.3	3800	3756	G	4.92	24.781743	87.067322	Normal
29/5/21	13:18:38	7	0.1	330	30.3	3300	3272	G	4.35	24.78264	87.067558	Normal
29/5/21	13:18:38	7	0.1	280	30.3	2800	2787	G	3.77	24.783343	87.067928	Curve
29/5/21	13:19:0	7	0.1	300	30.3	3000	2981	G	4	24.784058	87.06842	Curve
29/5/21	13:19:14	7	0.1	330	20.2	3300	3272	G	4.35	24.784827	87.068753	Bridge
29/5/21	13:19:14	7	0.1	360	30.3	3600	3562	G	4.69	24.78508	87.069697	Bridge
29/5/21	13:19:14	7	0.1	310	40.4	3100	3078	G	4.12	24.78533	87.070555	Normal
29/5/21	13:19:49	7	0.1	330	20.2	3300	3272	G	4.35	24.785465	87.071532	Normal
29/5/21	13:20:0	7	0.1	300	30.3	3000	2981	G	4	24.78489	87.072288	Normal
29/5/21	13:20:0	7	0.1	300	40.4	3000	2981	G	4	24.78425	87.073047	Normal
29/5/21	13:20:0	7	0.1	230	40.4	2300	2303	G	3.18	24.7836	87.073652	Curve
29/5/21	13:20:24	7	0.1	250	30.3	2500	2497	G	3.42	24.783177	87.07446	Normal
29/5/21	13:20:24	7	0.1	210	30.3	2100	2109	G	2.94	24.782962	87.075337	Curve
29/5/21	13:20:24	7	0.1	400	30.3	4000	3950	G	5.14	24.782212	87.075992	Curve
29/5/21	13:21:0	7	0.1	310	20.2	3100	3078	G	4.12	24.782682	87.076615	Curve
29/5/21	13:21:0	7	0.1	280	10.1	2800	2787	G	3.77	24.783562	87.076852	Normal
29/5/21	13:21:35	7	0.1	370	10.1	3700	3659	G	4.8	24.783755	87.077608	Normal
29/5/21	13:22:0	7	0.1	330	20.2	3300	3272	G	4.35	24.784538	87.077912	Normal
29/5/21	13:22:10	7	0.035	80	20.2	2286	2289	G	3.16	24.785363	87.078097	Curve
Total UV								Total IRI	159.28			
Average UV								Average IRI	4.084103			

06.06.21
E.C.

06.06.21
A.E.

06.06.21
A.E.