

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर

पत्रांक 1306/अनु दिनांक 22/06/2021

प्रेषक कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में
अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय— शीर्ष New Maintenance Policy-2018 मद में आवंटन उपलब्ध कराने के संबंध में।
महाशय,

उपर्युक्त विषयक शीर्ष New Maintenance Policy-2018 मद अन्तर्गत व्यय हेतु
विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की
कृपा की जाये।

अनु—यथोक्त।

विश्वासभाजन



कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर

Rev.
22/6/21

FROM GFR 19-A

(See Government of India's Division (I) below Rule- 150)

Form of Utilization Certificate upto 21.06.2021

PIU- E.E., R.W.D. Works Division, Samastipur

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto	157286388.00	Certified that out of Rs.157286388.00 received upto 21.06.2021 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.147318648.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 9967740.00 remaining unutilized at the end of period under report.
			15,72,86,388.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive/Superintending engineer.
- Periodical inspection has been conducted by Executive/Superintending engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- All other codal formalities have been observed.

3 Physical Progress achieved:-

- Construction of Road work.
- Construction of CD works.

22/6/21
Sr. Divisional Account Officer
R.W.D (W) Division Samastipur

22/6/21
Executive Engineer
Works Division Samastipur
Rural Works Department

Requisition Format for scheme Head : MIR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Samastipur																		
Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date	Administrative		Agreement Amount		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lakh)	Up to date expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM SASA M 19 0011	NEA22000667	Khoti se Keshopatti	2173 & 06.07.2019	4.90	157.17	87.70249	43.35044	01(MIBD) 2020-21 06.05.2020	05.02.2021	Complete	3339	25	5.20	0	0	87.702	341 completed
Total						157.17000	87.70249	43.35044							0.000	0.000	87.702	


- 1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MIS

Sr Divisional Account Officer
RWD (W) Division Samastipur

Executive Engineer
RWD (W) Div. Samastipur

Recd
22/6/21

File : D:\bump\Integrator\IRWD div Samastipur\KHAIRI SE KESHOPATTI.xlsx. Section No. : 90. Egn : test
 Name of Customer : M/S Ramsagar ray and co. Name of Work/ Road : Khor se keshopatti. Lab Job number :



4000 या 4000 से ऊपर की गठन जो आया है वह कई या Culvert के कारण आया है।

[Signature]
 02/06/2021
 JE

[Signature]
 22/06/2021
 AE

[Signature]
 Executive Engineer
 R. W. D. Works Division
 Samastipur
 22/6/21

Date	Time	Section	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km/ROAD	CATEGORY	Latitude	Longitud	Event	$v = 0 \cdot X^2 - 1.136 \cdot X + 132.5$
1/6/21	9:18:0	90	0.1	350	10.1	2500	3108 G		25.82912	85.78423	Normal	
1/6/21	9:18:16	90	0.1	390	10.1	1900	2562 G		25.82849	85.78357	Normal	
1/6/21	9:19:25	90	0.1	340	0	3400	3994 G		25.82777	85.78306	Normal	(R) RURAL ROAD
1/6/21	9:20:1	90	0.1	340	10.1	3400	4094 A		25.82712	85.78244	Curve	Good
1/6/21	9:20:1	90	0.1	460	10.1	2600	3358 G		25.8263	85.78207	Normal	<4000
1/6/21	9:20:36	90	0.1	360	20.2	3600	3922 G		25.82549	85.7818	Normal	4001-5000
1/6/21	9:21:0	90	0.1	320	20.2	3500	4067 A		25.82474	85.78145	Curve	>5001
1/6/21	9:21:11	90	0.1	210	20.2	2100	2518 G		25.82412	85.78081	Normal	
1/6/21	9:21:11	90	0.1	190	20.2	1900	2290 G		25.82327	85.7803	Normal	
1/6/21	9:21:46	90	0.1	190	20.2	1900	2290 G		25.82264	85.77975	Normal	
1/6/21	9:22:0	90	0.1	250	30.3	2500	2972 G		25.82201	85.77899	Normal	
1/6/21	9:22:0	90	0.1	450	20.2	3500	4044 A		25.8213	85.77842	Curve	
1/6/21	9:22:22	90	0.1	350	30.3	3100	3708 G		25.82069	85.77781	Normal	
1/6/21	9:22:22	90	0.1	220	30.3	2200	2631 G		25.82007	85.77712	Normal	
1/6/21	9:22:22	90	0.1	180	30.3	1800	2177 G		25.8193	85.77658	Normal	
1/6/21	9:23:0	90	0.1	170	30.3	1700	2063 G		25.81845	85.77628	Normal	
1/6/21	9:23:0	90	0.1	250	20.2	2500	2972 G		25.81788	85.77559	Normal	
1/6/21	9:23:32	90	0.1	330	20.2	3300	3881 G		25.81745	85.77476	Normal	
1/6/21	9:23:32	90	0.1	300	20.2	3000	3540 G		25.8167	85.77434	Normal	
1/6/21	9:24:8	90	0.1	380	20.2	3800	4449 A		25.81591	85.77386	Curve	
1/6/21	9:24:8	90	0.1	340	10.1	3400	3994 G		25.81519	85.77343	Normal	
1/6/21	9:24:8	90	0.1	200	30.3	2000	2404 G		25.81444	85.77303	Normal	
1/6/21	9:24:43	90	0.1	160	30.3	1600	1950 G		25.81363	85.77256	Normal	
1/6/21	9:25:0	90	0.1	270	20.2	2700	3199 G		25.81286	85.77214	Normal	
1/6/21	9:25:0	90	0.1	190	20.2	1900	2290 G		25.81204	85.772	Normal	
1/6/21	9:25:18	90	0.1	340	10.1	3400	3994 G		25.8112	85.77126	Normal	
1/6/21	9:26:0	90	0.1	310	10.1	3100	3654 G		25.81041	85.77088	Normal	
1/6/21	9:26:0	90	0.1	270	10.1	2700	3199 G		25.80965	85.77064	Normal	
1/6/21	9:26:0	90	0.1	240	20.2	2400	2858 G		25.8088	85.77037	Normal	
1/6/21	9:26:29	90	0.1	280	20.2	2800	3313 G		25.80789	85.77008	Normal	
1/6/21	9:27:4	90	0.1	250	20.2	2500	2972 G		25.80709	85.76987	Normal	
1/6/21	9:27:4	90	0.1	350	10.1	2500	3108 G		25.80626	85.76966	Normal	
1/6/21	9:28:0	90	0.1	410	10.1	2100	2790 G		25.80531	85.76951	Normal	
1/6/21	9:28:15	90	0.1	360	10.1	2600	3222 G		25.8045	85.76941	Normal	
1/6/21	9:28:50	90	0.1	350	10.1	3500	4108 A		25.80364	85.76906	Speed Breaker	
1/6/21	9:29:25	90	0.1	430	10.1	3200	3817 G		25.80304	85.76833	Normal	

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitud	Event	$y = 0 \cdot x^4 + 2 \cdot 1136 \cdot x + 1325$
1/6/21	9:29:25	90	0.1	430	10.1	3500	4017 A		25.80258	85.76758	Curve	
1/6/21	9:30:0	90	0.1	430	10.1	3100	3717 G		25.80191	85.7668	Normal	
1/6/21	9:30:36	90	0.1	420	10.1	3200	3803 G		25.80188	85.76593	Normal	
1/6/21	9:31:0	90	0.1	350	10.1	3500	4018 A		25.80192	85.76498	Curve	
1/6/21	9:31:11	90	0.1	370	10.1	3100	3835 G		25.80148	85.76407	Normal	
1/6/21	9:42:0	90	0.1	380	0	3500	4049 A		25.81982	85.78	Curve	
1/6/21	9:42:21	90	0.1	340	10.1	3400	4094 A		25.81944	85.78111	Curve	
1/6/21	9:42:21	90	0.1	270	20.2	2700	3199 G		25.81951	85.78209	Normal	
1/6/21	9:43:0	90	0.1	290	20.2	2900	3426 G		25.81934	85.78295	Normal	
1/6/21	9:43:0	90	0.1	440	20.2	2400	3130 G		25.81892	85.78377	Normal	
1/6/21	9:43:32	90	0.1	270	20.2	2700	3199 G		25.81852	85.78471	Normal	
1/6/21	9:43:32	90	0.1	390	20.2	3100	3862 A		25.81831	85.78561	Normal	
1/6/21	9:44:0	90	0.1	320	20.2	3200	3767 G		25.81809	85.78662	Normal	

4000 या 4000 से डर आया है जो आया है गेटे काले गा काले के आगे आया है।

22/06/2021

22/06/2021

K. W. D. Works Division
Samastipur