

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल समस्तीपुर ।

पत्रांक: 5623/90

दिनांक:- 4-03-2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल समस्तीपुर ।

सेवा मे,

अपर मुख्य कार्यपालक पदाधिकारी - सह - सचिव
ग्रामीण कार्य विभाग,
बिहार, पटना ।

विषय:- नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु आवंटन की मांग ।

महाशय,

उपर्युक्त विषयक नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु विहित प्रपत्र मे अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने का कृपा की जाए, ताकि किये गये कार्यो का भुगतान किया जा सके ।

अनु० :- यथोक्त ।

विश्वासभाजन

कार्यपालक अभियंता

ग्रामीण कार्य विभाग,

कार्य प्रमंडल समस्तीपुर ।

4-3-2021

FROM GFR 19-A
(See Government of India's Division (I) below Rule- 150)

Form of Utilization Certificate UpTo 02.03.2021
PIU- E.E., R.W.D. Works Division, Samastipur

S.N.	Name of Scheme	Sanction No.& Date with Amount	Amount Received	Particulars
1	Construction of Rural Road under 3054 (M/R)	Secretary cum Empowered Officer BRRDA Bihar Patna vide up to	95399814.00	Certified that out of Rs.95399814.00 received Upto 02.03.2021 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.68776488.00 has been utilized for the purpose of MR-3054 Maintenance Repairs Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 26623326.00 remaining unutilized at the end of period under report.
			95399814.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.

[Signature]
 4.3.21
SR. Divisional Account Officer
R.W.D (W) Division Samastipur

[Signature]
 4.3.21
Executive Engineer
Works Division Samastipur
Rural Works Dipartment

[Signature]
 4.3.2021

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date	Administrative		Agreement		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in MM)	Value of Bitumen Content in Percent	Previous Total Allocated Amount (in Lakh)	Upto date Expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/SA/S AM/19/0 014	32010102096	X-ROAD 1039 - JAGDISHPUR	2173 & 06/07/2019	1.4	50.46	29.699	13.267	11(MBD)19 -20/ 26.2.2020	7-Oct-20	On-Going	3940.2	25	5.1	28.69900	28.69900	0.61474	Work Complete
2	RM/SA/SA M/19/0007	32010102061	SH - CHANDHARPUR	2173/ 07.06.19	1.64	17.18	34.207	15.20719	12(MBD)201 -9- 20/26.02.20	07.10.202	OnGoing	3016.68	25	5.1	17.1035	0	14.60097	BT Complete
3	RM/SA/SA M/19/0012	32010102034	CHATURBAHUARA - KHATUAHA	2173/ 07.06.19	0.73	17.92	15.941	6.37047	14(MBD)201 -9- 20/02.03.20	07.10.2020	Ongoing	3135.57	25	5.1	4.462	0	11.479	BT Complete
4	RM/SA/SA M/19/0007	32010102030	Tara Chowk - Bhado Chowk	2173/ 07.06.19	7.0	150.57	133.583	66.90639	12(MBD)201 -9- 20/26.02.20	7-Oct-20	Ongoing	3326.85	25	5.1	60.11235	0	73.3252	BT Complete
5	RM/SA/ SAM/19 /0006	NEA220005 69	MAIN ROAD TO - BHINDI	2173 & 06/07/2019	4.0	89.27	78.287	34.5465	14(MBD)20- 21/02.06.202	01.03.2021	On-Going	3593.15	25	5.2	0	0	78.19987	Work Complete
Total						325.40000	291.71700	136.29755									178.21978	


1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
2 Upto-date Physical Progress has been uploaded in MIS

Sr. Divisional Account Officer
R.W.D (W) Division Samastipur

Executive Engineer
RWD (W) Div. Samastipur

4.3.2021

File D:\bump1 integrated\IWD div Somnathpur\MAIN ROAD SE BHIPADI.xlsx Section No. 09, Egn test
 Name of Customer Anjan Kumar, Name of Work/ Road Main Road to Bhundi, Lab Job number :



See to error & breakers & reading extend above 4cc.

Due
8/2/21

Chinthe
10/2/21

P. S. S.


T. S.

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 1.136 * X + 132.5
28/2/21	10:10:4	89	0.1	500	0	2000	2812	G	25.97473	85.84409	Normal	X = 4500
28/2/21	10:10:4	89	0.1	440	10.1	2400	3130	G	25.97385	85.844258	Normal	Y = 5244
28/2/21	10:10:40	89	0.1	390	20.2	1900	2562	G	25.97294	85.844427	Normal	
28/2/21	10:11:0	89	0.1	410	20.2	3100	3790	G	25.97205	85.844562	Normal	
28/2/21	10:11:15	89	0.1	400	20.2	3400	4176	A	25.97122	85.84478	Curve	(R) RURAL ROAD
28/2/21	10:11:15	89	0.1	340	20.2	3400	3994	G	25.97039	85.845185	Curve	Good
28/2/21	10:11:15	89	0.1	370	20.2	2700	3335	G	25.96975	85.845892	Normal	<4000
28/2/21	10:12:0	89	0.1	350	20.2	2500	3108	G	25.96897	85.846195	Normal	4001-5000
28/2/21	10:12:0	89	0.1	370	20.2	3700	4335	A	25.96805	85.846178	Culvert	>5001
28/2/21	10:12:0	89	0.1	360	20.2	2600	3222	G	25.96717	85.846195	Normal	
28/2/21	10:12:26	89	0.1	420	20.2	3500	4103	A	25.96627	85.846077	Curve	
28/2/21	10:13:1	89	0.1	400	20.2	3000	3676	G	25.96541	85.846077	Normal	
28/2/21	10:13:1	89	0.1	360	10.1	2600	3222	G	25.96454	85.845925	Normal	
28/2/21	10:13:36	89	0.1	390	10.1	2900	3562	G	25.96471	85.844948	Normal	
28/2/21	10:14:0	89	0.1	370	20.2	3700	4335	A	25.96494	85.843955	Curve	
28/2/21	10:14:11	89	0.1	330	20.2	3300	3881	G	25.96443	85.843282	Curve	
28/2/21	10:14:11	89	0.1	310	20.2	3100	3654	G	25.96435	85.842272	Normal	
28/2/21	10:15:0	89	0.1	370	20.2	2700	3335	G	25.96423	85.841278	Normal	
28/2/21	10:15:0	89	0.1	450	20.2	3500	4244	A	25.96429	85.840252	Culvert	
28/2/21	10:15:22	89	0.1	420	20.2	3200	3903	G	25.96446	85.839308	Curve	
28/2/21	10:15:22	89	0.1	290	20.2	2900	3426	G	25.96492	85.83848	Curve	
28/2/21	10:16:0	89	0.1	420	20.2	3200	3903	G	25.96523	85.837542	Normal	
28/2/21	10:16:0	89	0.1	320	20.2	3200	3767	G	25.96551	85.836598	Normal	
28/2/21	10:16:33	89	0.1	400	20.2	3000	3676	G	25.96585	85.835673	Curve	
28/2/21	10:16:33	89	0.1	380	20.2	3100	3849	G	25.96602	85.834662	Normal	
28/2/21	10:17:8	89	0.1	410	10.1	2100	2790	G	25.9661	85.833703	Normal	
28/2/21	10:17:8	89	0.1	380	20.2	1800	2449	G	25.96623	85.83271	Normal	
28/2/21	10:17:8	89	0.1	310	10.0	3100	3654	G	25.96536	85.83148	Normal	
28/2/21	10:19:0	89	0.1	390	10.1	2900	3562	G	25.96533	85.830505	Normal	
28/2/21	10:19:29	89	0.1	330	20.2	3300	3881	G	25.96534	85.829477	Curve	
28/2/21	10:19:29	89	0.1	440	20.2	2400	3130	G	25.96531	85.828535	Curve	
28/2/21	10:20:4	89	0.1	380	20.2	2800	3449	G	25.96535	85.827575	Normal	

9/1

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event			
28/2/21	10:20:4	89	0.1	320	20.2	3200	3767	G	25.96542	85.826598	Normal			
28/2/21	10:20:40	89	0.1	340	20.2	3400	3994	G	25.96531	85.825622	Normal			
28/2/21	10:21:0	89	0.1	280	20.2	2800	3313	G	25.96483	85.824797	Normal			
28/2/21	10:21:15	89	0.1	320	20.2	3200	3767	G	25.96465	85.823838	Normal			
28/2/21	10:21:15	89	0.1	420	10.1	3200	3903	G	25.96419	85.822928	Normal			
28/2/21	10:22:0	89	0.1	330	20.2	3300	3881	G	25.96365	85.822188	Normal			


 8/2/21
 J. S.


 10/2/21
 R. S.


 2/2
 A. S.