

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बांका-1

पत्रांक 493

बांका/ दिनांक ११/०३/२०२१

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल बांका-1

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण पटना।

विषय:- गैर योजना मद शीर्ष 3054 एम0आर0 योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर0 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया **15.968/-**लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-

1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन

(Signature)
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बांका-1।
(Signature)
११/०३/२०२१

प्रतिलिपि: मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचना एवं आवश्यक कार्रवाई हेतु रजिस्ट्रार।

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बांका-1

पत्रांक

बांका /

दिनांक

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल बांका-1

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण पटना।

विषय:- गैर योजना मद शीर्ष 3054 एम0आर0 योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर0 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया **15.968/-**लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-

1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन

SD/-

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बांका-1 ।

ज्ञापांक- 493 / बांका,

दिनांक- 9/3/2024

प्रतिलिपि- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

Subin
9/3/24
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बांका-1
Raoi
9/03/2024

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Banka-1

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA) Length (in Km)	Administrative Approval (AA) Amount (in Lac)	Agreement Amount (in Lac)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
1	MR-N/19-20 Banka-1/06	Banka santhal Pargana (Domuhan) road to Sadpur	27351021716	3073 17.07.2019	0.651	35.48323	Initial Rectification with Surface Renewal 31.9349	5 years Routine Maintenance 6.153	15.09.2020	15.09.2020	2372.14	25	5%	15.967	0	15.968	Completed
2		Khesar Tarapur Jilani Road (Part)	27351021715	3073 17.07.2019	3.400	145.48432	130.9359	30.553	15.09.2020	15.09.2020		25	5%	130.396	104.104	0.000	Completed
3		Mirzapur to Kiranpur	NEA22000412	3073 17.07.2019	5.775	250.83792	225.7541	51.510	15.09.2020	15.09.2020		25	5%	225.754	209.6109	0.000	Completed

Executive Engineer
RWD Works Division
Banka-1
9/10/20

Lab Job number :25

Date 03.02.2021

Name of Customer :		Arvind Singh	
Name of Work/ Road :		Banka Santhal Pargana Domuhan Road to Sadpur under MR 3054 New Maint. Policy 2018	
Sr.no	Location of test(in km)	Corrected U.I value(mm/km)	Road catagory
1	0.1	2497	G
2	0.2	2497	G
3	0.3	2012	G
4	0.4	3466	G
5	0.5	2206	G
6	0.6	2012	G
7	0.7	1915	G
Avg IRI Value per Km		2372.14	G

Junior Engineer

Ar. Singh
03.02.2021
Assistant Engineer
R.W.D Works Division
Banka-1

S. K. Singh
03.02.21
Executive Engineer
R.W.D Works Division
Banka-1

Rawl
8/2/2021

$$Y = 0 * X^2 + 0.969 * X + 74.60$$

$$X = 3300$$

$$Y = 3272$$

(R) RURAL ROAD

Good Average
<4000 4001-5000
Poor >5001

Name of Customer : Arvind Singh									
Name of Work/Road : Banka Santhal Pargana Domubhan Road to Sadpur under MR 3054 New Maint. Policy									
2018									
Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	UIV	CATEGORY ROAD	Lab Job No: 25
3/2/21	12:29:9	25	0.1	320	30.3	3200	3175	G	
3/2/21	12:29:45	25	0.1	240	40.4	2400	2400	G	
3/2/21	12:30:20	25	0.1	320	30.3	3200	3175	G	
3/2/21	12:30:20	25	0.1	240	40.4	2400	2400	G	
3/2/21	12:30:20	25	0.1	230	30.3	2300	2303	G	
3/2/21	12:30:55	25	0.1	270	30.3	2700	2690	G	
3/2/21	12:31:29	25	0.1	330	20.2	3300	3272	G	
								IRI	Latitude
								Longitude	Event
								4.23	24.97896
								3.3	24.97902
								4.23	24.98066
								3.3	24.9812
								3.18	24.9821
								3.65	24.98238
								4.35	24.98261
									86.762473
									86.76148
									86.75968
									86.758972
									86.759107
									86.758198
									86.757272
									Normal
									Speed Breaker
									Normal
									Normal
									Normal
									Normal

Pilam
09.10.2021
Assistant Engineer
Rural Works Department
Works Division, Banka-I

Junior Engineer

Pilam
09.10.2021
Executive Engineer
Rural Works Department
Works Division, Banka-I
Pav
8/10/2021

Name of Customer :	Arvind Singh
Name of Work/ Road :	Banka Santhal Pargana Domu
Lab Job number :	25
Date :	2/3/2021
Section No. :	25

Test Date :	2/3/2021	Road Name :	Banka Santhal Pargana Domu
Machine No :	407	Road Type :	(R) RURAL ROAD
Start S No :		Side :	
Start E No :		Interval	
Weather :		UIV Range :	1303 To 4000 mm/km
Start Location :	24.978963,86.7	Dist Range :	0 To 0.8
End Location :	24.982608,86.7	Equation :	$Y = 0 * X^2 + 0.969 * X + 74.60$

Print


Generate Report and Graph

Redraw Graph

Map View

File : D:\Arvind Singh\03021607.xlsx Section No. :25, Eqn : $Y = 0 * X^2 + 0.969 * X + 74.60$

Name of Customer :Arvind Singh, Name of Work/ Road :Banka Santhal Pargana Domuhan Road to Sadpur, Lab




Arvind
02.02.2021
K.E

Arvind
02.02.2021
K.E

12.03.2021
K.E

12.03.2021
K.E

Devil
Brynam



+ I