

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com

Mob:- 8986915310

पत्रांक.....548⁸¹⁷ सासाराम/दिनांक.....18/03/2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विश्वासभाजन

13/3/21
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

13/03/21

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)
Form of Utilization Certificate up to March 2021

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA Letter No.82, dt. 13.11.2020 Letter No.84, dt. 26.11.2020 Letter No.86, dt. 11.12.2020 Letter No.05, dt. 12.01.2021 Letter No.17, dt. 26.02.2021	24012800.00 19457900.00 65864300.00 142175100.00 17,09,10,570.00	Certified that out of Rs. 42,24,20,670.00 lakh of grants-in-aid sanctioned during the years 2020-21 Infavor of EE,RWD works division Sasaram-1 a sum of Rs 25,39,65,337.00 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 16,84,55,333.00 lakh remaining unutilized at the end of the period under report.
	Total:		25,15,10,100.00	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
 - ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
 - iii. Construction materials have been tested.
 - iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
 - v. All other caudal formalities have been observed.
3. **Physical Progress achieved:-**
- i. Construction of Road Works.
 - ii. Construction of CD works.


13/3/21
Divisional Accounts Officer
R.W.D, works Division
R.W.Sasaram-1, Sasaram-1


13/3/21
Executive Engineer
R.W.D, works Division
Sasaram-1

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Requisition Format for Scheme Head-MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Sl no.	Package No MR-N/ 2019-20	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
		Rohtas jila antargat Sasaram Prkhand ke bhadokhara panchayat ke nektahil chandansahid hote hua sasaram - tilauthu path tak																
1	3		10301003014	2159 06.07.2019	1.440	49.80000	31.109	13.60334	68/MBD/ 2020-21 24.02.20	23.11.2020	-	1415	25.00	5.02	15.55450	15.55450	15.55450	
Total					1.440	49.80000	31.109	13.60334							15.55450	15.55450	15.55450	

Handwritten signature
Divisional Accounts Officer
Rural Works Department
Works Division, Sasaram-1

Handwritten signature
Executive Engineer
Rural Works Department
Works Division, Sasaram-1

13/09/20

nektahil chandansahid hote hua sasaram - tilauthu path tak

[illegible] $X = 1000$
$$Y = 1415$$

(R) RURAL ROAD

Good	Average	Poor
<4000	4001-5000	>5001

Mr.
J. H. Johnson
The J. H. Johnson Co.
P.O. Box 100

Name of Customer : Narendra Kumar
Name of Work/ Road : Rohas jila antargat Sasaram Pr
Lab Job number : 44
Date : 11/2/2021
Section No. : 44


Test Date : 11/2/2021
Machine No. : 391
Start S No. : 7763
Start E No. : 7778
Weather : Normal
Start Location : 24.94396, 84.32
End Location : 24.93215, 84.32
Road Name : Rohas jila antargat Sasaram F
Road Type : (R) RURAL ROAD
Side : Sasaram
Interval :
U/V Range : 415 To 4000 mm/km
Dist Range : 0 To 0.476 0.028 ~ 1000 m
Equation : $Y = 0 * X^2 + 1.000 * X + 415.2$

Print

Generate Report and Graph

Redraw Graph

Map View



No
 24.94396, 84.32
 24.93215, 84.32
 24.94396, 84.32