

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल समस्तीपुर ।

+पत्रांक: 626 अगु०

दिनांक: 10.03.2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल समस्तीपुर ।

सेवा मे,

अपर मुख्य कार्यपालक पदाधिकारी - सह - सचिव
ग्रामीण कार्य विभाग,
बिहार, पटना ।

विषय:- नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु आवंटन की मांग ।

महाशय,

उपर्युक्त विषयक नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु विहित प्रपत्र मे अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने का कृपा की जाए, ताकि किये गये कार्यों का भुगतान किया जा सके ।

अनु० :- यथोक्त ।

विश्वासभूजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,

कार्य प्रमंडल समस्तीपुर ।

9.3.2021

FROM GFR 19-A

(See Government of India's Division (I) below Rule- 150)

Form of Utilization Certificate Up To 08.03.2021

PIU- E.E., R.W.D. Works Division, Samastipur

S.N.	Name of Scheme	Sanction No.& Date with Amount	Amount Received	Particulars
1	Construction of Rural Road under 3054 (M/R)	Secretary cum Empowered Officer BRRDA Bihar Patna vide up to	95399814.00	Certified that out of Rs.95399814.00 received Upto 08.03.2021 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.86376580.00 has been utilized for the purpose of MR-3054 Maintenance Repairs Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 9023234.00 remaining unutilized at the end of period under report.
			95399814.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have


Kind of Checks exercised:-


- i Works have been supervised by Executive/Supervising engineer.
- ii Periodical inspection has been conducted by Executive/Supervising engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.


SR. Divisional Account Officer
R.W.D (W) Division Samastipur



Executive Engineer
Works Division Samastipur
Rural Works Department


Viver
9.3.2021

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD Works Division : Samastipur																			
Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date	Administrative			Agreement		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percent	Previous Total Allotted Amount (In Lakh)	Upto date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (Km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	RM/SA/SA M/19/0011	32010102059	SH - BEJADIH		1.8	38.67	34.199	16.11842		5-Feb-21	OnGoing	3714	25	5.1	0	0	34.19900	BT Completed	
2	RM/SA/SA M/19/0011	32010102104	X-ROAD LOSS - BIKRAMPUR BANDE	2173 & 06.09.2019	1.75	39.3	32.441	16.61574		5-Feb-21	OnGoing	3564	25	5.2	0	0	32.44100	BT Completed	
3	RM/SA/SA M/19/0011	NEA22000652	MDR T01 - HAKIMABAD		2	45.18	37.091	19.14196	01(MBD)2020-21, 06.05.2020	5-Feb-21	OnGoing	3609.28	25	5.15	0	0	37.09100	BT Completed	
4	RM/SA/SA M/19/0011	NEA22000722	CROSS ROAD - BISHANPUR		1.17	28.57	23.711	10.73239		5-Feb-21	OnGoing	3848.36	25	5.02	0	0	23.71100	BT Completed	
5	RM/SA/SA M/19/0011	NEA22000726	SH T05 - CHAKHAJI		1.7	38.74	32.194	15.91806		5-Feb-21	OnGoing	3661	25	5.02	0	0	32.19400	BT Completed	
Total						190.46000	159.63600	78.52657							0.00000	0.00000	159.63600		

File : C:\My\master\Bump March\04.03.21\13021438.Xls, Section No.: 70, Eqn : $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$
 Name of Customer : M/S Ram Sagar Rai Co, Name of Work/ Road : SH T05 to Chakhaji, Lab Job number :



Speed Breaker, curve in curve & 11201 Reading
 4,000-7 211 (3.21) (3.21) (3.21) (3.21) (3.21) (3.21) (3.21) (3.21)

[Signature]
 13/02/2021
 JE

[Signature]
 13/02/2021
 JE

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event			
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			$Y = 0 * X^2 + 1.136 * X + 132.5$			
13/2/21	13:14:1	70	0.1	380	0	3800	4449	A	25.905478	85.704713	Speed Breaker	X = 3600		
13/2/21	13:14:36	70	0.1	310	20.2	3100	3654	G	25.90636	85.704797	Normal	Y = 4222		
13/2/21	13:15:0	70	0.1	290	20.2	2900	3426	G	25.907245	85.704882	Normal			
13/2/21	13:15:13	70	0.1	270	20.2	2700	3199	G	25.908115	85.704998	Normal			
13/2/21	13:15:13	70	0.1	310	20.2	3100	3654	G	25.90901	85.70507	Normal			
13/2/21	13:15:13	70	0.1	280	20.2	2800	3313	G	25.90993	85.705302	Normal	(R) RURAL ROAD		
13/2/21	13:15:48	70	0.1	280	20.2	2800	3313	G	25.91079	85.70542	Normal	Good	Average	Poor
13/2/21	13:16:0	70	0.1	350	10.1	3200	3654	G	25.911698	85.705487	Normal	<4000	4001-5000	>5001
13/2/21	13:16:24	70	0.1	400	10.1	2900	3313	G	25.912613	85.705622	Normal			
13/2/21	13:16:24	70	0.1	290	20.2	2800	3426	G	25.913485	85.705842	Normal			
13/2/21	13:17:0	70	0.1	400	10.1	4000	4676	A	25.914435	85.705942	Speed Breaker			
13/2/21	13:17:34	70	0.1	290	10.1	2900	3426	G	25.915275	85.70606	Normal			
13/2/21	13:17:34	70	0.1	370	10.1	3700	4335	A	25.91626	85.70606	Curve			
13/2/21	13:18:9	70	0.1	470	20.2	2900	3200	G	25.917007	85.706532	Normal			
13/2/21	13:18:9	70	0.1	360	20.2	3500	3900	G	25.917857	85.70673	Normal			
13/2/21	13:18:9	70	0.1	230	30.3	2300	2745	G	25.918723	85.706985	Normal			
13/2/21	13:18:45	70	0.1	390	10.1	3900	4562	A	25.919613	85.70734	Curve			

Speed Breaker, Curve RT subut 3 9/25
 Road 4000 mm 3426 3100 3654

SR
 13/09/2021
 AS

10/3/21