

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, हरनौत (नालन्दा)

पत्रांक 560/अनु०

दिनांक 17/03/2024

प्रेषक:- कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, हरनौत।

सेवामें,
नोडल पदाधिकारी MR3054
ग्रामीण कार्य विभाग
बिहार, पटना।

विषय:- शीर्ष-3054 अन्तर्गत बिहार ग्रामीण पथ अनुस्क्षण नीति-2018 के तहत अधियायना समर्पित करने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष-शीर्ष-3054 अन्तर्गत बिहार ग्रामीण पथ अनुस्क्षण नीति-2018 योजनान्तर्गत कराये गये निर्माण कार्य में भुगतान हेतु राशि उपलब्ध कराने की कृपा की जाए। इस पत्र के साथ विहित प्रपत्र में अधियायित राशि समर्पित की जा रही है।

अनु०- यथोक्त।

विष्वासमाजन

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, हरनौत

15/03/2024

FORM GFR 19-A

(See Government of India's Decision (1) below Rule-150)

Form of Utilization Certificate of MR-New Maintenance Policy 2018

As on Dated - 14-03-2021

PIU-	Harnaut		F.Yr.-- 2020-21		Rs. In Lakhs
Name of Scheme	Sl. No.	Sanction No. & Date		Amount Received (in Rs. Lakhs)	Particulars
Construction of Rural Roads under New Maintenance Policy 2018	1	Op. Balance -	01.04.2020	₹ -	Certified that out of ₹ 225.54105 Lakhs
		Ltr. No.- 40	02.06.2020	₹ 24.67803	received & balance of grants-in-aid sanctioned
	2	Ltr. No.- 64	03.09.2020	₹ 56.32469	during the Financial Yr. 2020-21 in favour of
		Ltr. No.- 69	24.09.2020	₹ 88.39000	Excutive Engg. R.W.D. Works Division Harnaut,
		Ltr. No.- 05	12.01.2021	₹ 56.14833	Nalanda, a sum of ₹ 131.19761 Lakhs
				scheme as given in the margin for which it was	
				sanctioned and that the balance of ₹ 94.34344	
				Lakhs remaining unutilized at the end of the	
				period under 14th March 2021	
		Total----- Rs.		₹ 225.54105	

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.

3 Physical Progress achieved:

- Construction of Road Works.

Asst. Acct. Manager
RWD (Works Division), Harnaut

Div. Acct. Officer
RWD (Works Division), Harnaut

Executive Engineer
RWD (Works Division), Harnaut

Rural Works Department

Requisition Format for Scheme Head-MR(3054) under Bihar Rural Road Maintenance Policy-2018. (Initial Rectification and Surface Renewal)

Name of Division :- **Harnaut**

Scheme Head:- **Scheme Head-MR(3054) under Bihar Rural Road Maintenance Policy-2018**

Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Sanction			Agreement amount (In Lakhs)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRL (in mm/Km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Allotment Received (In Lakhs)	Up to Date Expenditure as per MIS (In Lakhs)	Requisition Against Work done (In Lakh)	Remarks
				Tr No & Date	Length (In Km)	Amounts (In Lakhs)	Initial Rectification with Surface Renewal	Maintenance										
1	RA/NA/ H&R/19/0001	Bodhinegar Saraulpur RWD Path to Dhimay Vill	1271010314	S39 08/02/2019	1.000	32.17000	21.84500	4.41155	MRD-22/2019-20	27.03.2020		2150	25.00	5.00	-	-	21.800000	
2	RA/NA/ H&R/19/0001	Cheran to Vill Dhimay	10290704001	S39 08/02/2019	2.400	73.88000	49.49700	10.17815	MRD-22/2019-20	27.03.2020		2333	25.00	5.00	-	-	49.40000	
Total																	71.200000	

18/03/2021
Asst. Asst. Manager
RWD (Works Division), Harnaut

18/03/2021
Dy. Asst. Engineer
RWD (Works Division), Harnaut

18/03/2021
Executive Engineer
RWD (Works Division), Harnaut

Name of Road:- Bodhnagar Sandalpur RWD Path To Dhimoy Village

Name of Contractor:- Ram Prasad Singh

Date	Time	Section	Length in km	Bumps in mm	Speed Rate	OR mm/km	UIV	CATEGORY	IRI	Latitude	Longitude	Event
		No.						ROAD				
14/3/21	15:59:15	61	0.1	250	0	2500	2622	G	3.57	25.3232	85.61655	Normal
14/3/21	16:0:0	61	0.1	270	30.3	2700	2802	G	3.79	25.3241	85.61653	Normal
14/3/21	16:0:0	61	0.1	230	30.3	2300	2443	G	3.35	25.325	85.61662	Curve
14/3/21	16:0:0	61	0.1	180	20.2	1800	1994	G	2.79	25.3259	85.61694	Curve
14/3/21	16:0:27	61	0.1	190	20.2	1900	2084	G	2.91	25.326	85.61769	Normal
14/3/21	16:0:27	61	0.1	140	30.3	1400	1635	G	2.34	25.3268	85.61816	Normal
14/3/21	16:1:0	61	0.1	280	40.4	2800	2892	G	3.89	25.3275	85.6188	Normal
14/3/21	16:1:2	61	0.1	150	40.4	1500	1724	G	2.45	25.328	85.61963	Normal
14/3/21	16:1:2	61	0.1	220	40.4	2200	2353	G	3.24	25.3288	85.6203	Normal
14/3/21	16:1:2	61	0.1	240	20.2	2400	2533	G	3.46	25.3297	85.62051	Curve
Total=			1.00	2150	272.7	21500	23082		31.79			


0088
15/03/2021
JF

NK
15-3-2021
AR

15-3-2021

$Y = 0 * X^2 + 0.898 * X + 377.8$			
X = 2900			
Y = 2982			
(R) RURAL ROAD			
Good	Average	Poor	
<4000	4001-5000	>5001	

File F:\14031705.Xls. Section No. 61. Egn : $Y = 0 \cdot X^2 + 0.898 \cdot X + 377.8$
 Name of Customer Ram Prasad Singh. Name of Work/ Road Bodhnagar Sandalpur RWD Path to Dimoy Village.



0086
 15/03/2021
 JTC

NCH
 15-3-2021
 HE

17/4/21
 15-03-2021
 BR