

Inspection Report for Flood Damage work

of PTUS :- कार्यपालक अधिकारी, राष्ट्रीय कार्य विभाग, अहमदाबाद।
of Block :- पुरेनी
of Road :- Highway Road Nary Jola purvini bus stand to petrol pump

load

age Location/Chainage :- 9.00 KM (0.050 - 0.500) (0.600 - 1.00) (1.100 - 1.800) (1.900 - 2.00)
(3.00 - 4.00)

age Length :- 2.00 KM

ure of damage :-

ils of Restoration Works :- Brick bats

erial being used in Restoration works:- Brick bats, Bamboo

plements/Tools being used in Restoration works:- Fracture & Brick bats

cedure taken up in Restoration works :-

ored Length :- 4.00 KM

Bridge

age Location/Chainage :- 2.5 KM

age Length :- 0.02 KM

ure of damage :-

ails of Restoration Works :- Brick bats & sand bag, bamboo piling

terial being used in Restoration works:- Brick bats & bamboo, sand bag

ipments/Tools being used in Restoration works :-

cedure taken up in Restoration works :-

ored Length :- 0.02 KM

Sulley
24/11/2020
JE

AE
24/11/2020
AE

EE
24/11/2020
EE

[Signature]
24/11/2020
Signature
(Name of inspector)

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1x	1.00x	0.300	3	0.300m ³
	2.5x	3.00x	0.350	3	4.125m ³
	0.5x	0.50x	0.300	3	0.062m ³
	1.5x	1.00x	0.300	3	0.450m ³
	0.5x	0.500x	0.400	3	0.113m ³
	0.5x	0.500x	0.250	3	0.062m ³
	0.5x	0.500x	0.400	3	0.113m ³
	4x	3.75x	0.300	3	4.500m ³
	1x	0.50x	0.300	3	0.150m ³
	5x	3.75x	0.350	3	6.563m ³
	1x	2.70x	0.400	3	1.215m ³
	0.5x	0.50x	0.300	3	0.075m ³

5x	8.5x	3.75x	0.400	3	63.750m ³
2x	3.75x	0.400	3	3.375m ³	
2x	17x	4.00x	0.300	3	40.800m ³
1.5x	2.80x	0.300	3	1.470m ³	
9x	3.25x	0.350	3	5.180m ³	
1.5x	1.50x	0.500	3	1.125m ³	
0.5x	0.50x	0.600	3	0.100m ³	
1.5x	1.50x	0.350	3	0.787m ³	
4x	4.00x	0.350	3	3.600m ³	
2x	1.50x	0.400	3	1.800m ³	
5x	8x	3.75x	0.300	3	52.500m ³
4x	0.80x	0.600	3	1.200m ³	
0.5x	0.500x	0.350	3	0.086m ³	
5x	3.75x	0.300	3	6.173m ³	

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1x	3.75	0.80	0.100		0.000m ³
1x	2.50	0.80	0.250		0.250m ³
2x	1.50	0.80	0.350		0.025m ³
0.5x	0.500	2.25	0.400		0.063m ³
0.5x	0.50	0.30	0.30		0.075m ³
1.5x	1.50	0.30	0.30		0.900m ³
5x	3.75	0.80	0.250		6.563m ³
1x	1.00	0.70			0.300m ³
1x	1.00	0.750			0.350m ³
1x	3.25	0.450			1.680m ³
1.5x	1.00	0.450			0.450m ³
1x	0.50	0.30			0.450m ³
0.5x	0.50	0.300			0.075m ³
1x	3.50	0.450			1.350m ³
9x	0.300	0.350			0.945m ³
2x	1.00	0.400			0.800m ³
5x	0.500	0.450			1.125m ³
2x	1.00	0.350			0.700m ³
13x 5x	1.00	0.400			26.000m ³
3x	1.50	0.450			2.025m ³
10x 1x	3.75	0.400			15.000m ³
1x	3.00	0.350			1.050m ³
5x	1.500	0.350			2.625m ³
3x	1.00	0.520			30.000m ³
2x	3.75	0.200			2.250m ³
1x	3.00	0.400			1.200m ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	5x	1.00	X	0.250	=> 1.045 m ²
	52x	3.75	X	0.250	=> 12.688 m ²
	3x 12x	3.00	X	0.450	=> 42.600 m ²
	1x	3.75	X	0.350	=> 1.313 m ²
	7x	1.00	X	0.350	=> 2.450 m ²
	1x	1.00	X	0.400	=> 0.400 m ²
	8x	0.700	X	0.450	=> 2.520 m ²
	2x 12x	0.520	X	0.300	=> 5.400 m ²
	15x	2.20	X	0.270	=> 11.550 m ²
	8x	1.25	X	0.450	=> 4.500 m ²
	20x	1.50	X	0.300	=> 9.000 m ²
	4x 8x	4.00	X	0.500	=> 64.000 m ²

	12x	3.75	X	0.700	=> 13.500 m ²
	16x	2.00	X	0.400	=> 12.800 m ²
	9x	1.25	X	0.450	=> 5.663 m ²
	11x	1.00	X	0.300	=> 3.850 m ²
	2x 12x	3.00	X	0.400	=> 43.200 m ²
	60x	4.00	X	0.350	=> 84.000 m ²
	10x	0.700	X	0.450	=> 3.150 m ²
	25x	3.75	X	0.200	=> 28.125 m ²
	2x	1.00	X	0.400	=> 0.800 m ²
	5x	0.500	X	0.350	=> 0.875 m ²
	12x	1.50	X	0.450	=> 8.100 m ²
	8x	3.75	X	0.400	=> 12.00 m ²
	25x	3.75	X	0.450	=> 42.188 m ²
	5x	2.50	X	0.350	=> 4.375 m ²

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	50x	0.50	0.350	⇒	8.750m ³
	1x	3.00	0.400	⇒	1.200m ³
	0.5x	0.500	0.350	⇒	0.082m ³
	2.5x	3.25	0.400	⇒	3.750m ³
	5x	0.50	0.350	⇒	0.875m ³
	6x	3.10	0.350	⇒	6.570m ³
	15x	3.10	0.400	⇒	12.600m ³
	7x	2.50	0.400	⇒	7.875m ³
					891.258m ³
(2) Labour for cutting					
	62.07m to 24mm				
	dia bamboo piles —				
	— — — — etc				
	35x	1.25	⇒		43.750m
	35x	1.25	⇒		43.750m
					87.500m
	@ 87.500/1.25x3 ⇒				210m
(3) Labour for fitting and fixing 45mm dia bamboo runners					
	— — — — etc				
	10x	5	⇒		50m
	15x	4	⇒		60.0m

Continuation

Continuation

[illegible]This image shows a full page of blank graph paper. The grid consists of horizontal and vertical lines forming squares. There are approximately 20 columns and 20 rows visible. The paper has a slightly off-white or cream color, suggesting it might be older or scanned from a physical document. The grid lines are thin and dark, possibly black or dark blue ink.

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
①	providing & laying				
	gric outs				
	② TMBP-5 Qty-821.25 m ²				
	@ 184.34 / m ²				⇒ 15,11,082.01
②	labour for cutting 2mm				
	to 25mm bamboo				
	TMBP-5 Qty-210.00 m				
	@ 41.91 / m				⇒ 8801.10
③	labour for fitting &				
	fixing 25mm dia				
	TMBP-6 Qty-120.00 m				
	@ 5.06 / m				⇒ 910.80
④	Supply 20x bamboo				
	TMBP-6 Qty-65.00 No				
	@ 155.65 / No				⇒ 10117.25
⑤	labour filling empty				
	cement bags				
	TMBP-6 Qty-2880.01 kg				
	@ 34.75 / no.				⇒ 100080.00
					1790991.16
	@ 12 % GST				⇒ 214918.93
	@ 1 % labour cess				⇒ 17909.91
					2023820.00
	3rd RS				⇒ 20,23,820.00

1/2021

[Signature]
24/01/2021
J.E

Continuation

[Signature]
24/01/2021
E.E