

Inspection Report for Flood Damage work

Date:-

- 1 Name of PIUS :- Dgm Reton Rgm
2 Name of Block :- Udaipur
3 Name of Road :- Detailed estimate for Temporary Restoration of Road from Udaipur to Balinga

A. For Road

- 1 Damage Location/Chainage :- 0.00 to 0.985 km
2 Damage Length :- 0.450 km
3 Nature of damage :- Road cut
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-
Borrowed Bats

B. For Bridge

- 1 Damage Location/Chainage :-
2 Damage Length :-
3 Nature of damage :-
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-

JE

AE

EE

Signature
(Name of inspector)

Name of work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement—
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road: - Dehri/					
Estimate for Temporary					
Restoration of Road					
From Wopulra to					
Badiy Wast					
Name of Agency: -					

Heat: FDR					
Actual length 0.785 km					
Flood affected length 0.450 km					
Reconstruction					
① Daylight Distribution					
of Bridge Deck on affected					
Reconstruction for specifications					
to - as - per -					
6 x 2.4 x 1.5 x 0.25 = 4.50 m ³					
2 x 4.4 x 1.2 x 0.25 = 6.72 m ³					
2 x 3.6 x 1.1 x 0.25 = 2.25 m ³					
1 x 10.4 x 2.4 x 0.25 = 5.00 m ³					
2 x 16.5 x 1.6 x 0.25 = 4.80 m ³					
Continuation					
23.27 m ³					

[illegible]

7x4.6	x 1.40	x 6.40	=	5.60
4x5.6	x 2.60	x 6.40	=	8.60
4x14.6	x 1.80	x 6.40	=	14.60
2x18.6	x 2.60	x 6.40	=	18.60
2x12.6	x 1.80	x 6.40	=	12.60
2x10.6	x 2.60	x 6.40	=	10.60
2x12.6	x 1.80	x 6.40	=	12.60
6x8.6	x 2.60	x 6.40	=	10.60
2x9.6	x 3.60	x 6.40	=	8.60
2x14.6	x 1.80	x 6.40	=	14.60
5x7.6	x 2.60	x 6.40	=	14.60
4x11.6	x 1.80	x 6.40	=	6.40
2x16.6	x 2.60	x 6.40	=	16.60
2x16.6	x 2.60	x 6.40	=	16.60

AF 259.89

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4x3.6 x 2.6 x 0.45 =					6.6
4x3.6 x 2.6 x 0.40 =					4.80
8x3.6 x 1.6 x 0.40 =					4.80
5x12.6 x 1.15 x 0.35 =					16.5
4x3.6 x 2.6 x 0.20 =					4.80
Total					296.79

15/01/21
AC

15/01/21
AC

ABSTRACT OF COST

(D) Road clay & laying BTR
best material & proportion
-- of --

CH = 296.79

CH. 1874.77 - 15 55697234

Add 457/24 H 66716.68

Add (C.C. L.V. 15 5564.72

RA 628813.74

say 628814.00

Continuation

15/01/21
AC

15/01/2021
AC

15/01/2021
AC