

Basu to Ratanpura

Schedule XLV-Form No. 134

Darbhanga-1 DIVISION

Hanuman nagar SUB-DIVISION

Measurement Book

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Temporary					
Restoration of road from					
Baguara to Ratanpura					
Name of Agency - Departmental					
Head - FDR (2020-21)					
Date of Entry - 09-04-2021					

① Labour and Placing Brick
 bats with Light graining
 including cost of brick
 bats by tractor

1X	2.50X	2.30X	0.30 =	1.73
1X	3.50X	2.80X	0.20 =	1.96
3X	1.50X	1.50X	0.20 =	1.35
1X	2.00X	1.50X	0.20 =	0.60
1X	2.00X	1.50X	0.20 =	0.60
1X	4.00X	1.50X	0.30 =	1.80
1X	2.50X	2.80X	0.20 =	1.40
1X	8.50X	2.40X	0.25 =	5.10
1X	2.20X	0.60X	0.20 =	0.26
1X	3.50X	1.30X	0.30 =	1.37
2X	16.00X	2.30X	0.20 =	14.72
1X	2.20X	2.20X	0.30 =	1.45

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1X	1.80X	1.50X	0.30	= 0.81
	2X	2.20X	2.30X	0.20	= 2.02
	1X	5.20X	2.80X	0.30	= 4.37
	1X	1.00X	1.50X	0.20	= 0.30
	1X	4.60X	2.40X	0.30	= 3.31
	1X	4.80X	2.50X	0.20	= 2.40
	4X	1.50X	1.30X	0.20	= 1.56
	1X	3.20X	1.80X	0.20	= 1.15
	1X	5.20X	2.30X	0.30	= 3.59
	1X	2.50X	0.60X	0.30	= 0.45
	1X	1.00X	1.00X	0.20	= 1.13
	1X	12.00X	2.50X	0.20	= 6.00
	1X	3.30X	1.80X	0.30	= 1.78
	1X	9.50X	3.80X	0.40	= 14.44
	1X	9.20X	2.80X	0.30	= 7.73
	1X	3.40X	2.60X	0.30	= 2.65
	1X	8.00X	2.15X	0.30	= 5.16
	1X	1.80X	1.20X	0.30	= 0.65
	1X	26.00X	3.50X	0.30	= 27.30
	1X	2.40X	1.40X	0.30	= 1.01
	1X	8.40X	3.80X	0.40	= 12.77
	1X	4.70X	2.80X	0.20	= 2.63
	1X	3.50X	3.50X	0.40	= 4.90
	1X	17.50X	3.30X	0.30	= 17.33
	1X	3.50X	0.80X	0.20	= 0.56

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1X	7.60X	4.20X	0.40=	12.77
	1X	10.50X	3.80X	0.30=	11.97
	1X	6.70X	0.90X	0.40=	2.412
	1X	7.60X	3.80X	0.30=	8.68
	1X	8.00X	3.80X	0.40=	12.16
	1X	9.50X	3.80X	0.40=	14.44
	1X	1.00X	1.00X	0.20=	0.20
	1X	4.50X	0.60X	0.20=	0.54
	1X	8.20X	2.80X	0.40=	9.18
	1X	9.00X	2.65X	0.40=	9.54
	1X	28.00X	4.10X	0.50=	57.40
	1X	23.00X	5.30X	0.50=	60.95
	1X	2.30X	1.60X	0.40=	1.47
	1X	3.50X	1.40X	0.40=	1.96
	1X	3.70X	2.00X	0.80=	5.92
	1X	2.50X	1.80X	0.30=	1.35
	1X	2.60X	1.50X	0.20=	0.78
	1X	7.20X	3.80X	0.50=	13.68
	1X	10.80X	2.80X	0.40=	12.10
	2X	25.00X	4.60X	0.50=	115.00
	1X	8.00X	3.60X	0.60=	17.28
	1X	5.50X	0.80X	0.30=	1.32
	1X	3.50X	0.80X	0.30=	0.84
	1X	9.50X	2.40X	0.60=	13.68
	2X	30.00X	4.20X	0.50=	126.00

Continuation

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1 X	8.00 X	1.50 X	0.30 =	3.60
	1 X	10.80 X	2.90 X	0.35 =	10.98
	1 X	2.20 X	2.10 X	0.30 =	1.39
	1 X	8.20 X	3.80 X	0.40 =	12.46
	1 X	3.50 X	3.50 X	0.30 =	3.68
	1 X	8.20 X	2.80 X	0.30 =	6.89
	1 X	10.40 X	4.00 X	0.45 =	18.72
	1 X	7.50 X	2.80 X	0.30 =	6.30
	1 X	6.50 X	2.50 X	0.60 =	9.75
	1 X	3.80 X	2.10 X	0.40 =	3.19
	1 X	1.50 X	1.20 X	0.30 =	0.54
	1 X	2.50 X	2.00 X	0.80 =	4.00
	2 X	1.20 X	1.30 X	0.30 =	0.94
	2 X	1.50 X	1.60 X	0.30 =	1.44
	1 X	3.10 X	2.50 X	0.60 =	4.65
	1 X	3.00 X	1.90 X	0.80 =	4.56
	1 X	3.60 X	1.50 X	0.30 =	1.62
	1 X	4.20 X	1.80 X	0.30 =	0.30
	1 X	3.70 X	2.50 X	0.60 =	5.55
	1 X	4.50 X	4.20 X	0.40 =	7.56
	1 X	2.40 X	1.80 X	0.30 =	1.30
	1 X	7.60 X	3.80 X	0.40 =	11.55
	1 X	4.20 X	2.40 X	0.30 =	3.02
	1 X	3.20 X	2.10 X	0.70 =	4.70
	2 X	1.20 X	1.30 X	0.30 =	0.94

Continuation

Continuation

[illegible]

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2X	1.50X	1.50X	0.30	= 1.35
	1X	3.80X	1.50X	0.30	= 1.71
	1X	1.80X	2.10X	0.30	= 1.13
	1X	3.80X	1.50X	0.30	= 1.71
	1X	1.50X	1.50X	0.30	= 0.68
	3X	3.50X	2.50X	0.30	= 7.88
	1X	4.50X	0.80X	0.30	= 1.08
	1X	6.50X	1.20X	0.35	= 2.73
	1X	10.50X	1.50X	0.30	= 4.73
	1X	5.50X	3.00X	0.30	= 4.95
	4X	2.10X	2.00X	0.20	= 5.04
	3X	1.80X	1.50X	0.30	= 2.43
	1X	2.50X	1.20X	0.30	= 0.90
	2X	2.10X	1.50X	0.30	= 1.89
	1X	1.50X	0.80X	0.30	= 0.36
	1X	2.10X	1.50X	0.50	= 1.58
	1X	3.50X	3.00X	0.50	= 5.25
	1X	4.20X	2.00X	0.50	= 4.20
	1X	4.50X	1.20X	0.30	= 1.62
	1X	3.60X	1.20X	0.30	= 1.30
	1X	2.60X	1.60X	0.80	= 3.33
	1X	7.50X	3.80X	0.50	= 14.25
	1X	4.80X	2.50X	0.30	= 3.60
	1X	2.10X	1.60X	0.30	= 1.01

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1X	1.20X	1.10X	0.30=	0.40
	2X	3.00X	0.60X	0.20=	0.72
	1X	4.50X	3.60X	0.30=	4.86
	1X	2.10X	2.00X	0.30=	1.26
	1X	7.20X	2.00X	0.35=	5.04
	1X	3.60X	2.80X	0.40=	4.03
	1X	10.50X	3.00X	0.30=	9.45
	1X	9.80X	2.00X	0.40=	7.84
	1X	2.20X	2.50X	0.20=	1.10
	1X	4.50X	3.80X	0.30=	5.13
	1X	2.10X	0.80X	0.30=	0.50
	1X	2.10X	2.20X	0.30=	1.54
	1X	3.60X	3.50X	0.30=	3.78
	1X	1.50X	1.50X	0.40=	0.90
	1X	1.00X	1.50X	0.30=	0.45
	1X	0.80X	1.20X	0.30=	0.29
	2X	5.00X	2.10X	0.20=	4.20
	1X	2.20X	1.50X	0.30=	0.99
	1X	3.50X	2.50X	0.30=	2.63
	1X	1.80X	1.50X	0.20=	0.54
	1X	2.50X	3.50X	0.30=	2.63
	1X	2.80X	3.80X	0.20=	2.13
	1X	2.30X	1.50X	0.30=	1.04
	1X	8.50X	2.70X	0.30=	6.89
	2X	2.50X	2.80X	0.40=	5.60
					1569.164
					m ³

Continuation