

Amigos 1434 / 2020-2021

Schedule XLV-Form No. 134

look to take part

3000 11/11/11

DIVISION

11/11/11

SUB-DIVISION

Measurement Book

1

Date of Measurement	Contents of report
No. and date of agreement	
(These four lines should be repeated at the commencement of the measurement relating to each work)	
Control measurement	

RWD (W) DIVISION, DALSIKHSARAI
BAMASTIPUR

		2	335-28✓
--	--	---	---------

YEAR (2020 - 2021)

RWD (W) DIVISION

2. Laying Boric Bats
on prepared soil surface
until all complete —

an	1/1/17	until all employees	
Quarry.	4859.90	of May. =	194.39

Plots:

$12 \times 30m \times 2 \times 1.0w \times .20v = 120.0$	
$10 \times 30m \times 2 \times 1.0w \times .20v = 120.0$	
$3 \times 30m \times 2 \times 1.0w \times .20v = 36.0$	
$1 \times 9m \times 2 \times 1.0w \times .20v = 3.60$	
	473.992

Handwritten signature

Continuation

