

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल पटोरी ।

पत्रांक:.....614.....(अनु०)

दिनांक:-...14/05/2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल पटोरी ।

सेवा मे,

अपर मुख्य कार्यपालक पदाधिकारी - सह - सचिव
ग्रामीण कार्य विभाग,
बिहार, पटना ।

विषय:- नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु आवंटन की मांग के संबंध मे ॥

महाशय,

उपर्युक्त विषयक नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु विहित प्रपत्र मे अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने का कृपा की जाए, ताकि किये गये कार्यों का भुगतान किया जा सके । संबंधित संवेदक का इस प्रमंडल में ATR लम्बित नहीं है ।

अनु० :- यथोक्त ।

विश्वसभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल पटोरी ।

14/5/21

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date	Administrative		Agreement		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percent	Previous Total Allocated Amount (In Lakh)	Up to date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (Km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/19-20	32010401018	Basingpur Chowk To Kauna ghar	6489/13.1 2.2019	5.10	156.766	103.4298	49.52640	18/MBD/2020-21 01.08.2020	30.04.2021	Complete	3669	25 MM	5.11	0.00000	0.00000	98.60000	
2	Patoli/10	3201021036666	Bakarpur Chauk To Bakarpur Mahadaliti Tola	6489/13.1 2.2019	0.45	20.8471	15.85385	4.27082	18/MBD/2020-21 01.08.2020	30.04.2021	Complete	3937	25 MM	5.10	0.00000	0.00000	15.10000	
3		32010302044	Kheddar Path to Kabai	6489/13.1 2.2019	0.840	35.73	21.56533	8.04041	22 MBD/2019-20 13.08.2020	12.05.2021	Complete	3767	25 MM	5.12	0.00000	0.00000	15.55310	
4	MR-N/19-20	32010202021	T02 To Harpur Bochha	6489/13.1 2.2019	1.680	57.15	32.23990	16.28154	22 MBD/2019-20 13.08.2020	12.05.2021	Complete	5965	25MM	5.10	0.00000	0.00000	21.49206	
5	Patoli/13	3201021033809	Khedarpur Chowk To PWD Road	6489/13.1 2.2019	1.000	36.22	21.22210	9.77115	22 MBD/2019-20 13.08.2020	12.05.2021	Complete	3506	25MM	5.10	0.00000	0.00000	20.25055	
6		32010202024	T03 to Kancha	6489/13.1 2.2019	3.180	111.85	64.05938	31.22183	22 MBD/2019-20 13.08.2020	12.05.2021	Complete	3735	25MM	5.12	0.00000	0.00000	58.01960	
7		32010202025	T03 to Khesraha	6489/13.1 2.2019	2.550	90.56	52.88947	24.48959	22 MBD/2019-20 13.08.2020	12.05.2021	Complete	3465	25MM	5.12	0.00000	0.00000	48.86962	
Total					14.80	509.13	311.26	143.60							0.0000	0.0000	277.88493	

- 1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
2 Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer
RWD (W) Division Patoli
14.5.21
12/5/21

FORM GFR 19 –A

(See Government of India's Decision (1) below Rule-150)

Form of utilization certificate up to**Head - MR (3054)****Name of Division-** Rural Works Department, Works Division, Patori.

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lac)	Amount received (In lac)	Particulars
1	MR (3054)		605.68510	Certified that out of Rs. 605.68510 lac received during the years 2020-21 & 2021-22 in favour of the Executive Engineer, RWD, Works Division, Patori, a sum of Rs. 422.00552 lac has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs.183.67958 Lac remaining unutilized at the end of the period under.
	TOTAL		605.68510	

2. Certified that I have satisfied myself that the condition on which the grants-in-aid was sanctioned have been duly


Kinds of Cheks exercised:-

- Works have been supervised by the Executive Engineer / Superintending Engineer
- Periodical inspection has been conducted by the Executive Engineer / Superintending Engineer.
- Construction material have been tested.
- Measurement have been recorded in the M.Bs. and test cheks conducted by the Assistant.
- All other codal formalities have been observed


Physical progress Achieved-

- Construction of Road Works.
- Construction of C.D. Work.


D.A.O.
Rural Works Department
Works Division, Patori


Executive Engineer
Rural Works Department
Works Division, Patori

14/5/21

File : F:\15041142.Xls, Section No. : 29, Eqn : $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$
 Name of Customer : Chakardhar Choudhary, Name of Work/ Road : T03 to Kheshraha, Lab Job number :



Speed Breaker curve of road for chainage from Reading 4500 to 5000 of road.

Peri 2021 by
 1404 5.E
 14/11/21
 14:52
 EE

Date	Time	Section	Length	Bumps	Speed	OR	IRI CATEGORY	Latitude	Longitude	Event
14/4/21	12:7:7	29	0.1	2	30.3	2300	2745 G	25.63143	85.73906	Curve
14/4/21	12:7:7	29	0.1	290	30.3	2900	3426 G	25.63196	85.73833	Normal
14/4/21	12:7:42	29	0.1	320	30.3	3200	3767 G	25.63215	85.73741	Normal
14/4/21	12:8:0	29	0.1	290	30.3	2900	3426 G	25.63224	85.73638	Normal
14/4/21	12:8:17	29	0.1	360	20.2	3600	4222 A	25.6323	85.73534	Curve
14/4/21	12:8:17	29	0.1	260	30.3	2600	3086 G	25.63244	85.73436	Normal
14/4/21	12:8:17	29	0.1	310	30.3	3100	3654 G	25.63263	85.73342	Normal
14/4/21	12:9:0	29	0.1	340	20.2	3400	3994 G	25.63285	85.73244	Normal
14/4/21	12:9:0	29	0.1	260	20.2	2600	3086 G	25.63313	85.73148	Normal
14/4/21	12:9:28	29	0.1	230	30.3	2300	2745 G	25.63341	85.73061	Curve
14/4/21	12:9:28	29	0.1	260	30.3	2600	3086 G	25.63378	85.72965	Normal
14/4/21	12:9:28	29	0.1	260	20.2	2600	3086 G	25.63421	85.7288	Normal
14/4/21	12:10:3	29	0.1	270	30.3	2700	3199 G	25.63463	85.72786	Normal
14/4/21	12:10:3	29	0.1	220	20.2	2200	2631 G	25.63486	85.7269	Normal
14/4/21	12:10:3	29	0.1	300	20.2	3000	3540 G	25.63493	85.72591	Curve
14/4/21	12:10:38	29	0.1	230	20.2	2300	2745 G	25.63523	85.725	Normal
14/4/21	12:11:0	29	0.1	290	20.2	2900	3426 G	25.63553	85.72401	Speed Breaker
14/4/21	12:11:14	29	0.1	380	10.1	3800	4449 A	25.636	85.7232	Speed Breaker
14/4/21	12:11:14	29	0.1	290	30.3	2900	3426 G	25.63636	85.72227	Curve
14/4/21	12:11:49	29	0.1	300	30.3	3000	3540 G	25.63676	85.7214	Curve
14/4/21	12:12:0	29	0.1	340	20.2	3400	3994 G	25.63734	85.72089	Speed Breaker
14/4/21	12:12:23	29	0.1	340	30.3	3400	3994 G	25.63734	85.7199	Normal
14/4/21	12:12:23	29	0.1	300	30.3	3000	3540 G	25.63732	85.71887	Normal
14/4/21	12:13:0	29	0.1	340	20.2	3400	3994 G	25.63746	85.71786	Normal
14/4/21	12:13:0	29	0.1	300	20.2	3000	3540 G	25.63774	85.71692	Normal
14/4/21	12:13:34	29	0.1	320	20.2	3200	3767 G	25.63841	85.71655	Normal

$$Y = 0 * X^2 + 1.136 * X + 132.4$$

$$X = 6100$$

$$Y = 7062$$

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

Speed Breaker at curve of road verified change of Reading 4000 of 62151 at 500m

Ravi
14-04-2021

By
14/4/21

14.5.21
J.E