

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक.....799 अ 39 बाँका

दिनांक 30.4.21.

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।


महाशय,

उपर्युक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 1,78,88,940/-लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-1. अधियाचना प्रपत्र

2. IRI Report

विश्वासभाजन


30-04-21


कार्यपालक अभियंता
2014/21 ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक.....799अनुय बाँका

दिनांक30.4.21

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 1,78,88,940/-लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन

ह0/-

कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

ज्ञापांक-...../बाँका दिनांक

प्रतिलिपि :- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

30/4/21
कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

Form GFR 19-A

(See Government of India's Decision (1) below rule-15)
Form of utilization Certificate up to the Month March' 2021
MR/3054(NEW MAINTENANCE POLICY)

PIU-RWD(W), BANKA-2

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural roads under MR/3054(NEW MAINTENANCE POLICY)	विभागीय पत्रांक 37 दिनांक 27.05.2020 45(Encl)/18.06.2020 56(Encl)/12.08.2020 59(Encl)/18.08.2020 61(Encl)/26.08.2020 82(Encl)/13.11.2020 84(Encl)/26.11.2020 86(Encl)/11.12.2020 05(Encl) /12.01.2021 17 (Encl) / 26.02.2021 20 (Encl) /19.03.2021 22(Encl) /24.03.2021	217.86340 30.12339 525.63100 320.50000 6.57325 88.44000 395.49360 368.11196 570.35090 604.70836 361.33115 82.05330	Certified that out of Rs. 3571.18031 Lacs received during the years 2020-21 in favour of Ex. Engineer. RWD Bihar, RWD-2 Banka a sum of Rs. 3536.33652 Lacs has been utilized for the purpose of MR/3054(New Maintenance Policy) schemes as given in the margin for which it was sanctioned and that the balance of Rs 34.84379 remaining unutilized at the end of the period under.
	Total		3571.18031	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer .
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Measurement have been recorded in the MBs.
- All other code formalities have been observed.

3. Physical progress achieved :


- Construction of Road Works.
- Construction of CD Works.


Sr. D.A.O.
Works Division Banka-II
Rural Works Department


30-04-21
Executive Engineer
Works Division Banka-II
Rural Works Department

Requisition Format for Scheme Head-MR (3054) Under Bihar Rural Road Maintenance Policy 2018 (Initial Rectification and Surface Renewal)
Name of Division :- Banka-2

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion (Expected)	Value of IRI (in mm/km)	Thickness of Bitumen layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lac)	Up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (in Km)	Amount (in Lac)	Initial rectification on with Surface renewal (in lac)	5 Years Routine Maintenance (in lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/19-20 Banka-2/28	Repair of Road from BGP-Dumka Road To Uprama under MR/3054	20703502065	6276 02.12.2019	2.473	96.438	64.76726	25.51871	38/MBD/20-21 16.09.20	16.09.21	12.03.21	3224.880	25mm	5%	49.67053	49.67053	15.08940	Completed
2	MR-N/19-20 Banka-2/21	Repair of Road from Bounsiri Irrigation Dam Road To Gogula under MR/3055	20703502041	6276 02.12.2019	5.772	229.072	163.82504	58.06677	28/MBD/20-21 01.09.20	31.08.21	08.04.21	3406.879	25mm	5%	0.00000	0.00000	163.80000	Completed
		Total															178.88940	


 Executive Engineer
 R.W.D.(IV) Division,
 Banka-2
 30/11/21

Lab Job number :18

Date :12-03-2021

Name of Customer :Amar Kumar Mishra

Name of Work/ Road :Bhagalpur Dumka Road To Upmara


Sr.no	Location of test(in km)	Corrected U.I value(mm/km)	Road catagory
1	0.1	3078	G
2	0.2	3562	G
3	0.3	3756	G
4	0.4	3659	G
5	0.5	2981	G
6	0.6	3175	G
7	0.7	3272	G
8	0.8	3078	G
9	0.9	3369	G
10	1	3562	G
11	1.1	2981	G
12	1.2	3175	G
13	1.3	3272	G
14	1.4	3466	G
15	1.5	3078	G
16	1.6	3659	G
17	1.7	3078	G
18	1.8	2981	G
19	1.9	3369	G
20	2	3272	G
21	2.1	3369	G
22	2.2	2981	G
23	2.3	2787	G
24	2.4	2981	G
25	2.5	2687	G

12-3-2021
22

12/03/21
822

12-03-21
EXECUTIVE ENGINEER
R.W.D. (W) Division
Banka-2

File : F:\BANK-2\18\12031209.Xls, Section No. : 18, Eqn : $Y = 0 \cdot X^2 + 0.969 \cdot X + 74.60$
 Name of Customer : Amar Kumar Mishra, Name of Work/ Road : Bhagalpur Dumka Road To Upmara, Lab Job



[Signature]
 EXECUTIVE ENGINEER
 R.W.D. (W) Division
 Banka-2

[Signature]
 12.03.21

[Signature]
 12.03.21


Name of Customer : Anur Kumar Mishra
 Name of Work/ Road : Bhagelpur Dumka Road To Upmara
 Lab Job number : 18
 Date : 12-03-2021
 Section No. : 18

Test Date : 12-03-2021
 Machine No : 332
 Start S No :
 Start E No :
 Weather :
 Start Location : J48 86.98345
 End Location : J37 86.962845
 Road Name : Bhagelpur Dumka Road To Upmara
 Road Type : (R) RURAL ROAD
 Side :
 UV Range : 1687 To 5000 mm/km
 Dist Range : 0 To 25
 Interval : 0.1
 Equation : $Y = 0 \cdot X^2 + 0.969 \cdot X + 74.60$

Print Generate Report and Graph

Redraw Graph

Map View




12-03-2021
 12-03-21
 002

EXECUTIVE ENGINEER
 R.W.D. (W) Division
 Banka-2

Map View

File :F:\BANK-2\1812031209.Xls, Section No. :18, Eqn : $Y = 0 \cdot X^2 + 0.969 \cdot X + 74.60$



Ali
EXECUTIVE ENGINEER
R.W.D. (W) Division
Banka-2

Ali
12-03-21

12-3-2021

Name of Customer :Amar Kumar Mishra
Name of Work/ Road :Bhagalpur Dumka Road To Upmara

$$Y = 0 * X^2 + 0.969 * X + 74.60$$

$$X = 2697$$

$$Y = 2687$$

(R) RURAL ROAD

Good Average Poor
 <4000 4001-5000 >5001


Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR		CATEGORY ROAD	IRI	Latitude	Longitude	Event
						mm/km	UIV					
12/3/21	11: 53: 21	18	0.1	310	0	3100	3078	G	4.12	24.99048	86.98345	Normal
12/3/21	11: 53: 21	18	0.1	360	20.2	3600	3562	G	4.69	24.990788	86.982558	Normal
12/3/21	11: 54: 0	18	0.1	380	20.2	3800	3756	G	4.92	24.99103	86.981582	Normal
12/3/21	11: 54: 0	18	0.1	370	20.2	3700	3659	G	4.8	24.991435	86.980707	Culvert
12/3/21	11: 54: 31	18	0.1	300	10.1	3000	2981	G	4	24.990923	86.980202	Normal
12/3/21	11: 55: 0	18	0.1	320	20.2	3200	3175	G	4.23	24.990108	86.97983	Curve
12/3/21	11: 55: 42	18	0.1	330	0	3300	3272	G	4.35	24.990398	86.978855	Normal
12/3/21	11: 56: 0	18	0.1	310	10.1	3100	3078	G	4.12	24.990582	86.977928	Normal
12/3/21	11: 56: 51	18	0.1	340	0	3400	3369	G	4.46	24.990862	86.976968	Normal
12/3/21	11: 57: 0	18	0.1	360	10.1	3600	3562	G	4.69	24.99111	86.976043	Normal
12/3/21	11: 57: 27	18	0.1	300	10.1	3000	2981	G	4	24.991342	86.97507	Normal
12/3/21	11: 58: 2	18	0.1	320	10.1	3200	3175	G	4.23	24.99152	86.974123	Normal
12/3/21	11: 58: 2	18	0.1	330	20.2	3300	3272	G	4.35	24.99166	86.973248	Normal
12/3/21	11: 58: 2	18	0.1	350	30.3	3500	3466	G	4.58	24.9918	86.972205	Normal
12/3/21	11: 58: 37	18	0.1	310	30.3	3100	3078	G	4.12	24.992013	86.971245	Normal
12/3/21	11: 59: 0	18	0.1	370	20.2	3700	3659	G	4.8	24.992195	86.970268	Normal
12/3/21	11: 59: 13	18	0.1	310	10.1	3100	3078	G	4.12	24.992342	86.969308	Normal
12/3/21	11: 59: 13	18	0.1	300	30.3	3000	2981	G	4	24.992515	86.968332	Normal

EXECUTIVE ENGINEER
 R.W.D. (W) Division
 Banka-2

12-3-2021
 12/03/21
 09

12/3/ 21	11:59:13	18	0.1	340	30.3	3400	3369	G	4.46	24.992727	86.96739	Normal
12/3/ 21	12:0:0	18	0.1	330	10.1	3300	3272	G	4.35	24.99282	86.966447	Curve
12/3/ 21	12:0:23	18	0.1	340	10.1	3400	3369	G	4.46	24.992728	86.965555	Normal
12/3/ 21	12:0:23	18	0.1	300	10.1	3000	2981	G	4	24.99309	86.96468	Normal
12/3/ 21	12:1:0	18	0.1	280	10.1	2800	2787	G	3.77	24.992705	86.964023	Normal
12/3/ 21	12:1:34	18	0.1	300	0	3000	2981	G	4	24.992487	86.963265	Curve
12/3/ 21	12:2:9	18	0.089	240	10.1	2697	2687	G	3.65	24.991737	86.962845	Normal


 EXECUTIVE ENGINEER
 R.W.D. (W) Division
 Banka-2


 12/3/20
 12:03:4
 An