



कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग
Rural Works Department. (W) Division, Rosera

पत्रांक- 865 अगु

रोसड़ा,

दिनांक- 26/05/2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल रोसड़ा।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी - सह - सचिव
ग्रामीण कार्य विभाग,
बिहार, पटना

विषय:-

नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना अंतर्गत राशि की अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने का कृपा की जाए, ताकि किये गये कार्यों का भुगतान किया जा सके।

अनु० :- यथोक्त।

विश्वासभाजन,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, रोसड़ा

26-5-2021

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division, Rosera

Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval Letter No & Date	Length (Km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance	Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lakh)	Up to date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RMSA/ROS/19/0004	NEA22006803	TOT - RAMATL	1856 & 24.06.19	3.300	95.550	57.43500	28.43996	02(NIBD) 2020-21	13.05.2021	Ongoing	3752.906	25 MM	5.10	0.00000	0.00000	57.38500	SDBC Completed
2	RMSA/ROS/19/0005	32010302079	X-ROAD TO L023- Chatauni	1856 & 24.06.19	3.310	99.760	59.92700	29.78975	28(NIBD) 2020-21	12.08.2021	Ongoing	3023.606	25 MM	5.10	0.00000	0.00000	59.87700	SDBC Completed
Total					6.61	195.31	117.36	58.23							0.00000	0.00000	117.26200	

1 Signed Hard Copy of recorded IRI is enclosed.


2 Up-to-date Physical Progress has been uploaded in MIS

Sr. DAO
RWD (WD) Division Rosera

Executive Engineer
RWD (WD) Division Rosera

(Signature)

File : D:\New Maint. Policy Requisition\Rams Shankar Mahtha\03051931.xlsx, Section No. : 90, Eqn : $Y = 0 * X^2 +$
 Name of Customer : Ram Shankar Mahtha, Name of Work/ Road : L023-Chatauni, Lab Job number :



Curve for speed breaker to be made change in I.R.I reading 4000 to 5000

26/5/21
J.E

26/5/21
A.E

Executive Engineer
 Rural Work Department
 Work Division Rosera

Date	Time	Section	Length in km	Bumps in 100m	Speed Rate	OR mm/km	IRI mm/km	TEGORY ROAD	Latitude	Longitude	Event			
25/5/21	11:2:15	90	0.1	210	0	2100	2518 G		25.93028	86.17037	Normal	$v = 0 * X^2 + 1.136 * X + 132.5$		
25/5/21	11:2:15	90	0.1	200	10.1	2000	2404 G		25.93011	86.18013	Normal	$X = 5700$		
25/5/21	11:3:0	90	0.1	150	20.2	1500	1836 G		25.93022	86.19007	Normal	$v = 6607$		
25/5/21	11:3:0	90	0.1	170	20.2	1700	2063 G		25.93032	86.19982	Normal			
25/5/21	11:3:26	90	0.1	160	20.2	1600	1950 G		25.93053	86.20992	Normal	(R) RURAL ROAD		
25/5/21	11:3:26	90	0.1	340	10.2	3400	3994 G		25.93056	86.21935	Normal	Good	Average	Poor
25/5/21	11:3:26	90	0.1	280	0	2800	3313 G		25.93098	86.22625	Speed Breaker	<4000	4001-5000	>5001
25/5/21	11:4:1	90	0.1	220	20.2	2200	2631 G		25.93184	86.22928	Normal			
25/5/21	11:4:1	90	0.1	310	20.2	3100	3654 G		25.93237	86.23518	Curve			
25/5/21	11:4:1	90	0.1	270	30.3	2700	3199 G		25.9322	86.24562	Curve			
25/5/21	11:4:36	90	0.1	230	30.3	2300	2745 G		25.93197	86.25505	Curve			
25/5/21	11:5:0	90	0.1	270	30.3	2700	3199 G		25.93178	86.26463	Curve			
25/5/21	11:5:12	90	0.1	220	20.2	2200	2631 G		25.93154	86.2744	Curve			
25/5/21	11:5:12	90	0.1	200	20.2	2000	2404 G		25.93139	86.2838	Normal			
25/5/21	11:5:12	90	0.1	240	30.3	2400	2858 G		25.93154	86.29427	Normal			
25/5/21	11:5:47	90	0.1	280	30.3	2800	3313 G		25.93169	86.30387	Curve			
25/5/21	11:6:0	90	0.1	290	20.2	2900	3426 G		25.93228	86.30807	Normal			
25/5/21	11:6:22	90	0.1	280	20.2	2800	3313 G		25.93278	86.31328	Normal			
25/5/21	11:6:22	90	0.1	300	30.3	3000	3540 G		25.93261	86.32222	Curve			
25/5/21	11:6:22	90	0.1	300	30.3	3000	3540 G		25.93257	86.33282	Curve			
25/5/21	11:7:0	90	0.1	250	30.3	2500	2972 G		25.93251	86.34258	Curve			
25/5/21	11:7:0	90	0.1	230	30.3	2300	2745 G		25.93243	86.35235	Curve			
25/5/21	11:7:0	90	0.1	270	30.3	2700	3199 G		25.93207	86.3616	Normal			
25/5/21	11:7:33	90	0.1	230	30.3	2300	2745 G		25.93141	86.36852	Curve			
25/5/21	11:7:33	90	0.1	210	30.3	2100	2518 G		25.93081	86.37508	Normal			
25/5/21	11:8:0	90	0.1	250	30.3	2500	2972 G		25.93021	86.38298	Normal			
25/5/21	11:8:8	90	0.1	250	30.3	2500	2972 G		25.92969	86.3914	Curve			
25/5/21	11:8:8	90	0.1	240	30.3	2400	2858 G		25.92952	86.4008	Normal			
25/5/21	11:8:8	90	0.1	290	30.3	2900	3426 G		25.92956	86.41143	Normal			
25/5/21	11:8:43	90	0.1	270	20.2	2700	3199 G		25.92968	86.4212	Normal			
25/5/21	11:8:43	90	0.1	260	20.2	2600	3086 G		25.92969	86.43147	Normal			
25/5/21	11:9:0	90	0.1	390	10.1	3900	4562 A		25.92994	86.44073	Curve			
25/5/21	11:9:0	90	0.1	340	0	3400	3994 G		25.92954	86.44713	Normal			

26/5/21
JG

6/10/21 5/1/21
HKE

Executive Engineer
Rural Work Department
Work Division Rosera