

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com

Mob:- 8986915310

पत्रांक..... 2132 ~~430~~ सासाराम/दिनांक 29.11.2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवा में,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार


विषय :- नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।


महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विष्वासभाजन


कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1


29/11/21

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)
Form of Utilization Certificate up to Nov 2021

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA Letter No.82, dt. 13.11.2020	24012800.00	Certified that out of Rs. 78,40,25,150.00 lakh of grants-in-aid sanctioned during the years 2021-22 Infavor of EE,RWD works division Sasaram-1 a sum of Rs 72,93,57,785.00 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 5,46,67,365.00 lakh remaining unutilized at the end of the period under report.
		Letter No.84, dt. 26.11.2020	19457900.00	
		Letter No.86, dt. 11.12.2020	65864300.00	
		Letter No.05, dt. 12.01.2021	142175100.00	
		Letter No.17, dt. 26.02.2021	17,09,10,570.00	
		Letter No.20, dt. 19.03.2021	17,81,26,075.00	
		Letter No.22, dt. 24.03.2021	24439205.00	
		Letter No.26, dt. 15.04.2021	1,50,73,500.00	
		Letter No. 27 dt. 04.05.2020	1,13,94,700.00	
		Letter No. 30, dt. 21.05.2021	9,77,70,700.00	
		Letter No.40, dt. 14.06.2021	34800300.00	
	Total:		78,40,25,150.00	


2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.


Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.

2. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD works.


Divisional Accounts Officer
R.W.D, works Division
Sasaram-1


Executive Engineer
R.W.D, works Division
Sasaram-1


29/11/21

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Registration Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Sl no.	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement Mo & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	9	Sasaram Darigawan Path-Sakas	220002783	2735 14.08.2020	6.000	380.3440	279.892	60.40556	09/MBD/ 2021-22 29.06.21	28.03.2022		2215	25.00	5.01	0.00000	0.00000	279.89200	
Total					6.000	380.34400	279.892	60.40556							0.00000	0.00000	279.89200	

[Signature]
12/11/21
Divisional Accountants Office
Rural Works Department,
Works Division, Sasaram-1

[Signature]
29/11/21
Executive Engineer
Rural Works Department
Works Division, Sasaram-1

Name of Customer : Raghvendra Pratap Singh
Name of Work/ Road : Sasaram Dangawn Path - Sakka
Lab Job number : 13
Date : 11/25/2021
Section No. : 13


Test Date : 11/25/2021
Machine No. : 391
Start S No. : 9861
Start E No. : 9880
Weather : Normal
Start Location : 24.8942, 83.984
End Location : 24.90634, 83.97
Road Name : Sasaram Dangawn Path - Sakka
Road Type : (R) RURAL ROAD
Side : Sasaram
UIV Range : 615 To 5000 Interval 1000 mm/km
Dist Range : 0 To 0.588 Interval 0.028 * 1000 m
Equation : $Y = 0 * X^2 + 1.000 * X + 415.2$

Print Generate Report and Graph

Redraw Graph

Map View

File : I:\Bump Reg and Report\Requstion Nov 2020\41. Raghvendra Pratap Singh 20.11.2021\19111552 - Graph.xls.
 Name of Customer : Raghvendra Pratap Singh, Name of Work/ Road : Sasaram Dangawn Path - Sakka, Lab Job



Handwritten: 25/11/21
Signature: [Signature]
Initials: AB

Handwritten: 25.11.21
Signature: [Signature]
Initials: AB

Handwritten: 25/11/21
Signature: [Signature]
Initials: E.E.

Name of Road : Sasaram Darigawn Path -Sakas

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR inmm/km	IRI/TEGORY ROAD	Latitude	Longitude	Event
25/11/21	15:26:15	13	0.1	310	18.1	3100	3515 G	24.8942	83.98426	Normal
25/11/21	15:26:15	13	0.1	240	10.1	2400	2815 G	24.8952	83.98428	Normal
25/11/21	15:27:0	13	0.1	250	10.1	2500	2915 G	24.89546	83.98348	Normal
25/11/21	15:27:0	13	0.1	210	30.3	2100	2515 G	24.89588	83.98268	Normal
25/11/21	15:27:0	13	0.1	260	20.2	2600	3015 G	24.8962	83.98173	Normal
25/11/21	15:27:25	13	0.1	210	30.3	2100	2515 G	24.89679	83.98114	Normal
25/11/21	15:27:25	13	0.1	220	20.2	2200	2615 G	24.89753	83.98051	Normal
25/11/21	15:28:0	13	0.1	250	20.2	2500	2915 G	24.89843	83.98047	Normal
25/11/21	15:28:0	13	0.1	350	10.1	3500	3915 G	24.89871	83.97956	Curve
25/11/21	15:28:35	13	0.1	210	30.3	2100	2515 G	24.89955	83.97951	Normal
25/11/21	15:28:35	13	0.1	240	40.4	2400	2815 G	24.90043	83.97956	Normal
25/11/21	15:28:35	13	0.1	250	40.4	2500	2915 G	24.90132	83.97968	Normal
25/11/21	15:29:0	13	0.1	200	20.2	2000	2415 G	24.90196	83.97921	Normal
25/11/21	15:29:10	13	0.1	320	10.1	3200	3615 G	24.90292	83.97946	Normal
25/11/21	15:29:46	13	0.1	120	10.1	1200	1615 G	24.90378	83.97973	Normal
25/11/21	15:30:0	13	0.1	130	10.1	1300	1715 G	24.90416	83.97896	Curve
25/11/21	15:30:21	13	0.1	190	10.1	1900	2315 G	24.90503	83.97911	Normal
25/11/21	15:31:0	13	0.1	150	10.1	1500	1915 G	24.9058	83.97936	Normal
25/11/21	15:31:31	13	0.1	190	20.2	1900	2315 G	24.90634	83.97966	Normal
25/11/21	15:32:42	13	0.1	200	26.3	2000	2415 G	24.90634	83.97966	Normal
Total			2							

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

X = 2000
Y = 2415

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

25/11/21
21

25.11.21
AC

25/11/21
ER


Name of Customer : Raghendra Pratap Singh
 Name of Work : Sasaram Dangam Path - Saka
 Road :
 Lab Job number : 14
 Date : 11/25/2021
 Section No. : 14

Test Date : 11/25/2021
 Machine No : 391
 Start S No : 9881
 Start E No : 9887
 Weather : Normal
 Start Location : 24.90666, 83.37
 End Location : 24.90767, 83.37
 Road Name : Sasaram Dangam Path - Saka
 Road Type : (R) RURAL ROAD
 Side : Sasaram
 U/V Range : 1415 To 4000
 Dist Range : 0 To 0.224
 Equation : $Y = 0 * X^2 + 1.000 * X + 415.2$

Print Generate Report and Graph

Redraw Graph Map View

File : J:\Bump Reg and Report\Regusition Nov 2020\41. Raghendra Pratap Singh 20.11.2021\19111552 - Graph.Xls.
 Name of Customer : Raghendra Pratap Singh, Name of Work/ Road : Sasaram Dangam Path - Saka, Lab Job



25/11/21
 22

25.11.21
 22

25/11/21
 22

Name of Road : Sasaram Darigawn Path -Sakas

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI\TEGORY ROAD	Latitude	Longitude	Event
25/11/21	15:34:41	14	0.1	260	24.3	2600	3015 G	24.90666	83.97875	Normal
25/11/21	15:35:0	14	0.1	280	10.1	2800	3215 G	24.90663	83.97776	Normal
25/11/21	15:35:16	14	0.1	230	20.2	2300	2715 G	24.90694	83.97687	Normal
25/11/21	15:35:16	14	0.1	290	20.2	2900	3315 G	24.9073	83.97596	Normal
Total			0.4							

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2900$$

$$Y = 3315$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

25/11/21
28

25.11.21
28

25/11/21
28


Name of Customer: Raghendra Pratap Singh
Name of Work: Sasaram Dangam Path-Sakas
Road: 15
Lab Job number: 15
Date: 11/25/2021
Section No. 15

Test Date: 11/25/2021
Machine No.: 391
Start S No.: 9888
Start E No.: 9928
Weather: Normal
Start Location: 2430729.833
End Location: 2431066.846
Road Name: Sasaram Dangam Path-Sakas
Road Type: (R) RURAL ROAD
Side: Sasaram
U/V Range: 415 To 5000
Interval: 1000 mm/km
Dist Range: 0 To 1.176
Equation: Y = 0 * X^2 + 1.000 * X + 415.2

Print Generate Report and Graph

Redraw Graph Map View

File: J:\Bump Reg and Report\Reguestion Nov 2020\41_Raghendra Pratap Singh 20.11.2021\15111552 - Graph.xls.
Name of Customer: Raghendra Pratap Singh. Name of Work/Road: Sasaram Dangam Path-Sakas. Lab Job



Sum
2511/19
25

As 1-25
25.11.21
AC

2511/19
25
AC

Name of Road : Sasaram Darigawn Path-Sakas

Date	Time	Section	Length	Bumps	Speed	OR	IRI	TEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
25/11/21	15:37:0	15	0.1	270	22.1	2700	3115	G	24.90729	83.97601	Normal
25/11/21	15:37:28	15	0.1	280	20.2	2800	3215	G	24.90696	83.97692	Normal
25/11/21	15:37:28	15	0.1	250	20.2	2500	2915	G	24.90665	83.97781	Normal
25/11/21	15:38:2	15	0.1	250	20.2	2500	2915	G	24.90669	83.97788	Normal
25/11/21	15:38:2	15	0.1	290	10.1	2900	3315	G	24.90638	83.9798	Normal
25/11/21	15:40:23	15	0.1	330	23.5	3300	3715	G	24.90631	83.98064	Normal
25/11/21	15:41:0	15	0.1	170	23.4	1700	2115	G	24.90694	83.98126	Normal
25/11/21	15:41:34	15	0.1	230	10.1	2300	2715	G	24.90758	83.98162	Normal
25/11/21	15:42:0	15	0.1	100	20.2	1000	1415	G	24.90792	83.98251	Normal
25/11/21	15:42:9	15	0.1	260	20.2	2600	3015	G	24.90823	83.98	Normal
25/11/21	15:42:9	15	0.1	200	20.2	2000	2415	G	24.90838	83.98426	Normal
25/11/21	15:42:44	15	0.1	140	20.2	1400	1815	G	24.90839	83.98512	Normal
25/11/21	15:43:0	15	0.1	160	20.2	1600	2015	G	24.90832	83.98608	Normal
25/11/21	15:43:20	15	0.1	270	20.2	2700	3115	G	24.90828	83.98709	Normal
25/11/21	15:43:20	15	0.1	330	20.2	3300	3715	G	24.90818	83.98806	Normal
25/11/21	15:43:55	15	0.1	230	20.2	2300	2715	G	24.908	83.98906	Normal
25/11/21	15:44:0	15	0.1	290	20.2	2900	3315	G	24.90788	83.99	Curve
25/11/21	15:44:0	15	0.1	260	20.2	2600	3015	G	24.9087	83.9902	Normal
25/11/21	15:44:30	15	0.1	150	20.2	1500	1915	G	24.9091	83.99081	Normal
25/11/21	15:45:0	15	0.1	140	20.2	1400	1815	G	24.9089	83.99182	Normal
25/11/21	15:45:6	15	0.1	180	20.2	1800	2215	G	24.90883	83.99271	Normal
25/11/21	15:45:6	15	0.1	270	20.2	2700	3115	G	24.90973	83.99281	Normal
25/11/21	15:45:41	15	0.1	200	20.2	2000	2415	G	24.91063	83.99298	Normal
25/11/21	15:46:16	15	0.1	100	20.1	1000	1415	G	24.91158	83.993	Normal
25/11/21	15:46:16	15	0.1	280	10.1	2800	3215	G	24.91185	83.99374	Normal
25/11/21	15:47:0	15	0.1	130	10.1	1300	1715	G	24.91171	83.99475	Normal
25/11/21	15:47:27	15	0.1	200	10.1	2000	2415	G	24.91168	83.99571	Normal
25/11/21	15:48:2	15	0.1	220	10.1	2200	2615	G	24.91162	83.99665	Normal
25/11/21	15:48:2	15	0.1	160	20.2	1600	2015	G	24.91164	83.99766	Normal
25/11/21	15:48:37	15	0.1	170	10.1	1700	2115	G	24.91159	83.9986	Normal
25/11/21	15:48:37	15	0.1	120	20.2	1200	1615	G	24.91171	83.9996	Normal
25/11/21	15:49:48	15	0.1	100	16.4	1000	1415	G	24.91144	84.505	Normal
25/11/21	15:50:0	15	0.1	150	10.1	1500	1915	G	24.91104	84.1262	Normal
25/11/21	15:50:23	15	0.1	160	10.1	1600	2015	G	24.91028	84.1648	Normal
25/11/21	15:50:23	15	0.1	340	10.1	3400	3815	G	24.9105	84.2473	Normal
25/11/21	15:51:0	15	0.1	180	20.2	1800	2215	G	24.91068	84.345	Normal
Total			3.6								

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 1800$$

$$Y = 2215$$

(R) RURAL ROAD

Good Average Poor
4000 4001-5000 >5001