

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल पटोरी

पत्रांक:.....1348.....(अनु०)

दिनांक:..... 07/10/2021.....

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल पटोरी

सेवा मे,

अपर मुख्य कार्यपालक पदाधिकारी - सह - सचिव
ग्रामीण कार्य विभाग,
बिहार, पटना ।

विषय:- नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु आवंटन की मांग के संबंध
मे ।

महाशय,

उपर्युक्त विषयक नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु
विहित प्रपत्र मे अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने का कृपा
की जाए, ताकि किये गये कार्यों का भुगतान किया जा सके । संबंधित संवेदक का इस प्रमंडल में ATR
लम्बित नहीं है ।

अनु० :- यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल पटोरी
3/10/21

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Patori

Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date	Administrative		Agreement		Agreement t No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percent	Previous Total Allocated Amount (In Lakh)	Upto date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (Km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/19-20	32010102019	Patori Mudadabad Patori Purani Bazar-Sultanpur	1857/24.06.2019	6.500	230.56620	134.86406	58.77000	06 MBD/2019-2025.12.2019	24.09.2020	Complete	3496	25MM	5.10	109.94000	109.94000	16.41232	
2	MR-N/19-20	3201021032095	Mohaddin Nagar Harail to Chapar Harijn Tola	760/14.02.2020	1.400	104.00600	68.64600	9.54307	26/MBD/2020-2108.09.2020	07.06.2021	Complete	3748	25MM	5.12	0.00000	0.00000	55.00000	
3	MR-N/19-20	3201021036668	Bochha to Bochha Rausa chaurk	6489/13.12.2019	0.700	28.10500	18.45100	7.33245	18/MBD/2020-2101.08.2020	30.04.2021	Complete	3799	25MM	5.10	0.00000	0.00000	18.10000	
4	MR-N/19-20	3201021031935	Karim Nagar Durga Mandir To Mogal chaurk Yadav Tola	6489/13.12.2019	1.000	36.75160	23.26000	10.41867	18/MBD/2020-2101.08.2020	30.04.2021	Complete	3755	25MM	5.10	0.00000	0.00000	23.00000	
Total					9.600	399.43	245.22	86.06							109.9400	109.9400	112.51232	

1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.

2 Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer
RWD (W) Division Patori
7/10/24
7/10/24

FORM GFR 19 -A

(See Government of India's Decision (1) below Rule 150)

Form of utilization certificate up to**Head MR (3054)****Name of Division** Rural Works Department, Works Division, Patorl

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lac)	Amount received (In lac)	Particulars
1	MR (3054)		993.51003	Certified that out of Rs. 993.51003 lac received during the years 2020-21 & 2021-22 in favour of the Executive Engineer, RWD, Works Division, Patorl, a sum of Rs. 964.19772 lac has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs.29.31231 Lac remaining unutilized at the end of the period under
	TOTAL		993.51003	

2. Certified that I have satisfied myself that the condition on which the grants-in-aid was sanctioned have been duly
Kinds of Checks exercised:-

- Works have been supervised by the Executive Engineer / Superintending Engineer
- Periodical inspection has been conducted by the Executive Engineer / Superintending Engineer
- Construction material have been tested.
- Measurement have been recorded in the M.Bs. and test checks conducted by the Assistant.
- All other codal formalities have been observed

Physical progress Achieved-


- Construction of Road Works.
- Construction of C.D. Work.

[Signature]
D.A.G.

Rural Works Department
Works Division, Patorl

[Signature]
Executive Engineer
Rural Works Department
Works Division, Patorl
[Signature]
27/10/2021

File: C:\Users\BRADA38\Desktop\19051839.xls, Section No.: 70, Eqn: $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$
 Name of Customer: Paton Madudabad Paton Purani Bazar to Sultanpur, Name of Work/ Road: Arpit Engicon Pvt.



Curve ~~vs~~ Speed Breaker or Reading 4000 of ~~curve~~ Record ~~is~~ at
 Pav 19.05-2021
 J.E
 19/19/21
 24.5.21
 E.E

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
19/5/21	15:46:53	70	0.1	330	0	3300	3881 G		25.6297	85.59614	Speed Breaker
19/5/21	15:47:0	70	0.1	310	10.1	3100	3654 G		25.6295	85.59539	Curve
19/5/21	15:47:28	70	0.1	320	10.1	3200	3767 G		25.6294	85.59441	Curve
19/5/21	15:48:3	70	0.1	330	10.1	3300	3881 G		25.6291	85.59355	Curve
19/5/21	15:48:3	70	0.1	320	20.2	3200	3767 G		25.6286	85.59273	Normal
19/5/21	15:48:39	70	0.1	310	20.2	3100	3654 G		25.6282	85.59184	Normal
19/5/21	15:49:0	70	0.1	300	30.3	3000	3540 G		25.6278	85.59094	Normal
19/5/21	15:49:14	70	0.1	340	10.1	3400	3994 G		25.6273	85.59024	Culvert
19/5/21	15:49:14	70	0.1	300	20.2	3000	3540 G		25.6264	85.5902	Normal
19/5/21	15:49:49	70	0.1	330	30.3	3300	3881 G		25.6255	85.59012	Normal
19/5/21	15:50:0	70	0.1	320	20.2	3200	3767 G		25.6246	85.58988	Normal
19/5/21	15:50:0	70	0.1	310	30.3	3100	3654 G		25.6243	85.58904	Curve
19/5/21	15:50:25	70	0.1	340	30.3	3400	3994 G		25.6242	85.58808	Curve
19/5/21	15:50:25	70	0.1	360	30.3	3600	4222 A		25.6237	85.58715	Curve
19/5/21	15:50:25	70	0.1	310	30.3	3100	3654 G		25.6229	85.58689	Normal
19/5/21	15:51:0	70	0.1	300	30.3	3000	3540 G		25.622	85.58667	Curve
19/5/21	15:51:0	70	0.1	320	20.2	3200	3767 G		25.6217	85.58591	Curve
19/5/21	15:51:0	70	0.1	320	30.3	3200	3767 G		25.6208	85.58577	Normal
19/5/21	15:51:35	70	0.1	300	20.2	3000	3540 G		25.62	85.58549	Curve
19/5/21	15:51:35	70	0.1	310	20.2	3100	3654 G		25.6198	85.58473	Curve
19/5/21	15:52:0	70	0.1	340	20.2	3400	3994 G		25.6189	85.58439	Normal
19/5/21	15:52:10	70	0.1	360	30.3	3600	4222 A		25.6181	85.58409	Speed Breaker
19/5/21	15:52:10	70	0.1	310	30.3	3100	3654 G		25.6172	85.58377	Normal
19/5/21	15:52:10	70	0.1	330	30.3	3300	3881 G		25.6164	85.58355	Curve
19/5/21	15:52:46	70	0.1	360	30.3	3600	4222 A		25.6155	85.58328	Curve
19/5/21	15:52:46	70	0.1	310	30.3	3100	3654 G		25.6147	85.58278	Curve
19/5/21	15:53:0	70	0.1	310	30.3	3100	3654 G		25.614	85.58229	Curve
19/5/21	15:53:0	70	0.1	300	30.3	3000	3540 G		25.6132	85.58172	Normal
19/5/21	15:53:21	70	0.1	310	30.3	3100	3654 G		25.6124	85.58145	Culvert
19/5/21	15:53:21	70	0.1	290	40.4	2900	3426 G		25.6116	85.58094	Curve
19/5/21	15:53:21	70	0.1	260	30.3	2600	3086 G		25.6108	85.58037	Normal
19/5/21	15:53:56	70	0.1	320	40.4	3200	3767 G		25.61	85.57995	Normal
19/5/21	15:54:0	70	0.1	270	30.3	2700	3199 G		25.6092	85.57951	Curve
19/5/21	15:54:0	70	0.1	300	30.3	3000	3540 G		25.6084	85.57909	Curve
19/5/21	15:54:0	70	0.1	340	30.3	3400	3994 G		25.6076	85.57859	Normal
19/5/21	15:54:32	70	0.1	260	40.4	2600	3086 G		25.6068	85.57837	Normal

$Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$
 $X = 1200$
 $Y = 1495$

(R) RURAL ROAD
 Good Average Poor
 <4000 $4001-5000$ >5001

Ran
 19-05-2021
 J-E

19/5/21

25.61
 E.E

19/5/21	15:54:32	70	0.1	290	40.4	2900	3426 G		25.6058	85.57818	Normal
19/5/21	15:54:32	70	0.1	250	30.3	2500	2972 G		25.605	85.57795	Normal
19/5/21	15:55:7	70	0.1	310	30.3	3100	3654 G		25.6041	85.57776	Speed Breaker
19/5/21	15:55:7	70	0.1	300	10.1	3000	3540 G		25.6032	85.57753	Normal
19/5/21	15:55:42	70	0.1	150	20.2	1500	1836 G		25.6023	85.57724	Normal
19/5/21	15:56:0	70	0.1	170	20.2	1700	2063 G		25.6015	85.57699	Normal
19/5/21	15:56:0	70	0.1	160	20.2	1600	1950 G		25.6006	85.57673	Normal
19/5/21	15:56:17	70	0.1	340	30.3	3400	3994 G		25.5998	85.57652	Normal
19/5/21	15:56:17	70	0.1	300	30.3	3000	3540 G		25.5989	85.57625	Normal
19/5/21	15:56:17	70	0.1	340	30.3	3400	3994 G		25.598	85.57594	Normal
19/5/21	15:57:0	70	0.1	150	20.2	1500	1836 G		25.5976	85.57534	Normal
19/5/21	15:57:28	70	0.1	170	20.2	1700	2063 G		25.5978	85.57434	Normal
19/5/21	15:57:28	70	0.1	310	20.2	3100	3654 G		25.5982	85.57347	Normal
19/5/21	15:58:0	70	0.1	300	30.3	3000	3540 G		25.5985	85.57256	Normal
19/5/21	15:58:3	70	0.1	320	30.3	3200	3767 G		25.599	85.57168	Curve
19/5/21	15:58:3	70	0.1	300	30.3	3000	3540 G		25.5994	85.57082	Speed Breaker
19/5/21	15:58:3	70	0.1	330	30.3	3300	3881 G		25.5999	85.56997	Normal
19/5/21	15:58:39	70	0.1	300	30.3	3000	3540 G		25.6004	85.56912	Normal
19/5/21	15:59:0	70	0.1	270	10.1	2700	3199 G		25.6007	85.5682	Normal
19/5/21	15:59:0	70	0.1	340	30.3	3400	3994 G		25.6011	85.56734	Curve
19/5/21	15:59:14	70	0.1	290	30.3	2900	3426 G		25.6015	85.56653	Normal
19/5/21	15:59:14	70	0.1	270	20.2	2700	3199 G		25.6016	85.56552	Normal
19/5/21	16:0:0	70	0.1	350	30.3	3500	4108 A		25.6018	85.56458	Curve
19/5/21	16:0:0	70	0.1	300	30.3	3000	3540 G		25.602	85.56359	Normal
19/5/21	16:5:0	70	0.1	380	0	3800	4449 A		25.6021	85.56259	Curve
19/5/21	16:5:7	70	0.1	150	20.2	1500	1836 G		25.6029	85.56261	Normal
19/5/21	16:5:42	70	0.1	170	20.2	1700	2063 G		25.6038	85.56278	Normal
19/5/21	16:5:42	70	0.1	290	20.2	2900	3426 G		25.6047	85.56298	Normal
19/5/21	16:6:0	70	0.1	300	30.3	3000	3540 G		25.6055	85.56316	Normal

Curve of speed Breaker or Reading. 4000 of 64191 Record 2021

19-05-2021
J.E

25-5-21
E.E