

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक.....1.4.7.0.../बाँका

दिनांक 28/8/21

प्रेषक,

अ.उ.व.

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।


महाशय,

उपर्युक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए
गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 6,25,38,000/-लाख का
आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-1. अधियाचना प्रपत्र

2.IRI Report

विश्वासभाजन


24.08.21

कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक...../बाँका

दिनांक

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 6,25,38,000/-लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन

ह0/-

कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

ज्ञापक-1470/बाँका दिनांक 28/8/21

प्रतिलिपि :- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।


29.08.21

कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

Form GFR 19-A

(See Government of India's Decision (1) below rule-15)
Form of utilization Certificate up to the Month June' 2021
MR/3054(NEW MAINTENANCE POLICY)

PIU-RWD(W), BANKA-2

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural roads under MR/3054(NEW MAINTENANCE POLICY)	विभागीय पत्रांक 37 दिनांक 27.05.2020 45(Encl)/18.06.2020 56(Encl)/12.08.2020 59(Encl)/18.08.2020 61(Encl)/26.08.2020 82(Encl)/13.11.2020 84(Encl)/26.11.2020 86(Encl)/11.12.2020 05(Encl) /12.01.2021 17 (Encl) / 26.02.2021 20 (Encl) /19.03.2021 22(Encl) /24.03.2021 27(Encl) /04.05.2021 30 (Encl) /21.05.2021 32 (Encl) / 28.05.2021	217.86340 30.12339 525.63100 320.50000 6.57325 88.44000 395.49360 368.11196 570.35090 604.70836 361.33115 82.05330 88.60000 58.28940 440.19502	Certified that out of Rs. 4158.26473 Lacs received during the years 2020-21 in favour of Ex. Engineer. RWD Bihar, RWD-2 Banka a sum of Rs. 4152.93652 Lacs has been utilized for the purpose of MR/3054(New Maintenance Policy) schemes as given in the margin for which it was sanctioned and that the balance of Rs 5.32821 remaining unutilized at the end of the period under.
	Total		4158.26473	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer .
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Measurement have been recorded in the MBs.
- All other code formalities have been observed.

3. Physical progress achieved :

- Construction of Road Works.
- Construction of CD Works.


Sr. D.A.O.
Works Division Banka-II
Rural Works Department


Executive Engineer
Works Division Banka-II
Rural Works Department

Requisition Format for Scheme Head-MIR (3054) Under Bihar Rural Road Maintenance Policy 2018 (Initial Rectification and Surface Renewal)
Division :- Banka-2

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion (Expected)	Value of IRI (in mm/km)	Thickness of Bitumen layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (in Lac)	Up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (in Km)	Amount (in Lac)	Initial rectification on with Surface renewal (in lac)	5 Years Routine Maintenance (in lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MIR-N/19-20 Banka-2/27 under 3054/MIR	Somawaran To Tahariya	20703502064	6276 02.12.2019	4.600	185.308	125.83501	46.74704	25/NIBD/20-21 22.08.20	21.08.2021	21.08.2021	3003.545	25mm	5%	0.00000	0.00000	125.80000	Completed
2	MIR-N/19-20 Banka-2/27 under 3054/MIR	Inarabaran To Pipradh	20703502038	6276 02.12.2019	6.400	263.722	180.46687	65.23302	25/NIBD/20-21 22.08.20	21.08.2021	21.08.2021	2974.968	25mm	5%	0.00000	0.00000	180.40000	Completed
3	MIR-N/19-20 Banka-2/20 under 3054/MIR	BGP Dumka Road To Kairi	20703502058	6276 02.12.2019	7.184	282.700	195.04833	72.57049	40/NIBD/20-21 19.09.2020	18.09.21	18.09.21	3091.264	25mm	5%	0.00000	0.00000	195.00000	Completed
4	MIR-N/19-20 Banka-2/20 under 3054/MIR	Bounsri Irrigation Dam Road To Madhopur	20703502044	6276 02.12.2019	2.490	91.543	61.30495	25.23370	40/NIBD/20-21 19.09.2020	18.09.21	18.09.21	2839.340	25mm	5%	0.00000	0.00000	61.30000	Completed
5	MIR-N/19-20 Banka-2/20 under 3054/MIR	BGP Dumka Road To Begduma	20703502056	6276 02.12.2019	2.492	94.561	62.89817	25.29794	40/NIBD/20-21 19.09.2020	18.09.21	18.09.21	3402.500	25mm	5%	0.00000	0.00000	62.88000	Completed
		Total															625.38000	

Executive Engineer
R.V. Division,
Banka-2
29.08.21
29/8/21

Lab Job number :63			
Date :11-08-2021			
Name of Customer :Sai Shiv Construction Pvt. Ltd.			
Name of Work/ Road :Bounsi Irrigation Dam Road to madhopur			
Sr.no	Location of	Corrected U.I	
	test(in km)	value(mm/km)	Road catagory
1	0.1	2842	G
2	0.2	3124	G
3	0.3	2809	G
4	0.4	2793	G
5	0.5	3078	G
6	0.6	3369	G
7	0.7	2787	G
8	0.8	3175	G
9	0.9	2971	G
10	1	3562	G
11	1.1	2787	G
12	1.2	2983	G
13	1.3	2787	G
14	1.4	2722	G
15	1.5	2787	G
16	1.6	2742	G
17	1.7	2786	G
18	1.8	2400	G
19	1.9	2400	G
20	2	2768	G
21	2.1	2854	G
22	2.2	2400	G
23	2.3	2497	G
24	2.4	2721	G

11-8-21
SE

Pritam
11-08-21
NE

20-08-21
EXECUTIVE ENGINEER
R.W.D. (W) Division
Banka-2

Name of Customer :Sai Shiv Construction Pvt. Ltd.
Name of Work/ Road :Bounsri Irrigation Dam Road to madhopur

Date	Time	Section	Length	Bumps	Speed	OR	CATEGORY	IRI	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	ROAD				
11-08-2021	10:33:15	63	0.1	290	30.3	2900	2842	2.82	24.78119	86.98001	Normal
11-08-2021	10:34:0	63	0.1	320	30.3	3200	3124	2.33	24.78074	86.98064	Normal
11-08-2021	10:34:36	63	0.1	290	30.3	2900	2809	2.94	24.78029	86.98128	Normal
11-08-2021	10:35:0	63	0.1	260	30.3	2800	2793	3.53	24.77984	86.98191	Normal
11-08-2021	10:35:2	63	0.1	310	30.3	3100	3078	4.12	24.77940	86.98254	Normal
11-08-2021	10:35:37	63	0.1	340	30.3	3400	3369	4.46	24.77895	86.98318	Normal
11-08-2021	10:36:12	63	0.1	280	30.3	2800	2787	3.77	24.77850	86.98381	Normal
11-08-2021	10:38:0	63	0.1	320	30.3	3200	3175	4.23	24.77805	86.98445	Normal
11-08-2021	10:38:33	63	0.1	300	20.2	3000	2971	4	24.77760	86.98508	Normal
11-08-2021	10:39:9	63	0.1	360	30.3	3600	3562	4.69	24.77716	86.98571	Normal
11-08-2021	10:40:18	63	0.1	280	10.1	2800	2787	3.77	24.77671	86.98635	Normal
11-08-2021	10:41:0	63	0.1	300	20.2	3000	2983	4.03	24.77626	86.98698	Normal
11-08-2021	10:41:29	63	0.1	280	20.2	2800	2787	3.77	24.77581	86.98762	Normal
11-08-2021	10:42:4	63	0.1	280	30.3	2800	2722	4.7	24.77536	86.98825	Normal
11-08-2021	10:43:14	63	0.1	280	30.3	2800	2787	3.77	24.77492	86.98888	Normal
11-08-2021	10:44:0	63	0.1	280	30.3	2800	2742	2.82	24.77447	86.98952	Normal
11-08-2021	10:44:25	63	0.1	280	30.3	2800	2786	3.06	24.77402	86.99015	Normal
11-08-2021	10:45:0	63	0.1	240	30.3	2400	2400	3.3	24.77357	86.99079	Normal
11-08-2021	10:45:36	63	0.1	240	20.2	2400	2400	3.3	24.77312	86.99142	Normal
11-08-2021	10:46:0	63	0.1	280	10.1	2800	2768	2.57	24.77268	86.99205	Normal
11-08-2021	10:46:11	63	0.1	290	10.1	2900	2854	2.94	24.77223	86.99269	Normal
11-08-2021	10:46:11	63	0.1	240	10.1	2400	2400	3.3	24.77178	86.99332	Normal
11-08-2021	10:46:46	63	0.1	250	30.3	2500	2497	3.42	24.77133	86.99396	Normal
11-08-2021	10:47:0	63	0.1	270	30.3	2700	2721	2.45	24.77113	86.99405	Normal

Y = 0 * X ^ 2 + 1.136 * X + 132.5
Y = 0 * X ^ 2 + 1.136 * X + 132.5
X = 6800
Y = 5465
(B) BITUMINOUS CONC.
Good Average Poor
<4000 4001-5000 >5001

[Signature]
11.08.21
A.E

[Signature]
20.08.21

EXECUTIVE ENGINEER
R.W.D. (W) Division
Banka-2

Name of Customer :	S. S. Construction Pvt. Ltd.
Name of Work Road :	Baram Inga - Darn Road to n
Lab Job number :	53
Date :	11-08-2017
Section No. :	63


Test Date :	11-01-2021	Road Name :	Yashwantrao Chavan Road to madhapur
Machine No :	407	Road Type :	(R) RURAL ROAD
Start S No :	Empty Single	Side :	
Start E No :	madhapur	Interval :	
Weather :		UV Range :	1400 To 5000 mm/hm
Start Location :	17.88 2800377	Dist Range :	0 To 2.5
End Location :	17.86 n2405319	Equation :	$Y = 0.0 \times X^2 + 11.35 \times X + 12.5$

Print Generate Report and Graph

Redraw Graph

Map View

File: C:\Users\ASUS\Desktop\Bounsri Irrigation Dam Road to madhopur\42316511.xls, Section No. 63, Eqn. Y - 0
Name of Customer: Sai Shiv Construction P.M. Ltd., Name of Work/ Road: Bounsri Irrigation Dam Road to madhopur,




Pritham
11.08.11
A.E.

25
12/8/21

for
29.08.21

File : C:\Users\ASUS\Desktop\Bounsri Irrigation Dam Road to madhopur\42316511.Xls, Section No. : 63, Eqn : $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$



29.08.21
EXECUTIVE ENGINEER
R.W.D. (W) Division
Banka-2

Pritam
11.08.21
N.E

11.08.21
56