

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, उदाकिशुनगंज
पत्रांक.....611.....उदाकिशुनगंज, दिनांक.....25/3.....2022

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल— उदाकिशुनगंज ।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी —सह— सचिव,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय :- **MR New maintenance Policy 2018** योजना से संबंधित कार्यों के भुगतान हेतु आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषयक संबंध में कहना है, कि ग्रामीण कार्य विभाग, कार्य प्रमण्डल उदाकिशुनगंज में **MR New maintenance Policy 2018** योजना के अंतर्गत चल रहे कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचना पत्र तैयार कर समर्पित किया जाता है।

अतः अनुरोध है, कि आवंटन शीघ्र उपलब्ध कराने की कृपा की जाय, ताकि संवेदक को भुगतान किया जा सके।

अनु०:- यथोक्त विहित प्रपत्र में।

विश्वासभाजन

[Signature]
25/3/22
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल उदाकिशुनगंज।



FORM GFR 19-A

Letter No- _____ Date- _____

(See Government of India's Decision (1) below Rule-150)

Form of Utilisation Certificate up to March .2022

MR New Maintenance Policy 2018

Executive Engineer Rural Works Department Works Division Udakishunganj


| Sl No | Name of Scheme | Sanction No.& Date with Amount (in Rs. Lacs) | Amount Received (in Rs. lac) | particulars |
|-------|--------------------------------|---|------------------------------|---|
| 1 | MR New Maintenance Policy 2018 | Authorisation Letter No.-08 Dated 29.01.2022 Amount- 658.93820 Lacs | 658.93820 | Certified that Rs:- 658.93820 Lac received Till the date in favour of Executive Engineer, RWD Work Division Udakishunganj. A sum of Rs.635.21614 Lac has been utilized for the purpose of MR New maintenance Policy 2018 Scheme as given in the margin for which it was sanctioned and that the balance of Rs.23.72206 Lacs remaining . |
| TOTAL | | | 658.93820 | |

2. Certified that I have satisfied myself that conditions on which the grants in -aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.
kind of checks exercised:-

- (i) Works have been supervised by Executive Engineer
- (ii) periodical inspection has been conducted by Executive Engineer
- (iii) construction material have been tested.
- (iv) Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer,
- (v) All other codal formalities have been observed.

3. Physical progress achieved: as per progress report.


25/3/22
DAO
Rural Works Department
Works Division Udakishunganj



25-3-22
Executive Engineer
Rural Works Department
Works Division Udakishunganj



Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

| Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal) | | | | | | | | | | | | | | | | | | |
|--|-------------------|---|-----------------------|--|------------------------------|-----------------|---|--------------------------------------|-----------------------------|-------------------------------------|---------------------------|------------------------|------------------------------------|--|---------------------------------------|--|--|---------|
| Sl.No | Package no. | Name of Road | Project ID as per MIS | Administrative Approval (AA) Letter No. & Date | Administrative Approval (AA) | | Agreement Amount (in Lac) | | Agreement No. & Date | Date of Completion as per Agreement | Actual Date of Completion | Value of RI (in mm/km) | Thickness of Bitumen Layer (in mm) | Value of Bitumen Content in percentage | Previous Total Allowed Amount (1 Lac) | up to date expenditure as per MIS (in Lac) | Requisition Against work done (in lac) | Remarks |
| | | | | | Length (in Km) | Amount (in Lac) | Initial Rectification with Surface Renewal (in lac) | 5 years Routine Maintenance (in lac) | | | | | | | | | | |
| 1 | RM/MA/UDA/19/0003 | Const. of road from Duhabi - Subahi to Laxmipur PMGSY path in Brick soling road via Sripur Basa Nardah Mahadalit Tola. In Puraini Block | 21004801021 | 2170/06.07.2019 | 3.200 | 223.28490 | 173.57500 | 28.66337 | 52MBD/2020-21 Dt.23.01.2021 | 22-09-21 | 12.02.2022 | 2923 | 25mm | 5% | 0.00000 | 0.00000 | 162.11343 | |
| 2 | RM/MA/UDA/19/0003 | Const. of Road From Kursandi Bholia Baba Musahni via Kursandi Charakutti MMGSY Road | 21004801012 | 2170/06.07.2019 | 1.366 | 51.16590 | 32.89500 | 14.10356 | 52MBD/2020-21 Dt.23.01.2021 | 22-09-21 | 15.02.2022 | 2793 | 25mm | 5% | 0.00000 | 0.00000 | 34.37092 | |
| Total | | | | | | | | | | | | | | | 0.00000 | 0.00000 | 196.48435 | |


D.A.O
RWD Works Division
Udakishunganj


Executive Engineer
RWD Works Division
Udakishunganj