

Inspection Report for Flood Damage Works:-

Date :-

1. Name of PIUs - Executive Engineer, RWD, Raxaul.....
2. Name of Block - Adampur
3. Name of Road - 1056-702 Subahar to Badiyaspur

(A) For Road

1. Damage Location/Chainage :- 322-330, 350-352, 915-930, 1100-1115, 1250-1271, 1300-1315
2. Damage Length :- 68.3 M
3. Nature of Damage:- Road only damaged and shoulder also damaged in some location.
4. Details of Restoration Works:- Brick & bat filling

- (i) Material being used in Restoration works: Brick Bats
- (ii) Equipments/ Tools being used in Restoration works: Tractor
- (iii) Procedure taken up in Restoration works: Departmental.

(iv) Restored Length: 68.3 M

Satisfactory

Aug
20/04/22
SE

20/04/22
me

20/04/22
Executive Engineer
RWD, (W) Div. PATNA

Name of Work:- Estimate for Repair of Road breaches (Damaged by Flood) for Motorability in L086-T02 Dubaha to Barhiarpur (BR-11R-444) For year 2021.

Quant. - 1538 Length - 1800KM

Sl No	Item No	Name of Item	Unit	No	Length	Width	Height	Qty.	Rate	Amount
1		Labour for laying 150mm graded blanda khena or stone filter under Road Paving or Roadside Paving in slope or apron including light masonry etc. all complete as per approved design, specification and direction of E.I.	cum		As Per Appendix I			125955	1911.02	240700.00
TOTAL (in Rs.)										400311.00

Say Rs 400311.00 859584.00
240700.00

Chirag

Junior Engineer,
Rural Works Department,
Works Section, Adapur

18/11/21

Assistant Engineer,
Rural Works Department,
Works Sub Division, Adapur

18/11/21
Executive Engineer,
Rural Works Department,
Works Division, Raxaul

Post facto rate is accorded for Rs. 2,40,700.00
Two lacs forty
seven hundred

18/03/2022
S.E. (R.W.D.)
works Circle
Motihari