#### Inspection Report for I-lood Damage Report

-				
1	כו	10	•	٠
_	n	ιt	_	

1 Name of PIUs

- EEI RWD, WOORS oliviston, makan

2 Name of Block/ Road

Saritya | NH 102 Hulas Rajanto Sona Rayke Rathan telle parry trachend stonen,

A. For Road

1 Damage Location/Chainage

At Ch. 280, 240. 380, 422, 1050, 1210

2 Damage Length

3 Nature of Damage

: Comblete trothe Blocked due to rireal

4 Details of Restoration Works

Brokle Ball (157.43 WS)

Material being used in Restoration i.

Je.B. Tractor, Road Rolling

Equipments/Tools being used in Restoration works

Essispediate Rentsration of trath c

Procedure taken up in Restoration works

iv. Restored Length

The work found sould seeking

B For Bridge

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

Details of Restoration Works

11.12

Material being used in Restoration

works Equipments/Tools being used in

Restoration works Procedure taken up in Restoration

works

iv. Restored Length

(Name of Inspector) र्ग विकास कार्य प्रमण्डल, महनार

¹\sitnature of JE / AE / EE

#### **FDR**

### YEAR (2021-2022)

# GENERAL ABSTRACT OF COST

Restoration of Road from N.H.- 102 Hulas Bazar to Sona Ray ke Bathan tak Paru Prakhand Sirnant tak in Saraiya Block under F.D.R., RWD, Works Division, Muzaffarpur East-1

Block :- Saraiya

District :- Muzaffarpur

SI No.

Description

<u>Amount</u>

Road Restoration Cost

Rs.

3,40,900.00 325643

Total

3,40,900.00

Say Rs.

3,40,900.00

328643

3,256 law

Junior Engineer RWD, Works Section

Saraiya

Assitant Engineer RWD, Works Sub-Div. Saraiya

Executive Engineer RWD, Works Division Muzaffarpur East-1

43 Per S.E. RWE (W) Circle 18UZ Latter No. 1179 Bate# \$1/10/7:021 Estamete has been worsted by inspecting

E.E. RWD. (M) Division Malner

Technically Sanctioned for Rs. 3. 256 law (Rs. Three law tuenty fine thousand Six numbered) only (provisionally)

Superintending Engineer

Rural Works Department

Work Circle, Muzaffarpur

## Abstract of Cost & Detailed Estimate for

Restoration of Road from N.H.- 102 Hulas Bazar to Sona Ray ke Bathan tak Paru Prakhand Simant tak in Saraiya Block under F.D.R., RWD, Works Division, Muzaffarpur East-1

SI.	SO	Item of Work	Quantity	Unit	Rate	Amount
No.	R				7 10.10	runoane
1		2	6	7	8	9
1		Providing and laying Brick bats				<u></u>
		including all taxes etc. all complete job				
		as per specification and direction of				
		E/I.			2064.56	325 643 340883.00
		As per M.B	157.73	m³	,2181.18	340883.00
2 5.6.		Labour for laying, fiting and fixing NP3				
	2.4	pipe with collors in line level and grade				
		as well providing approved jointing				
		materials and joints properly filled to				
1 1		make them water proof all completeas				
		per specification and direction of E/I				
		(Hume pipe available within a lead of				
		40 mtr 1000 mm dia or 100 mm dia				
		NP3 H.P				
		As per M.B	0.00	m	3992.28	325643
					Total Rs.	3,40,883.

Say Rs.

3,40,900.00

3256433

Junior Engineer RWD, Works Section

Saraiya

Assitant Engineer RWD, Works Sub-Div Saraiya Executive Engineer RWD, Works Division
Muzaffarpur East-1