

Schedule XLV-Form No. 134

ਅਧਿਕਾਰੀ ਪ੍ਰਾਪਤ ਹੋ ਸਕਦਾ ਹੈ

ਦੇਵਰ

DIVISION

ਦੇਵਰ

SUB-DIVISION

MEASUREMENT BOOK

- 686

N/W:- Notrable of road
 N.H. Chimni Bhatta
 to Sabikpur damaged by
 Flood Oct 2024.

Block - Lakhisar

Agays Departmentally.

Date:-

G- PW Mooram fillup in
 Pat Hole & road side

Specification				
	m	m	m	m ³
1x	3.5m	3m	30	3.15
1x	5m	3.75	30	5.63
1x	7m	3.25	30	6.83
1x	9m	3.75	30	10.13
1x	2m	3m	30	1.80
1x	7m	3.75	30	7.88
1x	3m	1m	30	.90
1x	2m	3.75	30	2.25
1x	3m	1m	30	.90
1x	2m	1m	30	.60
1x	1m	2m	30	.60
1x	2m	2m	30	1.20
1x	1m	1.5	30	.45
1x	5m	1m	30	1.50

Continuation

43.82m

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	14	3m	3.75	30	3.38
	14	2m	2m	30	1.60
	14	5m	2m	30	3.00
	14	3m	1m	30	1.60
	14	4m	3.75	30	4.50
	14	2m	3m	30	1.80
	14	1.5	2m	30	1.20
	14	1m	2m	30	1.60
	14	3m	3.75	30	3.38
	14	3m	2m	30	1.80
	14	1.50	1	30	1.45
	24	1m	1m	30	2.60
	24	1m	1.5	30	1.90
	14	10m	2m	30	6.00

	14	2m	3m	30	1.80
	14	12m	2m	30	7.20
	14	15m	2m	30	9.00
	14	10m	3m	30	9.00
	14	5m	2m	30	3.00
	14	6m	2.5	30	4.50
	14	5m	3m	30	4.50
	34	2m	3m	30	5.40
	14	6m	2m	30	3.60
	5	3m	2m	30	9.00

129.33 m

- Plv lay p spread p Conpr
 List in pot H. H. 7 tra
 As for specific au

No	m	m	m	m ³
1	x 3.5	x 3	x 1.5	= 1.584
1	x 5m	x 3.75	x 1.5	= 2.8125
1	x 7m	x 3.25	x 1.5	= 3.4125
1	x 9m	x 3.75	x 1.5	= 5.0625
1	x 2m	x 2m	x 1.5	= 0.90
1	x 7m	x 3.75	x 1.5	= 3.94
1	x 1	x 3m	x 1.5	= 1.484
1	x 2m	x 3.75	x 1.5	= 1.13
1	x 3m	x 1m	x 1.5	= 1.45
1	x 2m	x 1m	x 1.5	= 1.30
1	x 1m	x 2m	x 1.5	= 1.30
1	x 2m	x 2m	x 1.5	= 1.60
1	x 1m	x 1.5	x 1.5	= 1.23
1	x 5m	x 1m	x 1.5	= 1.75
1	x 3m	x 3.75	x 1.5	= 1.69
1	x 1m	x 2m	x 1.5	= 1.30
1	x 5m	x 2m	x 1.5	= 1.50
2	x 1m	x 1m	x 1.5	= 1.30
1	x 4m	x 3.75	x 1.5	= 2.25
1	x 2m	x 3m	x 1.5	= 1.94
1	x 1.5	x 2	x 1.5	= 1.48
1	x 1	x 2m	x 1.5	= 1.30
1	x 3m	x 3.75	x 1.5	= 1.694

Continuation

33.99 m

Particulars	Details of actual measurement				Contents c area
	No.	L	B.	D.	
	1x	3m	2m	1.5	23.55 9.0
	1x	1m	1.5	1.5	2.25
	2x	1m	1m	1.5	1.50
	2x	1x	1.5	1.5	.45
	1x	10m	2x	1.5	1.90
	1x	2x	3m	1.5	.90
1m	1x	12m	2x	1.5	3.6
	1x	15	2x	1.5	4.5
2m	1x	10m	3m	1.5	4.5
	1x	5m	2x	1.5	1.50
	1x	6m	2.5	1.5	2.25
	1x	5m	3m	1.5	2.25
	3x	2m	3x	1.5	2.7
	1x	6m	2x	1.5	1.80
	5x	3m	2x	1.5	4.50
					64.67 m
255- 71/2" Brick Bal's					
in back of roadbed					
floor.					
	7m	3m	1.5m	5m	280 m
			2		
	15/11/2007			15/11/2007	
	J.E			ME	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstracting cut for Hottel of road for N. 1/2 section Block to adjacent Block Lakin's					
D. 20' 6" 1/2 mason in place Hole of road N. 1/2 m					
P. 129.33 m					
C. 1010.11/2					13063
2. Eminent Repair by filling trenches in flood dam etc					
Stretch of road					
P. 280.43					
C. 2095.145/2					585887
3. Curb of road by forming well grade main spring pipe and capacity street only curb spring					
P. 64.67 m					9453
C. 1455.93/2					
					810680 =

Particulars	Details of actual measurement				Content area
	No.	L.	B.	D.	
				155	
				81068	
14. Jan 14				8107	
				128957	97282
S. S. 1st Base Run					
Run 2650 25-25-875					
9150 2-36				66491/2=17526	
				208965148=10649	
Local 50 33-11-45				141088=4672	
Run 1520 15-9-27				2407	
Run 335 11-22-34082					
				404570/25404	

15 95651400
 (-19-09/09 9 - 86947-
 869567-00

15/11/2021
 3-E
 15/11/2021
 A-E

15/11/2021
 E-E