



Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
	ABSTRACT OF COST			
Name of Road - Dimahi to				
Harmon Nagar				
Name of Work - Restoration of				
Flood damage part of				
Road.				
Block - Parikar				
Authority - E. E. R. W. D (W) Div.				
Sitamardi				
① providing and laying				
of brick bats for				
filling the ditch in				

road - - - all comp				
dry vide p. no - (1) T.M.B.				
44.59 M				
8.92 M ³ @ 1827-25/M				65178-0
35.67 M				
② providing quarry material				
Rabbish for filling the				
voids in brick bats.				
- - - all comp.				
dry vide p. no - (1) T.M.B.				
8.92 M ³ @ 873-01/M				7787-00
				72965-00
APP.  20.04.22  20/4/22 S.E. Per  20/04/22 AE				

Continuation