

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
CH —					
Name of Work — Restoration of					
Floor damage part of					
Road					
Name of Road — Chautah Purvi					
Tola to L037					
Authority: — E.E.R.W.D (W) Div;					
Sitamarhi					
(1) Providing and laying					
of brick bats for					
filling the ditch --					
-- all comp					
Duty vide p.no. — (2) T.M.B.					
830.39 M ³					
166.08 M ³ k.f. + 1/2					
664.31					
M ³ @ 1827 = 25 / M ³ - Rs					1213860 = a
(2) Providing Quarry					
Material rubbish for					
filling the voids in					
brick bats -- etc.					
Duty vide p.no. — (2) T.M.B.					
166.08					
M ³ @ 873 = 01 / M ³ - Rs					144989 = a
					B 13 58849 = a
Total 140 Labour less 1/4					
Total 12 to G.S. 1/4					
Total 10 to S. 1/4					

Continuation

K.

C&P.

20.04.22

S.E.

20/4/22