

ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILD PROJECT REPORT FOR MOTRABLE REPAIRING OF ROAD

F.D.R. PART - MOTRABLE RESTORATION

L032-T02 TO AMDAUL (TRACK 12)

DETAILED ESTIMATE OF F.D.R. MOTRABLEREPAIRING ROAD

ROAD LENGTH	0 TO 2250	
DISTRICT	KATIHAR	
BLOCK	PRANPUR	
DIVISION	MANIHARI	
TOTAL LENGTH OF ROAD	2.250	KM
TOTAL COST OF F.D.R. PART - A	Rs. 33.627	Lacs
ADD G.S.T @ 12%	Rs. 4.035	Lacs
ADD Labour Cess @ 1%	Rs. 0.336	Lacs
ADD Seigniorage Fee @ 10%	Rs. 1.831	Lacs
TOTAL COST OF RESTORATION WORK In Rs.	Rs. 39.829	Lacs

SUBMITTED BY

The Executive Engineer, Works Division, Manihari

प्रतिवेदन

प्रस्तुत प्राक्कलन ग्रामीण कार्य विभाग कार्य प्रमण्डल मानिहारी अन्तर्गत प्राणापुर प्रखंड के पथ L022, 102 वि अमफोल (TRACK12) (...) जो विभागीय Online Morititring System MIS पर अपलोड है के बाढ 2021 से क्षतिग्रस्त हो जाने के कारण यातायात लायक Moterable हेतु बनाया गया है। इस कार्य को करने का निर्देश ग्रामीण कार्य विभाग, बिहार सरकार के पत्रांक:—मु०अ०—4(मु०) विविध (कार्य) —23—291/2019—4275/पटना, दिनांक— 22 / 10 / 2021 से प्राप्त है। इस पत्र से Real time Geotagged Photographs को कार्य के दौरान अपलोड करते हुए (Moterable) कार्य कराना सुनिश्चित करने का निर्देश प्राप्त है।

उक्त निर्देश के आलोक में २० ५ अतिवृष्टि / बाढ़ उपधार से आए बाढ के करण इस पथ के रोडवे के क्षतिग्रस्त हो जाने से सुरक्षित आवागमन हेतु Moterable कार्य कराया गया है। MIS में उपलोडेड फोटो दिनांक ..१.। ११ ११ का Lat/Long के साथ लिया गया है। नेपाल तराई से निकलनेवाली इस नदी के तेज धार से इस पथ में कटाव की स्थिति बनी। मोटरेबल कार्य में आवश्यकतानुसार मिट्टी भराई, लोकल बालु भराई, खाली सिमेंट बैग में लोकल बालु भरकर, बॉस का पाइल, चचरी, बॉस का रनर, ह्यूम पाइप एवं ब्रिक बैट का इस्तेमाल किया गया है । निर्देशानुसार कराए गए कार्य कि Geotagged Photographs Real Time के साथ MIS पर उद्वत है। MIS की छायाप्रति, अपलोडेड फोटोग्राफ की छायाप्रति, दर विश्लेषण एवं विभागीय आदेशों की छायाप्रति प्राक्कलन में संलग्न की जा रही है। प्राक्कलन में प्रयुक्त दर अद्यतन है।

प्राक्कलन की यथाशीध्र अनुमोदन अपेक्षित है ताकि अग्रेतर कार्रवाई की जा सके।

कनीय अभियंता ग्रामीण कार्य विभाग कार्य प्रशाखा, प्राधापुर

सहायक अभियंता ग्रामीण कार्य विभाग कार्य अवर प्रमंडल, प्राणपुर कार्य प्रमंडल, सीन

ग्रामीण कार्य विभाग

Date: Inspection Report for flood damings work 1. Name of PIUs- !— EE RWD, Manihari
2. Name of Block/Road- Pranput, Loss - Tor to AmDAUL (Track)
A.For Rond
1.Damage Location/Chainage: CH — 1.8 ro km. 2. Damage Lengh: 206 m 3. Nature of Damage: flowed works was filled. 4. Details of Restoration: Brick bash filling i Material being used in Restoration works: Brick bash filling ii Equipment/Tools being used in Restoration works: iii Procedure taken up in Restoration works iv Restored Length: 206 m. B. For Bridge 1. Damage Location/Chainage: N/A 2. Damage Lengh: 3. Nature of Damage: i Material being used in Restoration: i Material being used in Restoration ii Equipment/Tools being used in Restoration works: iii Procedure taken up in Restoration works: iii Procedure taken up in Restoration works: iv Restored Length: iv Restored Length: iii Procedure taken up in Restoration works: iv Restored Length: iii Procedure taken up in Restoration works: iv Restored Length: iii Procedure taken up in Restoration works: iv Restored Length: iii Procedure taken up in Restoration works: iv Restored Length: iii Procedure taken up in Restoration works: iv Restored Length: iiiii Procedure taken up in Restoration works: iv Restored Length: iiii Procedure taken up in Restoration works: iv Restored Length: iii Procedure taken up in Restoration works: iv Restored Length: iii Procedure taken up in Restoration works: iv Restored Length: iii Procedure taken up in Restoration works: iv Restored Length: iii Procedure taken up in Restoration works: iv Restored Length: iii Procedure taken up in Restoration works: iii Procedure taken up in Restoration ii Procedure
Signature of JE/AE/EE Signature (Name of Inspector)

Scanned with Cams

GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD :

L032-T02 TO AMDAUL (TRACK 12)

DISTRICT

KATIHAR

DIVISION

MANIHARI

BLOCK

PRANPUR

LENGTH OF ROAD (IN KM)

2 250

Sl. No.	ITEM OF WORK	AMOUNT (LAKHS
1	EARTH WORK	
		0.000
2	WINE DID	
	HUME PIPE	0.000
3	DDUCO	
•	BRIKCK BAT	33.627
4	SAND BAGS	
	3.00	0.000
5	BAMBOO WORK	
	J. SHECO WORK	0.000
6	CTCT DDIVI	
•	STEEL DRUM SHEET	0.000
		2.000
	TOTAL COST OF PROJECT =	33.627
Add G.S.1. @ 12%		4.035
Add Labour Cess @ 1%		0.336
Add Seigniorage Fee @ 10%		1.831
Total Cost of Restoration Work =		39.829

J.E. RWD

A.E

RWD

EE ON

Technically sanctioned for its 39.829 lack. (Puppers thirty nine eighty two thousand Inine hundred)

Superintendent Engine or Rural Works Department Works Circle, Purnea