



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR REPAIRING OF ROAD

F.D.R. PART - MOTRABLE RESTORATION

S0100 TO MANDIR (LAKHI TOLO RAGHOPUR)

DETAILED ESTIMATE OF F.D.R. MOTRABLE REPAIRING ROAD

ROAD LENGTH	0 TO 555	
DISTRICT	KATIHAR	
BLOCK	MANIHARI	
DIVISION	MANIHARI	
TOTAL LENGTH OF ROAD	0.555	KM
TOTAL COST OF F.D.R. PART - A	Rs. 4.160	Lacs
ADD G.S.T @ 12%	Rs. 0.499	Lacs
ADD Labour Cess @ 1%	Rs. 0.042	Lacs
Add Seigniorage Fee @ 10 %	Rs. 0.223	Lacs
TOTAL COST OF RESTORATION WORK In Rs.	Rs. 4.924	Lacs

SUBMITTED BY
The Executive Engineer,
Works Division, Manihari

प्रतिवेदन


पथ का नाम :- S0100 To Mandir (Lakhitola Ragharpur)
पथ की लम्बाई :- 0.555 KM
प्राक्कलित राशि :- 4.924 Lac
वित्तीय वर्ष :- 2021-2022
प्रखंड :- Manihari

प्रस्तुत प्राक्कलन मो० 4.924 (चार लाख नब्बे हजार दो सौ)

की राशि में ग्रामीण कार्य विभाग, कार्य प्रमंडल मनिहारी अन्तर्गत मनिहारी प्रखंड के S028 To Banfh Ganga पथ हेतु तैयार की गई है। वर्तमान वर्ष 2021 के बाढ़ एवं अतिवृष्टि के कारण क्षतिग्रस्त एवं पथ को MIS पर अपलोड किया जा चुका है, तथा विभागीय निर्देश ग्रामीण कार्य विभाग, बिहार के पत्रांक-मु० अ०-4 (मु०) विविध (कार्य)-23/291/2019-4275/पटना, दिनांक- 22.10.2021 के आलोक में यातायात (Motorable) पुर्नस्थापन किया गया है।

उपर्युक्त प्राक्कलन में क्षतिग्रस्त सड़क के फलैंक/सरफेस को Bricks basts से भरकर आवागमन चाक किया गया है एवं सड़क पर होने वाली दुर्घटना को रोका गया है।


प्रस्तुत प्राक्कलन ग्रामीण कार्य विभाग, कार्य अंचल पुर्णियाँ द्वारा प्राप्त कोटेशन के न्युनतम दर पर तैयार किया गया है, प्राक्कलन की स्वीकृति जनहित में अति आवश्यक है।


25/11/21

कनीय अभियंता

ग्रामीण कार्य विभाग


कार्य प्रशाखा, मनिहारी


25/11/21

सहायक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रशाखा, मनिहारी


25/11/21

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रमंडल, मनिहारी

9

Inspection Report for Flood damage work

Date:

1. Name of PIUs-

Manihari

2. Name of Block/Road-

50.100 To Mandir (Labhi R. Raghapur)

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 180 m/r

3. Nature of Damage

4. Details of Restoration : Side cleared - cutting due to Flood.

i Material being used in Restoration

: Bricks Bats

ii Equipment/Tools being used in Restoration works:

Tractor

iii Procedure taken up in Restoration works

: Manual

iv Restored Length

: 180 m/r

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Man
25/11/21

Signature of JE/AE/EE

San 25/11/21
12

25/11

Signature

(Name of Inspector)

GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD : S0100 TO MANDIR (LAKHI TOLO RAGHOPUR)
DISTRICT KATIHAR
DIVISION MANIHARI
BLOCK MANIHARI
LENGTH OF ROAD (IN KM) 0.555

Sl. No.	ITEM OF WORK	AMOUNT (LAKHS)
1	BRICK BAT	4.093
2	SAND BAGS	0.000
3	BAMBOO WORK	0.000
4	HUME PIPE	0.068
TOTAL COST OF PROJECT =		4.160
Add G.S.T. @ 12%		0.499
Add Labour Cess @ 1%		0.042
Add Seigniorage Fee @ 10 %		0.223
Total Cost of Restoration Work =		4.924

Munir
25/11/21
JE
RWD

Sant
25/11/21
AE
RWD

EE
RWD

Technically Sanction for Rs. 4.924 Lac (Rs. Four Crore. four Lac. ninety two Thousand. four Hundred.) Only

[Signature]
Superintendent Engineer
Rural Works Department
Works Circle, Purnea