

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर

पत्रांक 2307/अनु दिनांक 10/12/22

प्रेषक:—

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:—

शीर्ष New Maintenance Policy 2018 मद में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषयक शीर्ष New Maintenance Policy 2018 योजनान्तर्गत निर्मित/
निर्माणाधीन पथों का विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजा जा रहा है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की कृपा
की जाय।

अनु०—यथोक्त।

विश्वासभाजन

NY
10.12.22

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर

FROM GFR 19-A**(See Government of India's Division (I) below Rule- 150)****Form of Utilization Certificate upto 10.12.2022****PIU- E.E., R.W.D. Works Division, Samastipur**

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto Lt. no.-35 dt. 13.10.2022	328669369.00	Certified that out of Rs.328669369.00 received upto 10.12.2022 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.317224594.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 11444775.00 remaining unutilized at the end of period under report.
			32,86,69,369.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.

ny
10.12.22
Executive Engineer
Works Division Samastipur
Rural Works Department

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Samastipur																			
Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date		Administrative		Agreement Amount		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lakh)	Upto date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
				Length (Km)	Amount (In Lakh)	Initial Rectificatio n with Surface Renewal	5 Year Routine Maintenance												
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	RM/SA/SAM/20/0003	32010101001	Berhata Middle School to Bhagwanpur	2930 & 26.08.2020	2.280	97.961	65.554	22.668	49(MBD)21-22	17.11.2022	Complete	3099	25	5.0	0	0	65.554	BT Complete	
		NEA22000573																	
2			SH TO - MANKAULI		2.950	101.169	57.305	37.719		17.11.2022	Complete	3102	25	5.0	0	0	57.305	BT Complete	
Total						199.13000	122.85862	60.38700										122.859	

1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.

2 Up-to-date Physical Progress has been uploaded in MIS

M. 10.12.22
Executive Engineer
RWD (W) Div. Samastipur

Name of Road :-Barhatta Middle School To Bhagwanpur
Section no.-38

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
3/12/22	13:7:18	38	0.1	300	0	3000	2998	G	26.003045	85.806054	Curve
3/12/22	13:7:18	38	0.1	310	10.1	3100	3087	G	26.003225	85.806782	Normal
3/12/22	13:7:18	38	0.1	320	10.1	3200	3176	G	26.00272	85.807376	Normal
3/12/22	13:8:0	38	0.1	330	10.1	3300	3265	G	26.002861	85.808388	Normal
3/12/22	13:8:0	38	0.1	290	10.1	2900	2909	G	26.003272	85.808889	Curve
3/12/22	13:8:28	38	0.1	310	10.1	3100	3087	G	26.00285	85.809954	Curve
3/12/22	13:9:3	38	0.1	320	10.1	3200	3176	G	26.003214	85.811115	Curve
3/12/22	13:9:39	38	0.1	300	10.1	3000	2998	G	26.003236	85.811315	Curve
3/12/22	13:10:0	38	0.1	310	10.1	3100	3087	G	26.002741	85.811484	Normal
3/12/22	13:10:12	38	0.1	320	10.1	3200	3176	G	26.002529	85.813603	Normal
3/12/22	13:10:12	38	0.1	330	10.1	3300	3265	G	26.002309	85.813733	Normal
3/12/22	13:10:47	38	0.1	310	10.1	3100	3087	G	26.000863	85.814248	Curve
3/12/22	13:10:47	38	0.1	290	10.1	2900	2909	G	26.000571	85.814052	Normal
3/12/22	13:11:22	38	0.1	280	10.1	2800	2820	G	25.9994	85.813817	Normal
3/12/22	13:11:22	38	0.1	310	10.1	3100	3087	G	25.998576	85.813898	Normal
3/12/22	13:11:22	38	0.1	330	10.1	3300	3265	G	25.997966	85.813981	Curve


[Signature]
31/12/22

[Signature]
31/12/22
J.C

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY	Latitude	Longitude	Event
3/12/22	13:11:58	38	0.1	320	10.1	3200	3176	ROAD	25.997287	85.813688	Normal
3/12/22	13:12:0	38	0.1	340	10.1	3400	3354	G	25.996909	85.81368	Curve
3/12/22	13:12:18	38	0.1	310	10.1	3100	3087	G	26.003505	85.809165	Normal
3/12/22	13:12:18	38	0.1	300	10.1	3000	2998	G	26.004558	85.809859	Normal
3/12/22	13:13:0	38	0.1	310	10.1	3100	3087	G	26.005175	85.810038	Normal
3/12/22	13:13:9	38	0.1	310	10.1	3100	3087	G	26.004316	85.809067	Normal
		Total=	2.2				Avg.	3099.14			


 9.12.22
 Executive Engineer
 R.W.D.(W) Division,
 Samastipur


 3/12/22
 7-8



[Signature]
3/12/22
S.E.

[Signature]
3/12/22
S.E.

[Signature]
3/12/22
S.E.