

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सहरसा।

पत्रांक 1766 3190
प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सहरसा।

सेवा में,

नोडल पदाधिकारी,
नई अनुरक्षण नीति - 2018 (MR 3054)
ग्रामीण कार्य विभाग,
बिहार, पटना।

सहरसा दिनांक 16-12-22

विषय : शीर्ष MR 3054 / नई अनुरक्षण नीति - 2018 के तहत कराए गए कार्य के विरुद्ध में
आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषयक संबंध में इस प्रमंडल के शीर्ष MR 3054 / नई अनुरक्षण नीति - 2018 के अंतर्गत Latha Koshi nahar purbi tola se Tirhut Chowk bypass PWD Sarak hote hue Sarahi Chowk tak पथ का कार्य पूर्ण किया जा चुका है। उक्त पथ में किए गए कार्य के भुगतान हेतु कुल 54.24209 लाख (चौबन लाख चौबिस हजार दो सौ नौ) के भुगतान हेतु आवंटन की अधियचना विहित प्रपत्र में तैयार कर समर्पित की जाती है।

अतः अनुरोध है कि उक्त कार्य हेतु आवंटन उपलब्ध कराने की कृपा की जाय।

अनु. - यथोक्त।

विश्वासभाजन

16-12-2022

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
सहरसा।

बिहार सरकार


कार्यपालक अभियंता का कार्यालय,

ग्रामीण कार्य विभाग, कार्य प्रमंडल, सहरसा।

प्रमाणित किया जाता है कि 3054 MR नई अनुरक्षण नीति 2018 योजनांतर्गत Latha Koshi Nahar Purbi tola se Tirhut Chowk bypass PWD Sarak hote hue Sarahi Chowk tak पथ मरम्मत कार्य पूर्ण कर दिया गया है जिसमें कनीय अभियंता द्वारा मापी पुस्त संख्या 2903 में दर्ज सभी मदों की मापी जांच शत प्रतिशत की गई एवं सहायक अभियंता द्वारा 50 प्रतिशत की गई तथा कार्यपालक अभियंता के द्वारा 10 प्रतिशत मापी की जांच की गई जो गुणवत्ता पूर्ण एवं विशिष्टियों के अनुरूप है।


कनीय अभियंता


सहायक अभियंता


कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सहरसा।

RWD Works Division, Saharsa

Requisition Format for Scheme Head- MR (3054) Under Bihar Rural Road " New Maintenance Policy 2018" (Initial Rectification and Surface Renewal)

Name of Division:- Saharsa

S.N	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (A.A) Letter No. & Date	Administrative Approval (A.A)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI in MM/KM	Thickness of Bitumen Layer (in MM)	Value of Bitumen Content (in %)	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (K.M)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RN/SASAH/200006	Latha koshi nahar purbi tola se urhut chowk by pass PWD Sadak hote hue Sarahi chowk tak	29431033496	Letter no 472 dated 28.01.20	2.40	86.401	55.46343	22.91403	05/ MBP/MR/2020-21	16.08.2021	11.12.2022	2650	25	5.09	0	0	54.24209	Final Bill Comp.

Executive Engineer
RWD Works Division Saharsa

05/12/2022

Name of work : Latha koshi nahr purbi tola se trihut chowk bypass pwd sadak

Name of customer : M/S Krishna Construction

(R/Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMPI(cm)	Speed(Km/Hr)	Ull(mmm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
11/12/22	20:55:50	78	100	100	27.0 cm	7.0 Km/Hr	2700.0 mmm/Km	2610	3.56	Good	25.8825914	N	86.5688791	E	Normal
11/12/22	20:56:14	78	100	200	30.0 cm	15.0 Km/Hr	3000.0 mmm/Km	2890	3.9	Good	25.8821860	N	86.5694361	E	Normal
11/12/22	20:56:39	78	100	300	34.0 cm	14.5 Km/Hr	3400.0 mmm/Km	3264	4.34	Good	25.8616176	N	86.5693064	E	Normal
11/12/22	20:57:02	78	100	400	39.0 cm	15.4 Km/Hr	3900.0 mmm/Km	3731	4.89	Good	25.8803549	N	86.5691385	E	Normal
11/12/22	20:57:40	78	100	500	31.0 cm	9.5 Km/Hr	3100.0 mmm/Km	2984	4.01	Good	25.8792448	N	86.5690470	E	Normal
11/12/22	20:57:40	78	100	600	31.0 cm	9.5 Km/Hr	3100.0 mmm/Km	2984	4.01	Good	25.8792448	N	86.5690470	E	Normal
11/12/22	20:58:07	78	100	700	36.0 cm	13.0 Km/Hr	3600.0 mmm/Km	3451	4.57	Good	25.8784762	N	86.5689478	E	Normal
11/12/22	20:58:28	78	100	800	24.0 cm	17.0 Km/Hr	2400.0 mmm/Km	2330	3.21	Good	25.8777438	N	86.5689478	E	Normal
11/12/22	20:59:05	78	100	900	30.0 cm	9.6 Km/Hr	3000.0 mmm/Km	2890	3.9	Good	25.8776541	N	86.5698252	E	Normal
11/12/22	20:59:05	78	100	1000	30.0 cm	9.6 Km/Hr	3000.0 mmm/Km	2890	3.9	Good	25.8776541	N	86.5698252	E	Normal
11/12/22	20:59:20	78	100	1100	20.0 cm	23.1 Km/Hr	2000.0 mmm/Km	1956	2.75	Good	25.8778201	N	86.5705271	E	Normal
11/12/22	20:59:42	78	100	1200	25.0 cm	18.1 Km/Hr	2500.0 mmm/Km	2423	3.33	Good	25.8782645	N	86.5718088	E	Normal
11/12/22	21:00:02	78	100	1300	24.0 cm	16.7 Km/Hr	2400.0 mmm/Km	2330	3.21	Good	25.8786021	N	86.5727549	E	Normal
11/12/22	21:00:32	78	100	1400	29.0 cm	12.1 Km/Hr	2900.0 mmm/Km	2797	3.78	Good	25.8787528	N	86.5734568	E	Normal
11/12/22	21:00:46	78	100	1500	24.0 cm	24.6 Km/Hr	2400.0 mmm/Km	2330	3.21	Good	25.8788348	N	86.5745096	E	Normal
11/12/22	21:01:00	78	100	1600	23.0 cm	26.7 Km/Hr	2300.0 mmm/Km	2237	3.1	Good	25.8787680	N	86.574862	E	Normal
11/12/22	21:01:33	78	100	1700	28.0 cm	11.0 Km/Hr	2800.0 mmm/Km	2704	3.67	Good	25.8786879	N	86.5764170	E	Normal
11/12/22	21:01:47	78	100	1800	20.0 cm	23.4 Km/Hr	2000.0 mmm/Km	1956	2.75	Good	25.8786383	N	86.5776072	E	Normal
11/12/22	21:02:09	78	100	1900	25.0 cm	17.1 Km/Hr	2500.0 mmm/Km	2423	3.33	Good	25.8787070	N	86.5784388	E	Normal
11/12/22	21:02:09	78	100	2000	25.0 cm	17.1 Km/Hr	2500.0 mmm/Km	2423	3.33	Good	25.8787070	N	86.5784388	E	Normal
11/12/22	21:02:25	78	100	2100	20.0 cm	22.7 Km/Hr	2000.0 mmm/Km	1956	2.75	Good	25.8784762	N	86.5795603	E	Normal

11/12/22

11/12/22

16-12-2022

EXECUTIVE
Rural Work Division, Salem
meer

Name of work		: Latha koshi nahr purbi tola se trihut chowk bypass pwd sadak													
Name of customer		: M/S Krishna Construction													
		(R) Rural Road													
		Good		Average				Poor							
		< 4000		4001 - 5000				> 5000							
11/12/22	21:02:48	78	100	2200	26.0 cm	15.3 Km/Hr	2600.0 mm/Km	2517	3.44	Good	25.8783465	N	86.5805674	E	Normal
11/12/22	21:03:16	78	100	2300	20.0 cm	13.3 Km/Hr	2000.0 mm/Km	1956	2.75	Good	25.8782435	N	86.5817194	E	Normal
11/12/22	21:03:54	78	100	2400	15.0 cm	9.3 Km/Hr	1500.0 mm/Km	1489	2.16	Good	25.8781176	N	86.5827799	E	Normal

bi
11/12/2022
SE


11/12/22
A-E

11/12/22
16-12-2022

Executive Engineer
Rural Work Department
Saharsa
Works Division.

NTGraph ActiveX Control

Machine no: 19215 , Road: Latha koshi nahr purbi tola se trihut chowk bypass pwd sadak , Date: 15/12/22 , Section No:



11/12/2022

11/12/22
A.E.

15-12-2022

Executive Engineer
Rural Work Department
Works Division, Saharsa