



| Particulars                                                | Details of actual measurement |      |    |    | Contents of area |
|------------------------------------------------------------|-------------------------------|------|----|----|------------------|
|                                                            | No.                           | L.   | B. | D. |                  |
|                                                            |                               | 8.11 |    |    | 79271.0          |
| ⑤ cont. of Embankment with approved material vide TMBP-29, |                               |      |    |    |                  |
| Qty. 233.1 m <sup>3</sup> @ 35.14                          |                               |      |    |    | 8424.0           |
| ⑥ cont. of Embankment with approved material vide TMBP-30  |                               |      |    |    |                  |
| Qty lead 100m                                              |                               |      |    |    |                  |
| Qty. 4275.592 m <sup>3</sup> @ 190.07                      |                               |      |    |    | 812662.0         |
| b) lead 100m                                               |                               |      |    |    |                  |
| Qty. 1065.898 m <sup>3</sup> @ 152.05                      |                               |      |    |    | 162526.0         |
| ⑦ cont. of Granular sub base                               |                               |      |    |    |                  |
| vide TMBP-30,                                              |                               |      |    |    |                  |
| Qty. 1210.774 m <sup>3</sup> @ 2933.8                      |                               |      |    |    | 3552169.0        |
| ⑧ provide four spreads compact                             |                               |      |    |    |                  |
| 63 wide TMBP-30,                                           |                               |      |    |    |                  |
| Qty. 630.619 m <sup>3</sup> @ 3593.91                      |                               |      |    |    | 2266388.0        |
| ⑨ G.W in excavation for final dia                          |                               |      |    |    |                  |
| TMBP-229.682 m <sup>3</sup> @ 2790.9                       |                               |      |    |    | 64102.0          |
| ⑩ laying brick solar lamp on platform                      |                               |      |    |    |                  |
| bed wide TMBP-31,                                          |                               |      |    |    |                  |
| Qty. 97.51 m <sup>3</sup> @ 284.43                         |                               |      |    |    | 27741.0          |
| ⑪ provide concrete for plain/reinforced                    |                               |      |    |    |                  |
| concrete in open foundation vide                           |                               |      |    |    |                  |
| TMBP-31, Qty. 26.80 m <sup>3</sup> @ 6024.10               |                               |      |    |    | 161446.0         |
| ⑫ Brick masonry work in cm in foundation                   |                               |      |    |    |                  |
| for wide TMBP-31,                                          |                               |      |    |    |                  |
| Qty. 99.08 m <sup>3</sup> @ 5595.79                        |                               |      |    |    | 554431.0         |
|                                                            |                               |      |    |    | 7689163.0        |

Continuation

| Particulars                                                                                                   | Details of actual measurement |       |    |    | Contents of area |
|---------------------------------------------------------------------------------------------------------------|-------------------------------|-------|----|----|------------------|
|                                                                                                               | No.                           | L.    | B. | D. |                  |
|                                                                                                               |                               | B/F/P | —  | —  | 7689163.00       |
| (13) Brick masonry work in cm in sub structure vide TMBP-32                                                   |                               |       |    |    |                  |
| Qty 35.46 m <sup>3</sup> @ 5823.36                                                                            |                               |       |    |    | 206850.00        |
| (14) Plain/reinforced concrete in sub structure vide TMBP-32                                                  |                               |       |    |    |                  |
| Qty 9.72 m <sup>3</sup> @ 6558.59                                                                             |                               |       |    |    | 63749.00         |
| (15) Provide & lay reinforced concrete in super structure vide TMBP-32, Qty 4.62 m <sup>3</sup>               |                               |       |    |    |                  |
| @ 7538.81                                                                                                     |                               |       |    |    | 49907.00         |
| (16) Supply fifth & plain HYSD bar reinforcement vide TMBP-33                                                 |                               |       |    |    |                  |
| Qty 1.3 m <sup>3</sup> @ 50492.72                                                                             |                               |       |    |    | 65640.00         |
| (17) Brick masonry work in cm (1:3) in parapet vide TMBP-33                                                   |                               |       |    |    |                  |
| Qty 7.98 m <sup>3</sup> @ 5793.03                                                                             |                               |       |    |    | 46228.00         |
| (18) Plaster work in cm (1:4) 15 mm thick vide TMBP-33                                                        |                               |       |    |    |                  |
| Qty 154.36 m <sup>2</sup> @ 174.73                                                                            |                               |       |    |    | 26971.00         |
| (19) Provide concrete for plain/reinforced concrete in open foundation vide TMBP-32, Qty 49.02 m <sup>3</sup> |                               |       |    |    |                  |
| @ 5744.98                                                                                                     |                               |       |    |    | 281619.00        |
| (20) Provide concrete for plain/reinforced concrete in M20 vide TMBP-34                                       |                               |       |    |    |                  |
| Qty 5.22 m <sup>3</sup> @ 6354.670                                                                            |                               |       |    |    | 33171.00         |
|                                                                                                               |                               |       |    |    | 8463298.00       |

Continuation

| Particulars                               | Details of actual measurement |        |    |    | Contents of area |
|-------------------------------------------|-------------------------------|--------|----|----|------------------|
|                                           | No.                           | L.     | B. | D. |                  |
|                                           |                               | B/F 18 |    |    | 8463298.0        |
| (21) Back fill behind Alt. wing wall      |                               |        |    |    |                  |
| R. wall inside TMBP-34                    |                               |        |    |    |                  |
| Qty. 146.64m <sup>3</sup> @ 700.83        |                               |        |    |    | 102792.0         |
| (22) provide weep hole in back            |                               |        |    |    |                  |
| work with TMBP-34                         |                               |        |    |    |                  |
| Qty 64 Nos. @ 110.25                      |                               |        |    |    | 7056.0           |
| (23) provide 3 lay RCC HP, 1000mm         |                               |        |    |    |                  |
| dia. H.P. inside TMBP-35                  |                               |        |    |    |                  |
| Qty. 15.0 Nos @ 3599.43                   |                               |        |    |    | 53991.0          |
| (24) provide guide post with              |                               |        |    |    |                  |
| TMBP-35, Qty. 16.0 Nos                    |                               |        |    |    |                  |
| @ 511.54                                  |                               |        |    |    | 8185.0           |
| (25) Dismantling of existing Str          |                               |        |    |    |                  |
| inside TMBP-36, Qty. 1.06m <sup>3</sup>   |                               |        |    |    |                  |
| @ 487.17                                  |                               |        |    |    | 516.0            |
| (26) Dismantling of RCC Str               |                               |        |    |    |                  |
| inside TMBP-36, Qty. 5.04m <sup>3</sup>   |                               |        |    |    |                  |
| @ 1208.45                                 |                               |        |    |    | 6090.0           |
| (27) Dismantling of Rubble masonry        |                               |        |    |    |                  |
| inside TMBP-36, Qty. 66.825m <sup>3</sup> |                               |        |    |    |                  |
| @ 347.62                                  |                               |        |    |    | 23230.0          |
| (28) Remove all top of H.P. inside        |                               |        |    |    |                  |
| TMBP-36, Qty. 5.0m <sup>3</sup> @ 181.13  |                               |        |    |    | 905.0            |
| (29) provide 3 appl. Primer coat          |                               |        |    |    |                  |
| SS-1 inside TMBP-37,                      |                               |        |    |    |                  |
| Qty. 8408.25m <sup>2</sup> @ 40.45        |                               |        |    |    | 340114.0         |
|                                           |                               |        |    |    | 9006157.0        |

Continuation

| Particulars                         | Details of actual measurement |       |    |    | Contents of area |
|-------------------------------------|-------------------------------|-------|----|----|------------------|
|                                     | No.                           | L.    | B. | D. |                  |
|                                     |                               | B/F/R | —  | —  | 9066157.~        |
| 30) provide & apply tack coat       |                               |       |    |    |                  |
| R3-1 view TMBP-37                   |                               |       |    |    |                  |
| Qty. 8408.25m <sup>2</sup> @ 13.82  |                               |       |    | —  | 116286.~         |
| 31) provide down and rolling of     |                               |       |    |    |                  |
| closed graded premix view           |                               |       |    |    |                  |
| TMBP-37, Qty. 8408.25m <sup>2</sup> |                               |       |    |    |                  |
| @ 197.79                            |                               |       | —  | —  | 1663068.~        |
| 32) RCC mis grade kilometer         |                               |       |    |    |                  |
| Stone view TMBP-37                  |                               |       |    |    |                  |
| Qty. 3.0 Nos @ 2317.5               |                               |       |    | —  | 6952.~           |
| 33) provide RCC mis grade           |                               |       |    |    |                  |
| 200m stone view TMBP-37             |                               |       |    |    |                  |
| Qty. 9.0 Nos @ 623.05               |                               |       |    | —  | 5607.~           |
| 34) provide RCC mis grade           |                               |       |    |    |                  |
| boundary pillar view TMBP-38        |                               |       |    |    |                  |
| Qty. 33.0 Nos @ 511.59              |                               |       |    | —  | 16882.~          |
| 35) provide & fix masonry           |                               |       |    |    |                  |
| beam view TMBP-38                   |                               |       |    |    |                  |
| Qty. 2.0 Nos @ 10732.17             |                               |       |    | —  | 21464.~          |
| 36) provide & fix of mainte         |                               |       |    |    |                  |
| nance beam view TMBP-38             |                               |       |    |    |                  |
| Qty. 1.0 Nos @ 10732.17             |                               |       |    | —  | 10732.~          |
| 37) provide & fix of masonry        |                               |       |    |    |                  |
| beam view TMBP-38, Qty. 1.0 Nos     |                               |       |    |    |                  |
| @ 10732.17                          |                               |       | —  | —  | 10732.~          |
|                                     |                               |       |    |    | 10857880.~       |

Continuation

| Particulars                        | Details of actual measurement |       |    |     | Contents of area |
|------------------------------------|-------------------------------|-------|----|-----|------------------|
|                                    | No.                           | L.    | B. | D.  |                  |
|                                    |                               | B/F/P |    |     | 10857880.0       |
| 38) provide & fix 600mm            |                               |       |    |     |                  |
| equilateral triangle wide TMBP-38  |                               |       |    |     |                  |
| Qty. 6.0 nos. @ 3456.95            |                               |       |    |     | 20982.0          |
| 39) provide & fix of 600mm         |                               |       |    |     |                  |
| circular wide TMBP-39              |                               |       |    |     |                  |
| Qty. 2.0 nos. @ 4665.49            |                               |       |    |     | 9331.0           |
| 40) provide & fix of 600 X 450mm   |                               |       |    |     |                  |
| rectangular wide TMBP-39           |                               |       |    |     |                  |
| Qty. 4.0 nos. @ 4618.67            |                               |       |    |     | 18425.0          |
| 41) provide & fix hot applied      |                               |       |    |     |                  |
| thermoelastic wide TMBP-39         |                               |       |    |     |                  |
| Qty. 444.6m <sup>2</sup> @ 721.950 |                               |       |    |     | 320545.0         |
| 42) provide & fix strip wide       |                               |       |    |     |                  |
| TMBP-40, Qty. 78.75m <sup>2</sup>  |                               |       |    |     |                  |
| @ 197.79                           |                               |       |    |     | 15576.0          |
| 43) plenty of free & flow maintain |                               |       |    |     |                  |
| wide TMBP-40,                      |                               |       |    |     |                  |
| Qty. 111.0 nos. @ 844.09           |                               |       |    |     | 93694.0          |
|                                    |                               |       |    |     | 11336483.0       |
| Add 1% L.C.                        |                               |       |    | (+) | 113365.0         |
| Add 12% G.S.T                      |                               |       |    | (+) | 1360378.0        |
| Add 10% Begun fee                  |                               |       |    | (+) | 190110.0         |
|                                    |                               |       |    |     | 13000336.0       |
| less 15.12% below                  |                               |       |    | (-) | 1965651.0        |
|                                    |                               |       |    |     | 11034685.0       |
| less previous bill amount          |                               |       |    | (-) | 5833818.0        |
|                                    |                               |       |    |     | 5200867.0        |

11/5/22  
JE

Continuation

Liability Rs 2912486.00  
14/5/22