

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बेनीपट्टी।

पत्रांक...११३३३३

दिनांक...०८/०१/२२

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी -सह- सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय:-

शीर्ष **NEW MAINTENANCE POLICY - 2018 (MR - 3054)** में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है शीर्ष **NEW MAINTENANCE POLICY - 2018 (MR - 3054)** अन्तर्गत पथ में संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय ताक संवेदक का भुगतान किया जा सके।

अनु०:-

1. अधियाचना प्रमाण पत्र 1 पृष्ठ में।
2. उपयोगिता प्रमाण पत्र एक प्रति।

विश्वासभाजन

अ.प. ११३३
८-१-२२

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

०८/०१/२२

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilisation Certificate Upto the month of 31December2021

New Maintenance policy - 2018

PIU – Executive Engineer, R.W.D (W) Division, Benipatti

SL. No	Name of Gen.heme	Sanction No. & Date with Amount (In Rs. lacs)	Amount Received (In Rs. lacs)	Particulars
1	Construction of Rural roads under New maintenance policy - 2018	Authorization letter No.52 wedt- 24.08.2021 Rs.15.53935	719.84686	Certified that out of Rs.719.84686 Lakh received during the years up to 2021-22 (31December 2021) in favour of Ex. Engineer, RWD (W) Division Benipatti, Madhubani, Bihar, a sum of Rs.719.02338 Lakh has been utilized for the purpose of New maintenance policy-2018 as given in the margin for which the balance of Rs0.82348 Lakh remaining unutilized at the end of the period under.

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised :-

- I. Works have been supervised by Executive Engineer/Superintending Engineer.
- II. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- III. Construction materials have been tested.
- IV. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.

3. Physical Progress achieved:-

- I. Construction of Road Works.
- II. Construction of CD Works.


Sr. D.A.O. 7/01/2022
R.W.D (W) Division
BenipattiBenipatti


Executive Engineer
R.W.D (W) Division


Formate of Requisition under Head New Maintenance policy - 2018 (MR- 3054) for the month of December - 2021

Name of Division :- Benipatti

Sl No.	Package No.	Name of road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date		Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lakh)	up-to-date expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
				Length (In km)	Amount of (in lakh)	Initial Rectification with Surface Renewal (In Lakh)	5 Year Routine Maintenance (In Lakh)												
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	MR-N/19-20 Benipatti/02	Bankatta to Ganguli	31910002018	1859 24.06.2019	2.510	81.39990	51.55049	20.86945	71MBD/19-20 25.01.2020	24.01.2021	—	2630	25	5	44.65771	44.65771	4.52156	BT Work Completed	
		Uchaith - Sohraul	31910002084	1859 24.06.2019	4.200	133.05540	88.63191	33.06953	71MBD/19-20 25.01.2020	24.01.2021	—	3050	25	5	76.47929	76.47929	8.68848	BT Work Completed	
2		Total																	
					6.710	214.455	140.18240	53.93898	—	—	—	5680	50	10	121.13700	121.13700	13.21004		

R. W. D. (W) Div. Benipatti
Sr. D.A.O.
R.W.D(W)Div. Benipatti
11/12/2022

R. W. D. (W) Div. Benipatti
Executive Engineer
R.W.D(W)Div. Benipatti
07/10/22

2nd on A/c Bill

6

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/H:- Rural Road Contract for					
the maint. of Road from					
Uchaith to Sahraul					
Agency:- Sri Gobind Jha					
Ag. No. 71 HBD/19-20					
D.O.S 25-01-2020					
D.O.C 24-01-2021					

Record Entry.

- ① Construction of subgrade & E. shoulder
all comp job --- SDETS

$$2 \times 30 \times 100 \times \frac{0.90 + 0.80}{2} \times 0.30 = 1530.00$$

$$2 \times 2 \times 100 \times \frac{1.1 + 1.20}{2} \times 0.30 = 138.00$$

$$2 \times 2 \times 50 \times \frac{1.50 + 1.10}{2} \times 0.60 = 156.00$$

$$2 \times 5 \times 100 \times \frac{1.30 + 1.40}{2} \times 0.30 = 405.00$$

$$2229.00$$

limit to 2025.00 M³

- ② PIF KM Post --- all comp
job --- SDETS

5 Nos.

- ③ PIF 200 H Post --- all comp --- ETS
17 Nos.

- ④ PIF direction & Place identification
all comp --- ETS

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of Cost.</u>					
① Clearing & grubbing Rd land					
QVTHB P-1	1.05	Heet			
@ Rs 49946.70					52444.00
② P/L GSB					
QVTHB P-1	39.375	m ³			
@ Rs 3191.64					125671.00
③ P/L WBM gr-II					
QVTHB P-2	43.79	m ³			
@ Rs 3951.78					173048.00
④ P/A Primer Coat					
QVTHB P-2	589.70	m ²			
@ Rs 41.22					24307.00
⑤ Patch work over WBM					
QVTHB P-2	6363.00	m ²			
@ Rs 211.60					1346411.00
⑥ P/A tack Coat					
QVTHB P-3	22270.50	m ²			
@ Rs 13.98					311342.00
⑦ P/L SDBC 25 mm Thick					
QVTHB P-3	397.69	m ³			
@ Rs 10625.96					4225838.00
⑧ Const. of subgrade & E. shoulder					
QVTHB P-6	2025.00	m ³			
@ Rs 176.75					357919.00
⑨ P/F KM Post					
QVTHB P-6	5	Nos			
@ Rs 2355.34					11777.00

Continuation

Continuation

10
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑭ Road marking with hot applied thermoplastic					
8VTMB P-7		770.00			
②	735.40				566258.00
					7540956.00
Add 12% GST					904899.00
Add 1% L.C.					75408.00
					8521055.00
Less 0.05% Below					4261.00
					8516794.00
Less forer pay					7068686.00
					1448108.00

Insdri

25/05/21

J.E.

up to date Matt. stamp

Same as vide TMB P-5

Insdri

25/05/21

J.E.

Quality control Report should be collected by office from The Agency.

Insdri

25/05/21

J.E.

