

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-2

पत्रांक: 81 अनु०
प्रेषक,

मुज०/दिनांक: 13-01-2022

सेवा में,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल मुजफ्फरपुर, पूर्वी-2

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
बिहार, पटना।

विषय: बिहार ग्रामीण पथ अनुरक्षण नीति- 2018 के तहत स्वीकृत योजनाओं के विरुद्ध आवंटन की माँग करने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में वित्तीय वर्ष 2019-20 नई अनुरक्षण नीति अंतर्गत वित्तीय वर्ष 2020-21 में अनुरक्षण मद में व्यय हेतु संलग्न विवरणी के अनुसार 6.88325 (छः लाख अठासी हजार तीन सौ पच्चीस रुपया मात्र) रुपये का आवंटन उपलब्ध कराने की कृपा की जाये ताकि किये गये अनुरक्षण कार्यों का भुगतान किया जा सके।

अनु०:- यथोक्त।

विश्वासभाजन



कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
मुजफ्फरपुर पूर्वी-2

FORM GFR 19-A

Form of utilisation Certification up to month of Dec-2021

MR3054(CFMS)

RWD ,Works Division, Muzaffarpur East-II

SL. NO.	Name of Scheme	Sanction No & Date with Amount (In Rs.)	Amount Received (In Rs.)	Particulars
1.	Construction of Rural Road under MR3054 (CFMS)	Secretary cum Empowered officer B.R.R.D.A Letter No.- Dated	Opening Balance- Rs. 33,40,91,008.00	Certified that out of Rs. 33,40,91,008.00 of grant in aid received during the Year 2021-2022 in favour of Executive Engineer R.W.D. Works Division, Muzaffarpur East-II. A sum of Rs. 32,90,98,891.00 has been utilized for the purpose of MR3054 (CFMS) schemes as given in the margin for which it was sanctioned and that the balance of Rs. 49,92,117.00 remaining unutilized at the end of the period under.
			Rs. + 0.00	
			Rs. 33,40,91,008.00 Rs. - 32,90,98,891.00 Rs. 49,92,117.00	
		Total	Rs. 33,40,91,008.00	

2. Certified that I have satisfied that the conditions on which the grants-in aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- I. Works have been supervised by Executive Engineer/ Superintending Engineer.
- II. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- III. Construction material has been tested.
- IV. Measurements have been recorded in the MBS and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.

3. Physical progress achieved:

- i. Construction of Road Works.
- ii. Construction of CD Works.


 Executive Engineer
 RWD, Works Division
 Muzaffarpur East-2

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-2

प्रमाण-पत्र

प्रमाणित किया जाता है कि सभी अवयवों की जाँच शत प्रतिशत कनीय अभियंता द्वारा किया गया है। सहायक अभियंता, द्वारा सभी अवयवों की 50 प्रतिशत से अधिक जाँच किया गया है। अधोहस्ताक्षरी द्वारा 10 प्रतिशत अवयवों की जाँच की गई है।

(Signature) 13/1/22
कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल
मुजफ्फरपुर पूर्वी-2

(Signature) 13/01/22
A. E. minpur
(Signature) 13.1.2022
A. E. Kutra.

(Signature)
13/1/22
JE


Requisition Format for Scheme IIend - MIR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Department of Works Division :- Muzaffarpur East-II

S.N.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	RM/MU/M UZ20/0008	Junia kata Monraje Road	31507203003	6486/13-12-2019	10.00	372.9000	240.95700	75.34416	MIR/MBD-09/2020-21	22/03/2021	Ongoing	2640.53	25	5.020	235.00000	235.00000	4.70696	surface completed
2	RM/MU/M UZ20/0009	Zamin Marbia main road - Pakmaha Mahesh	31507302018	6486/13-12-2019	1.28	38.5197	24.19200	11.78866	MIR/MBD-13/2020-21	14/04/2021	Ongoing	2443.231	25	5.020	23.95500	23.95500	0.14967	surface completed
3	RM/MU/M UZ20/09	Improvement of Baria Moujpur N.H. to prasad Village Road	31507201003	6486/13-12-2019	3.85	125.1020	81.39100	35.3173	MIR/MBD-13/2020-21	14/04/2021	Ongoing	2474.514	25	5.020	80.55000	80.55000	0.45293	surface completed
4	RM/MU/M UZ20/0009	PANAPUR NH28 - PANAPUR	NEA220002521	6486/13-12-2019	1.23	39.8780	25.90500	27.4293	MIR/MBD-13/2020-21	14/04/2021	Ongoing	2202.917	25	5.020	24.85000	24.85000	0.95220	surface completed
5	RM/MU/M UZ20/0010	Baigra Lakhanpur path to Janjaur Bari pokhar Durga Mandir	315731000000	6486/13-12-2019	1.90	135.9330	96.84500	15.06218	MIR/MBD-14/2020-21	14-04-2021	Ongoing	1498.43	25	5.020	68.95000	68.95000	0.62149	Length- 0.585 km Surface Completed By MNCSTY Geo and Length 1.315 km Surface Completed by MIR3054
																	6.88325	

Executive Engineer
RWD Works Division
Muzaffarpur East-II

File :C:\Users\DELL\Downloads\07051426.xls. Section No. :51, Eqn : $Y = 0 \cdot X^2 + 0.989 \cdot X - 13.58$
Name of Customer :Vijay Kumar Rushan, Name of Work/ Road :Bairia Motipur NH to Prasad Village Road. Lab Job



Jan 11

Road Name:-Bairia Motipur NH to Prasad Village Road

Date	Time	Section No.	Length In km	Bumps In mm	Speed Rate	IRI In MM/KM	UIV	ROAD CATEG	ORY	Latitude	Longitu de	Event
7/5/21	14:14:0	51	0.1	220	0	2200	2162 G	ROAD		26.25254	85.28099	Normal
7/5/21	14:14:29	51	0.1	130	30.3	1300	1272 G			26.25229	85.28192	Normal
7/5/21	14:14:29	51	0.1	170	30.3	1700	1667 G			26.252	85.28293	Normal
7/5/21	14:15:4	51	0.1	310	10.1	3100	3052 G			26.25172	85.28392	Curve
7/5/21	14:15:4	51	0.1	210	20.2	2100	2063 G			26.25087	85.28387	Normal
7/5/21	14:15:40	51	0.1	170	20.2	1700	1667 G			26.24997	85.28372	Normal
7/5/21	14:16:0	51	0.1	230	20.2	2300	2261 G			26.24923	85.28419	Culvert
7/5/21	14:16:15	51	0.1	280	20.2	2800	2755 G			26.24838	85.28389	Normal
7/5/21	14:16:15	51	0.1	250	30.3	2500	2458 G			26.24745	85.28399	Normal
7/5/21	14:16:15	51	0.1	140	20.2	1400	1371 G			26.24706	85.28488	Normal
7/5/21	14:16:50	51	0.1	160	20.2	1600	1568 G			26.24643	85.28532	Normal
7/5/21	14:17:0	51	0.1	220	30.3	2200	2162 G			26.24551	85.28517	Normal
7/5/21	14:17:0	51	0.1	210	30.3	2100	2063 G			26.24466	85.28535	Normal
7/5/21	14:17:25	51	0.1	220	30.3	2200	2162 G			26.24391	85.28603	Culvert
7/5/21	14:17:25	51	0.1	260	20.2	2600	2557 G			26.24311	85.28653	Normal
7/5/21	14:17:25	51	0.1	270	30.3	2700	2656 G			26.24228	85.28694	Normal
7/5/21	14:18:0	51	0.1	320	20.2	3200	3151 G			26.2414	85.28702	Normal
7/5/21	14:18:0	51	0.1	360	20.2	3600	3546 G			26.24074	85.28763	Normal
7/5/21	14:18:0	51	0.1	200	30.3	2000	1964 G			26.24003	85.28827	Normal
7/5/21	14:18:35	51	0.1	270	30.3	2700	2656 G			26.23921	85.28845	Normal
7/5/21	14:18:35	51	0.1	220	30.3	2200	2162 G			26.23825	85.2884	Normal
7/5/21	14:19:0	51	0.1	330	30.3	3300	3250 G			26.23736	85.28822	Normal
7/5/21	14:19:10	51	0.1	260	20.2	2600	2557 G			26.23645	85.28793	Normal
7/5/21	14:19:46	51	0.1	240	30.3	2400	2360 G			26.23562	85.28759	Normal
7/5/21	14:19:46	51	0.1	200	30.3	2000	1964 G			26.23475	85.28734	Normal
7/5/21	14:19:46	51	0.1	390	30.3	3900	3843 G			26.23385	85.28712	Normal
7/5/21	14:20:0	51	0.1	270	30.3	2700	2656 G			26.23333	85.28653	Normal
7/5/21	14:20:0	51	0.1	230	30.3	2300	2261 G			26.23247	85.28606	Normal
7/5/21	14:20:21	51	0.1	240	30.3	2400	2360 G			26.23161	85.28577	Normal
7/5/21	14:20:21	51	0.1	310	30.3	3100	3052 G			26.23074	85.28544	Normal
7/5/21	14:20:21	51	0.1	350	30.3	3500	3447 G			26.22995	85.28498	Normal
7/5/21	14:21:0	51	0.1	300	20.2	3000	2953 G			26.22913	85.28446	Culvert

$$Y = 0 * X^2 + 0.929 * X - 13.58$$

$$X = 5000$$

$$Y = 4931$$

(R) RURAL ROAD
Good Average PCCR
<4000 4001-5000 >5001

7/5/21	14:21:0	51	0.1	280	30.3	2800	2755 G	26.22223	85.22429 Normal
7/5/21	14:21:0	51	0.1	310	20.2	3100	3052 G	26.22274	85.22395 Normal
7/5/21	14:21:32	51	0.1	260	20.2	2600	2557 G	26.22651	85.22359 Normal
7/5/21	14:22:0	51	0.1	320	20.2	3200	3151 G	26.22558	85.22332 Speed Breaker
7/5/21	14:22:7	51	0.1	200	20.2	2000	1964 G	26.22477	85.22303 Normal
Average:-						2474.514			


 5/11/21
 B. D.