



कार्यपालक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य प्रमंडल मुंगेर



पत्रांक- 473/22
मो0-8986915296

दिनांक- 19/01/2022
ई मेल - ee.reomunger@gmail.com

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मुंगेर।

सेवा में,

नोडल पदाधिकारी,
नई अनुरक्षण नीति 2018" (3054-MR)
ग्रामीण कार्य विभाग, बिहार पटना।

विषय :- शीर्ष MR(3054) "नई अनुरक्षण नीति 2018" योजनान्तर्गत पथ के निर्माण में
संवेदक के विपत्र भुगतान हेतु राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि शीर्ष MR(3054) "नई अनुरक्षण
नीति 2018" योजनान्तर्गत पथ:-

1. Indurab Purvi Panchayat Me Gauripur Me Bajragwali Asthan Se Shiv
Mandir Hote Hue Rajput Tola Tak Path Maramati का Surface कार्य पूर्ण
हो चुका है। इस कार्य के भुगतान हेतु आवंटन की अधियाचना विहित प्रपत्र में
भर कर की जाती है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु0:-यथोक्त।

विश्वासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल मुंगेर

19/01/2022

19/01/2022

Requisition Formate for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Munger

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA)	Agreement Amount (In Lakh)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks			
																Administrative Approval (AA)	Initial Rectification with Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RMM/MLN/20/0003	Indurbh Puri Panchayat Me Gaurpur Me Bajraywahi Ashdan Se Shiv Mandir Hole Hinc Rajpur Tola Tak Patil Maranatu	28371034842	662/ 10.02.2020	0.63	24.078	16.587	4.20635	36 MLBD/20-21	28-Aug-21		3492	25.00	5.00	0.00000	0.00000	13.45809	Surface Complete

Total = 13.45809

- 1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MIS.

Executive Engineer
RWD, Works Division, Munger

16/10/22
16/11/2022

FORM GFR 19-A

(See Government of India,s Decision (I) below Rule-150)
From of Utilization Certificate upto the Month of Jan-2022
(RURAL ROAD MAINTENANCE POLICY 2018 UNDER MR-3054)

PIU - Munger

Sl.No.	Name of Scheme	Sanction No. & Date with Amount (in lacs Rs.) T/S	Amount Received (In lacs Rs.)	Particulars
1	Rural road Maintenance Policy 2018 Under MR-3054	B.R.R.D.A - Patna Letter No. 02 (En), dt. 03.01 2022	8,15,44,396 00	A Sum of Rs. 8,15,44,396.00/- is allotted for this Div under this Head out of which After expenditure up to Jan.-2022 the closing Balance is Rs. 8,15,44,396/- and Expenditure is Rs. 7,54,30,876 /- till yet. Allotment up to 17.01.2022 Rs 8,15,44,396.00/- Expenditure up to 17.01.2022 (-)Rs7,54,30,876 /- Balance Rs. 61,13,520/-
	Total :-		8,15,44,396.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised :-


- Work have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection lhas ;been conducted by Executive Engineer / Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant
- All other codal formalities have been observed.

3. Physical Progress achieved :-

- Construction of Road Works.
- Construction of CD works


D.A.O
R.W.D.Works Division,
Munger


E.E
R.W.D.Works Division,
Munger


19/10/2022

**Name of Work - Indurab Purvi Panchayat Me Gauripur Me Bajragwali Asthan Se Shiv
Mandir Hote Hue Rajput Tola Tak Path Maramati**

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
14/ 1/ 22	14: 32: 13	39	0.1	280	10.1	2800	3449	G	25.55627	86.26078	Normal
14/ 1/ 22	14: 33: 24	39	0.1	230	10.1	2300	3017	G	25.55628	86.26071	Normal
14/ 1/ 22	14: 33: 59	39	0.1	320	10.1	3200	4026	A	25.55629	86.26079	Culvert
14/ 1/ 22	14: 34: 34	39	0.1	250	10.1	2500	3380	G	25.55621	86.2608	Normal
14/ 1/ 22	14: 35: 10	39	0.1	320	10.1	3200	4098	A	25.55625	86.26077	Curve
14/ 1/ 22	14: 35: 45	39	0.1	230	10.1	2300	3289	G	25.55765	86.27156	Normal
14/ 1/ 22	14: 36: 20	39	0.1	210	20.2	2100	3190	G	25.55764	86.27157	Normal

$$Y = 0 * X^2 + 1.021 * X + -31.77$$

$$X = 0$$

$$Y = -32$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001


Executive Engineer
RWD Works Division
Munger


12/01/2022


Customer: M/S Shanti Constructions Prop
Name of Work/Road: Indurab Purvi Panchayat Me G.
Lab Job number: 39
Date: 14-01-2022
Section No.: 39

Test Date: 14-01-2022 Road Name: Indurab Purvi Panchayat Me G.
Machine No: 385 Road Type: (R) RURAL ROAD
Start S No.: Side:
Start E No.: Interval
Weather: UIV Range: 2017 To 5000 1000 mm/km
Start Location: Dist Range: 0 To 0.8 0.1 = 1000 m
End Location: Equation: $Y = 0 \cdot X^2 + 1.021 \cdot X + -31.77$

Print Generate Report and Graph

Redraw Graph

Map View



Executive Engineer
RWD Works Division Munger
15/01/2022