

कार्यपालक अभियंता, ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 131 अडु

दलसिंहसराय/दिनांक 25/01/2022

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय-


New Maintenance Policy 2018(MR New) योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।

महोदय,

उपरोक्त विषय के संबंध में कहना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान हेतु **Rs.-37.81262(Thirty Seven Lakh Eighty One Thousand Two Hundred Sixty Two Rupees)** की आवश्यकता है। अधियाचना का निर्माण कार्य विशिष्टों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-37.81262(Thirty Seven Lakh Eighty One Thousand Two Hundred Sixty Two Rupees)** उपलब्ध कराने की कृपा की जाये।

- अनु०- 1) अधियाचना प्रपत्र।
2) 19 ए फॉर्म।
3) IRI Report की छायाप्रति सलग्न।

विश्वासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Division : PLK(Dalsinghsarai)

Sl No	Package no	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA) Length (in Km)	Administrative Approval (AA) Amount (in Lac)	Agreement Amount (in Lac)	5 years Maintenance (in Lac)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RI (in million)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content (in percent)	Previous Total Allotted Amount (in Lac)	up to date expenditure as per MIS (in Lac)	Requisition against work done (in Lac)	Remarks
1	3	Santipur jila santipur moyna pakhanda me kahi anban vandodori mithi ke ghari hote huan shivchandra sub ke dahan PMGSY tak path banan	32010403009		0.690	21.26390	9.36400	4.09392				3764	25mm	5.10%	9.39500	9.29001	0.00000	
2		Santipur jila santipur moyna pakhanda ke gram panchayat indrawan ke prebanasari sadak madhy chok se vai shivji subai ke ghari huan sun nahi ghar anban tak sadak banan	32010403010		0.570	18.44820	8.29300	3.36880				3729	25mm	5.10%	8.29300	8.20242	0.00000	
3		Chandauli Hasi Se Morigpur Village me Rono Sadak Tak	10165100	2200	1.800	57.50880	34.22700	13.79239	27.02.2020	16.09.2020		3508	25mm	5.10%	23.38160	23.38160	9.61568	
4		Gumai Bhasi Ward-1 Se Ward No-2 Tak	10165101	08.07.2019	1.250	42.07280	25.38200	9.50617				3611	25mm	5.10%	0.00000	0.00000	21.73029	
5		Belapur Mahadevi Basi Se Shalish Baha Sehan se RKO Path Tak	10165104		0.500	15.62720	9.90100	2.83012				-	-	-	0.00000	0.00000	0.00000	
6		SH Prati Path Se Palaspur Hase Hase Bagipur Chok Tak	10165106		1.700	61.09960	36.44300	14.43161				2744	25mm	5.10%	18.22150	33.67585	0.00000	
7		SUST Path se Rai Tola Tak	10165108		0.750	29.83630	18.86800	5.99173				-	-	-	0.00000	0.00000	0.00000	
8		PWD Sadak Se Chandauli APHC Mandir Tak	10165116		1.000	29.67960	19.20500	5.64539				3370	25mm	5.10%	12.25000	12.25000	6.46665	
					3.060	97.22090	51.915	21.255							41.06960	40.87403	37.81262	

1. Signed Hard Copy and Soft Copy (in Excel) of recorded RI is enclosed.
2. Up-to date Physical Progress has been uploaded in MIS.

[Signature]
 Sr. Divisional Account Officer,
 Rural Works Department,
 Works Division Dalsinghsarai

[Signature]
 Executive Engineer,
 Rural Works Department,
 Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)
Form of Utilisation Certificate upto JANUARY 2022

New Maintenance Policy 2018(MR New)

PIU:- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	1787.50405	1787.50405	Certified that out of Rs-1787.50405 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-1777.88419 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margin for which it was Sanctioned and that the Balance of Rs-9.61986 Lakh remaining unutilized at the end of period under the time of completion
		1787.50405	1787.50405	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was


Kind of Checks Exercised:-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurements have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have observed

3. Physical Progress Achieved



- (i) Construction of Road Works
- (ii) Construction of CD Works


Sr.DAO
Rural Works Department,
Works Division Dalsinghsarai


Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल दलसिंहसराय
नयी अनुरक्षण नीति 2018 के अधियाचना हेतु प्रमाण पत्र

क्र० स०	शर्त	अभियुक्ति
1	मापि पुस्त पर इस आशय का प्रमाण पत्र दर्ज है कि कार्य गुणवत्ता पूर्ण कराया गया है एवं विशिष्टियों के अनुरूप है ।	PWD Sadak to Chanduali APHC Mandir Tak पथ का निर्माण कार्य गुणवत्ता पूर्ण कराया गया है एवं विशिष्टियों के अनुरूप है ।
2	कराये गए कार्यों के सभी अवयवों के अवयववार 100 प्रतिशत कार्य का दर्ज मापी का सत्यापन कनीय अभियंता, कम से कम 50 प्रतिशत मापी का सत्यापन सहायक अभियंता एवं कम से कम 10 प्रतिशत मापी का सत्यापन कार्यपालक अभियंता द्वारा किये जाने का प्रमाण पत्र को विभागीय MIS पर अपलोड जाय ।	PWD Sadak to Chanduali APHC Mandir Tak पथ का कराये गए कार्यों के सभी अवयवों के अवयववार मापी का सत्यापन कनीय अभियंता, सहायक अभियंता एवं कार्यपालक अभियंता द्वारा किया गया है ।

 कनीय अभियंता ग्रामीण कार्य विभाग, कार्य प्रमंडल दलसिंहसराय	 सहायक अभियंता ग्रामीण कार्य विभाग, कार्य प्रमंडल दलसिंहसराय	 कार्यपालक अभियंता ग्रामीण कार्य विभाग, कार्य प्रमंडल दलसिंहसराय
---	--	--

मापीपुस्तक 1354/2019-2020
Schedule XLV-Form No. 134
PWD सड़क से चन्दौली APHC मंदिर तक।

मुरादाबाद जिला DIVISION

सीतावा SUB-DIVISION

MEASUREMENT BOOK

निवेदन: रजिस्ट्रार इन्सुलेशन 5/10/20

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	

ABSTRACT OF COST

(1/1) Clearing and grubbing of
road land —

Qty vide P.No-(9) of T.M.B.

0.20 Hec @ 49496.70

= 9899.34

(2/2) Box cutting —

Qty vide P.No-(10) of T.M.B.

236.26 m² @ 0.00

= 0.00

(3/3) Const. of GSB by well
graded material —

Qty vide P.No-(10) of T.M.B.

157.50 m² @ 1869.87

= 294505.00

(4/4) P.V. Laying, spreading and
comp. Gr-III 1:1.25 —

Qty vide P.No-(10) of T.M.B.

56.25 m² @ 3034.24


= 170676.00

(5/5) P.V. & applying prime
coat SS-1 —

Continuation

Continuation

File : C:\My\master\18.10.2021\10101215.Xls. Section No. : 64. Egn : $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$
Name of Customer : RATNESH CONSTRUCTION PVT LTD. Name of Work/ Road : PWD Sadak Se Chandauli APHC



Handwritten signature and text:
Ratnesh
10/10/2021
Ratnesh

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event			
10/10/21	11:12:28	64	0.1	320	10.1	3200	3400	G	25.815197	85.659225	Normal	$Y = 0 * X^2 + 1.136 * X + 132.5$		
10/10/21	11:13:3	64	0.1	340	10.1	3400	3600	G	25.814282	85.659007	Normal	$Y = 2404$		
10/10/21	11:13:3	64	0.1	280	10.1	2800	3200	G	25.813462	85.65867	Normal			
10/10/21	11:14:0	64	0.1	260	10.1	2600	2900	G	25.813172	85.657777	Normal			
10/10/21	11:14:14	64	0.1	310	20.2	3100	3400	G	25.81327	85.65678	Curve	(R) RURAL ROAD		
10/10/21	11:14:14	64	0.1	350	20.2	3500	3700	G	25.81321	85.655842	Curve	Good	Average	Poor
10/10/21	11:15:0	64	0.1	360	10.1	3600	3900	G	25.813753	85.655252	Normal	<4000	4001-5000	>5001
10/10/21	11:15:23	64	0.1	310	10.1	3100	3400	G	25.81462	85.654998	Normal			
10/10/21	11:15:23	64	0.1	360	10.1	3600	3800	G	25.81546	85.654797	Normal			
10/10/21	11:16:0	64	0.1	200	10.1	2000	2404	G	25.81638	85.654662	Normal			

Dr. Ravi Kumar
10/10/21
11:16:0