

Inspection Report for Flood Damage Report

Date :

1 Name of PIUs

- EE, RUD, wares division, mahar

2 Name of Block/ Road

- Sadiya / SH-74 Beispang Rayker ghar
se chauri chauri to Pachin Akhach
matid talu

A. For Road

1 Damage Location/Chainage

: At ch, 1.240 km, & 1.546 km

2 Damage Length

: 160 mtr

3 Nature of Damage

: Complete lane blocked due to Flood
flood water (Breach of road)

4 Details of Restoration Works

i. Material being used in Restoration works

: Porece Bats

ii. Equipments/Tools being used in Restoration works

: JCB, tractor, road Roller

iii. Procedure taken up in Restoration works

: Immediate restoration of traffic

iv. Restored Length

: 160 mtr

B For Bridge

work found satisfactory

1 Damage Location/Chainage

2 Damage Length

3 Nature of Damage

4 Details of Restoration Works

i. Material being used in Restoration works

ii. Equipments/Tools being used in Restoration works

iii. Procedure taken up in Restoration works

iv. Restored Length

Signature of JE / AE / EE

Signature of Inspector
(Name of Inspector)
प्रमाणित क्षेत्र विभाग
कार्य प्रमाणित, महुनाह

FDR

YEAR (2021-2022)

GENERAL ABSTRACT OF COST

Restoration of Road from S.H.- 74 Bajarangi Ray ke ghar se
Chak Imbrahim to Pashchim Abu Chak Masjid tak in Saraiya
Block under F.D.R., RWD, Works Division, Muzaffarpur East-1

Block :- Saraiya

District :- Muzaffarpur

Sl
No.

Description

Amount

Road Restoration Cost

Rs.

1220774
12,78,000.00


Total

12,78,000.00


Say Rs.

12,78,000.00

1220774-


Junior Engineer
RWD, Works Section
Saraiya


Assitant Engineer
RWD, Works Sub-Div.
Saraiya


Executive Engineer
RWD, Works Division
Muzaffarpur East-1

Say 12.208 lacs

As Per S.E. RWD (M) Circle Muz
Letter No 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD, (M) Division Mahmar

Technically Sanctioned for Rs. 12.208 lacs
(Rs. Twelve lacs twenty thousand eight hundred)
only (provisionally)


Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur
27/12/21


Abstract of Cost & Detailed Estimate for

Restoration of Road from S.H.- 74 Bajarangi Ray ke ghar se Chak
Imbrahim to Pashchim Abu Chak Masjid tak in Saraiya Block under
F.D.R., RWD, Works Division, Muzaffarpur East-1


Sl. No.	SO R	Item of Work	Quantity	Unit	Rate	Amount
1		2	6	7	8	9
1		Providing and laying Brick bats, including all taxes etc. all complete job as per specification and direction of E/I.			2064.52	1220774
		As per M.B	591.30	m ³	2161.18	1277906.00
2	5.6. 2.4	Labour for laying, fitting and fixing NP3 pipe with collors in line level and grade as well providing approved jointing materials and joints properly filled to make them water proof all complete as per specification and direction of E/I. (Hume pipe available within a lead of 40 mtr 1000 mm dia or 100 mm dia NP3 H.P				
		As per M.B	0.00	m	3992.28	1220774 0.00
					Total Rs.	12,77,906.00

Say Rs. ~~12,78,000.00~~

12207742


Junior Engineer
RWD, Works Section
Saraiya

Assitant Engineer
RWD, Works (Sub-Div.
Saraiya


Executive Engineer
RWD, Works Division
Muzaffarpur East-1