




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



L042 to Dakshin Tola





DISTRICT	:-	Samastipur	
DIVISION	:-	Dalsingh Sarai	
BLOCK	:-	SAYWINGAN	
TOTAL LENGTH OF ROAD	:-	0.239	KM
TOTAL COST OF PROJECT	:-	2074.5	Lac

5.58 Lac

Site Photograph

ne of Road:- L042 Dakshin tola

Block- *Sayurman*



30/10/2021

*30/10/21
AE*

SUMMARY OF COST ESTIMAT FOR THE PROJECT

IE OF ROAD :- L042 to Dakshin Tola

RICT

SAMASTIPUR

CK

Amubamgan

S.NO	DESCRIPTION	AMOUNT LAKH
1	E/W	61217.000
2	BRICK BAT	566856.000
	SUB TOTAL:-	628073.000 493965
	12% GST on Total Amount:-	75368.760 59976
	SUB TOTAL:-	6280.730 4940
	Total Cost (including GST and Labour Cess	709722.000

558181

[Signature]
29/10/2021
Junior Engineer

[Signature]
30/10/21
Assistant Engineer

[Signature]
02/12/21
Executive Engineer

RWD, Works Division, Dalsinghsarai

Sanctioned
provisional estimate can be approved for Rs 5,58,181=00 say five
Lakh fifty Eight thousand One Hundred Eighty One
only with C.I.C. 12% C.P 10% only.

[Signature]
10/12/21
T.A

[Signature]
10/12/21
बनौदय बरिबन
प्रवीण कार्य विभाग
कार्य प्रमाण, प्रयत्नोद्ग
10/12/21

FDR
YEAR (2020-2021)
GENERAL ABSTRACT OF COST

DISTRICT :- SAMASTIPUR

CK :-

S. Narayan
S. Narayan

OF ROAD :- L042 to Dakshin Tola

NO	ITEM OF WORK						AMOUNT	
								493965
	TOTAL COST OF CONSTRUCTION					:-	Rs.	709722
					SUB TOTAL	:-	Rs.	709722

[Signature]
20/10/21
Junior Engineer

[Signature]
20/10/21
Assistant Engineer

[Signature]
02-12-21
Executive Engineer
RWD, Works Division,
Dalsinghsarai

493965

Inspection Report for Flood Damage Work

Date: 05/4/22

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Dalsingh sarai

2. Name of Block – Sarairanjan

3. Name of Road/Bridge – L 42 to Dakshin Tola tak sadak Nirmam kanya

A. for Road

1. Damage Location/Chainage : 200m,

2. Damage Length : 239m

3. Nature of Damage : Flood

4. Details of Restoration Works : Restoration work to be done.

i. Material being used in Restoration works : E/W, Brick Bats

ii. Equipments/Tools being used in Restoration Works : Tractor, Labour, Roller

iii. Procedure taken up in Restoration works :

iv. Restored Length : 239m

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

J.E. 05/4/22
A.E. 05/4/22

Executive Engineer,
R.W.D. Works Division,
Dalsingh sarai

Wm. J. D. S. H. S.
factory
Signature
(Name of Inspector)
E. B. Teshing
R.W.D. Works Division