## Inspection Report for Flood Damage Work

Inspection Report to:
Date.:  1. Name of PIUs - Executive Engineer, R. W.D., Works, Division.  Somustipar
2. Name of Block Keelyanpar
-3. Name of Road Bridge SH to Narm ger
1. Damage Location Chainage Lat to 2.36 Km
2. Damage Length 2/8 M
3. Nature of Damage Ditahus
4. Details of Restoration Works : Brichs but's
i. Material being used in Residuation works.
ii. Equipments/Tools being used in Restoration Works:
iii. Procedure taken up in Restoration works:
iv. Restored Length: 218 M
B. for Bridge
1. Damage Location/Chainage
2. Damage Length  3. Nature of Damage
3. Nature of Damage
4. Details of Restoration Works
i. Material being used in Restoration works:
ii. Equipments/Tools being used in Restoration Works:
iii. Procedure taken up in Restoration works:
iv. Restored Length:
I.E. Executive Engineer,  R.W.D. Works Division,  Sema Shi Plan

## Inspection Report for Flood Damage Work

Inspection Report to:
Date.:  1. Name of PIUs - Executive Engineer, R. W.D., Works, Division.  Somustipar
2. Name of Block Keelyanpar
-3. Name of Road Bridge SH to Narm ger
1. Damage Location Chainage Lat to 2.36 Km
2. Damage Length 2/8 M
3. Nature of Damage Ditahus
4. Details of Restoration Works : Brichs but's
i. Material being used in Residuation works.
ii. Equipments/Tools being used in Restoration Works:
iii. Procedure taken up in Restoration works:
iv. Restored Length: 218 M
B. for Bridge
1. Damage Location/Chainage
2. Damage Length  3. Nature of Damage
3. Nature of Damage
4. Details of Restoration Works
i. Material being used in Restoration works:
ii. Equipments/Tools being used in Restoration Works:
iii. Procedure taken up in Restoration works:
iv. Restored Length:
I.E. Executive Engineer,  R.W.D. Works Division,  Sema Shi Plan