SUMMARY OF COST ESTIMATE FOR THE PROJECT

NAME OF ROAD :	EMERGENT REPAIR OF ROAD FROM DUMAR BIGAHA TO DAMAR BIGHA UNDER FDR		
DISTRICT	PATNA		
BLOCK	DHANARUA		
DIVISION	MASAURHI		
Total Damaged length of Road	33.75 m		
SI. No. DESCRIPTION		AMOUNT (LAKHS)	
1	COST OF ITEM		
	TOTAL COST IN LACS =	9.678 9.679	

8.169 los

12.10.21 RWD

AE RWD RWD

Technically sanctioned for Rs. 8:169 Rupees Corne laes sixtees thousand and month does

including five year Maintenance Cost

Estimator R.W.D. Works Circle, Patna

तक्किनकी सलाहकार प्रामीण कार्य विभाग कार्य अंचल, पटना Superintending Engineer
R.W.D. WORKS CIRCLE, PATNA

Inspection Report for Flood Damage Work

D	ate	:-
ע	ale	

1.	Name of PIUs	E.E.	R.W.DLW) DIVISion	Masaurhi

- :- Dhanarua | Emergent repair of Road 2, Name of Block / Road from Duman bigaha to Daman Digaha under FDR
- A. For Road
- :- MBOVRIVER side at 0.500 KM. Damage Location / Chainage 1.
- 2: Damage Length :- 33075 Meler
- : Flank & crust (in some coidir (0.5m) from toe of emberkment due to heavy Flores 3. Nature of Damage
 - i. Material being used in Restoration works :-
 - Equipments / Tools being used in Restoration works: Tractor, J.e. B. Labour. ii.
 - Procedure taken up in Restoration works: Byfilling breach Postion with Restored Length:

 33.75 Meter Manually iii.
 - iv.

Satisfactory

- For Road Bridge В.
- Damage Location / Chainage 1.
- :- | NUI Damage Length 2.
- Nature of Damage 3.
- Details of Restoration Works:-4.
 - Gran Brick bats Material being used in Restoration works:i.
 - Equipments / Tools being used in Restoration works: ii.
 - Procedure taken up in Restoration works: iii.
 - Restored Length: 23.75 M iv.

Name of Inspector **Executive Engineer** R.W.D. Works Division Barh