

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
CH -					
Armed Road - Rewari porchoyat					
Below to Brahman Tali					
Malesita Block Rge.					
N/W - providing and laying					
brick bats for filling in					
ditch --- all cut.					
Qty vide p.no - (1) T.M.B.					
4394					
N/W - Restoration work for					
Flood damage Road.					
Authority - E.B.R.W.D (W) Div. Sitamark					
(1) providing and laying brick					
for filling in ditch --- etc.					
Qty vide p.no - (1) T.M.B.					
105.82 M ³					
21.16 M ³ bats					
84.66 M ³					
M ³ @ 1827 = 25/M ³ - B					154695 = 00
(2) providing Quarry material					
Rubbish for filling the					
voids in brick bats. -					
--- all cut					
Qty vide p.no - (1) T.M.B.					
21.16 M ³					
@ 873 = 01/M ³ - B					18473 = 00
(3) single bamboo palasidly					
width of tube --- 75mm dia					
and closely packed &					
--- Runner - three sets					
--- all cut					
Qty vide p.no - (1) T.M.B.					
43 M @ 140 = 40/M					6037 = 00

Continuation

CA 12
20.04.22

B 179205 = 00
20179201 = 00

20/4/22
JE