## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 8/06/2022 District: ROHTAS		
Division	1: BIKRAMGUNJ Length (km): 2-30 Km		
	fthe Road: BIKRAMGUNJ DINARA PATH KOLHA	RCC BRIDGE	TO MILK
Scheme	Programme: MMGSY		
Sl. No.	Parameters to be checked	Remarks (S/U)	
1.	Pavement	•	
a)	Condition of Surfacing	5	
b)	Riding Quality	5	
c)	Road Camber	2	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_	
e)	Contraction Joints provided or not (CC Pavement)	S	
f)	Compaction of flank/slope & raincuts if any	S	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	_	
c)	Condition of railings/slab/approach for Bridges	_	
d)	Condition of Vent Clearance	5	
Observa	tion Remarks:-		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S	
Observat	tion Remarks:-		
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall I	Rating : Satisfactory (S)/ Unsatisfactory (U)	SATISFACTO	PY
Name of Designat		313 816/2022	
	(Sig		

Vitash Kumar 8/6/2027