



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

BIHAR RURAL ROADS PROJECT

Bihar Rural Road Development Agency (BRRDA)

YEAR (2021 - 2022)

FDR

PART A

STATE :- BIHAR
DISTRICT :- Samastipur
BLOCK :- Sarairanjan

NAME OF ROAD :- Detailed Estimate For Repair of Flood
Damaged in L038 To Dakshin Tola

TOTAL COST OF PROJECT :- Rs. 13.5735 Lacs
1300 OK (12)

SUBMITTED BY:

EXECUTIVE ENGINEER

RWD (W) DIVISION, DALSINGHSARAI

SAMASTIPUR

FDR

YEAR (2021 - 2022)

GENERAL ABSTRACT OF COST

Block:--Sarairanjan


District:--Samastipur


Name of Road:--


Detailed Estimate For Repair of Flood Damaged in L038 To
Dakshin Tola

SL. No.	Item of Work	Amount
A		13.5735
	TOTAL COST OF REPAIR DAMAGE	15.859 Lacs
	Sub Total= (A)	15.859 Lacs
		13.5735
	TOTAL cost of project	15.859 Lacs


13.5735 lacs



27/11/21
Junior Engineer
RWD (w) Section ,
Sarairanjan


27/11/21
Asstt. Engineer
RWD (w) Sub Division , Sarairanjan


02.12.21
Executive Engineer
RWD (w) Division,
Dalsinghsarai

Sanctioned
for repair of flood damaged in Rs 13,57,350.00 say Thirteen
Lacs fifty seven thousand three hundred fifty only
including OMC 12% C.P 10% only.



10/12/21
T.A


10.12.21
T.A
10/12/21


SUMMARY OF COST ESTIMATE FOR THE PROJECT

NAME OF ROAD : Detailed Estimate For Repair of Flood Damaged in L038 To
Dakshin Tola
DISTRICT Samastipur
BLOCK Sarairanjan


Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	BRICK BAT	114 2/4 13.372
	SUB TOTAL OF PAVEMENT COST IN LACS =	11.945 13.372
	Sub Total :-	1. 13.372
	12% GST on Total Amount :-	1.374 1.605
	1% Lab Cess :-	.1145 0.134
	Seigniorage Fee @ 10%	.64 0.748
	TOTAL COST OF PROJECT IN LACS(including GST 12% & 1% Lab Cess)(A+B+C) :-	15.859


Junior Engineer

RWD (w)Section , Sarairanjan


Assistant Engineer

RWD (w)Sub Division , Sarairanjan


Executive Engineer
RWD (w) Division,
Dalsinghsarai

Inspection Report for Flood Damage Work

Date: 05/4/22

1. Name of PIUs - Executive Engineer, R.W.D., Works, Division,

2. Name of Block - Sarairanjan

3. Name of Road/Bridge - L38 to Dakshin Tola

A. for Road

1. Damage Location/Chainage :

2. Damage Length : 1.095 km

3. Nature of Damage : Flood

4. Details of Restoration Works : Restoration work to be done.

i. Material being used in Restoration works : Brick Bats

ii. Equipments/Tools being used in Restoration Works : Tractor, Labour, Roller

iii. Procedure taken up in Restoration works :

iv. Restored Length : 1.095 km

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

J.E. 05/4/22

A.E.

Executive Engineer,
R.W.D. Works Division,
Dakshin Tola

Signature
(Name of Inspector)
B. G. Tasing
RWD works division