




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



Repair of Road From T05 to Madhaipur

STRICT			
	:-	Samastipur	
VISION	:-	Dalsingh Sarai	
OCK	:-	Dalsinghsarai	
TAL LENGTH OF ROAD	:-	0.025	KM
TAL COST OF PROJECT	:-	2.81	Lac

Site Photograph

me of Road:-

Block-dalsinghsarai



Alenda
31/10/21
J-E

SUMMARY OF COST ESTIMATE FOR THE PROJECT

NAME OF ROAD :- Repair of Road From T05 to Madhaipur

DISTRICT

SAMASTIPUR

WORK

Dalsinghsarai

S.NO	DESCRIPTION	AMOUNT LAKH
1	BRICK BAT	248948.000
	SUB TOTAL:-	248948.000
	12% GST on Total Amount:-	29873.760
	1% Labour Cess	2489.480
	Total Cost (including GST and Labour Cess)	281311.240

Add 10% Suggestion for material

14346 = 00

Total Rs 2,95,657 = 00

[Signature]
31/10/21

Junior Engineer

[Signature]
31/10/21

Assistant Engineer

[Signature]
01/12/21

Executive Engineer

(W) Section, Dalsinghsarai RWD (W) Sub Division, Dalsinghsarai

RWD, Works Division, Dalsinghsarai

Sand roped
for 2,95,700 = 10 say
Longer money for thousand seven hundred say Two
including overhead use and C Profit

[Signature]
10/12/21
T.A

FDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST

WORK :- Dalsinghsarai

DISTRICT :- SAMASTIPUR

NAME OF ROAD :- Repair of Road From T05 to Madhalpur

NO	ITEM OF WORK						AMOUNT	
A								
	TOTAL COST OF CONSTRUCTION							
						:-	Rs.	281311
						SUB TOTAL	:-	Rs. 281311

Asin
31/10/21
Junior Engineer

RWD (W) Section, Dalsinghsarai

U. G.
31/10/21
Assistant Engineer
RWD (W) Sub Division,
Dalsinghsarai

P. K. S.
01/11/21
Executive Engineer
RWD, Works Division,
Dalsinghsarai

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Dalsinghsarai

2. Name of Block – Dalsinghsarai

3. Name of Road/Bridge – Tos to Madhaipur.

A. for Road

1. Damage Location/Chainage : 25.683248' N 85.840071° E
25.6768' N 85.843488° E.

2. Damage Length : 0.025 km.

3. Nature of Damage : due to heavy rain

4. Details of Restoration Works :

i. Material being used in Restoration works : Brick bat

ii. Equipments/Tools being used in Restoration Works : tractor/ roller

iii. Procedure taken up in Restoration works : -

iv. Restored Length : 0.025 km

B. for Bridge

1. Damage Location/Chainage : -

2. Damage Length : -

3. Nature of Damage : -

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Abin
05/04/22
I.E.

Abin
05/04/22
A.E.

Abin
05/04/22
Executive Engineer,
R.W.D. Works Division,
Dalsinghsarai

Wmson Lakshar
Chary
05/04/22
Signature
(Name of Inspector)
E.C. Teshing
RWD works division