




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



Chakdaulat To Akha Road

DISTRICT	1-	Samastipur	
DIVISION	1-	Dalsingh Sarai	
BLOCK	1-	Ujilarpur	
TOTAL LENGTH OF ROAD	1-	0.028	KM
TOTAL COST OF SURFACE RENEUAL	1-	2120 2.633	Lac
TOTAL COST OF PROJECT	1-	2120 2.633	Lac

Site Photographs

2.3

NAME OF ROAD :- Chakdaulat To Akha Road Village


BLOCK :- Ujiyarpur

District:- Samastipur

1




2



3



4



5



6



25/10/2021

25/10/21
AE

FLOOD DAMAGED REPORT

GENERAL ABSTRACT OF COST

Block:-- Ujjarpur


District:- Samastipur

Length of Road:-- 0.028 KM


Name of Road:-- Chakdaulat To Akha Road

SL. No.	Item of Work	Amount
A	TOTAL COST OF CONSTRUCTION	: <u>2.120</u> 2.633 Lacs
	TOTAL	: 2.655 Lacs

2.120 lacs



Junior Engineer


Asstt. Engineer



Executive Engineer

SE
RWD


Sanction of
Provisional Technical work approved for Rs 2.12 Lacs say Two -
Lakh Twelve thousand only including O.H.C
1.2% C.P 10%


10/12/21

T.A


10.12.21

बनाकर बांधकर
बांधीय कार्य विभाग
बांधी संयुक्त, प्रयत्नोप


10.12.21

GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD : Chakdohat To Aikha Road
DISTRICT : Samantpur
BLOCK : Dhanpur
DIVISION : Dain Singh Sarai
LENGTH OF ROAD (in Km) : 0.028

Sl. No.	DESCRIPTION	Amount	1 % Labour Cess	12 % GST	1% Labour Cess & 12% GST AMOUNT (LAKHS)
PART - A INITIAL RECTIFICATION INCLUDING SURFACE RENEWAL					
1	Brick Sets	1.779	0.022	0.270	2.540
2	(By mix in place method) For Grading II Material	0.082	0.001	0.010	0.093
3	Supply For Bamboo	0.000	0.000	0.000	0.000
4	Bamboo Piles	0.000	0.000	0.000	0.000
5	Bamboo Woven Checkers	0.000	0.000	0.000	0.000
6	Bamboo Ropers	0.000	0.000	0.000	0.000
SUB TOTAL OF SURFACE RENEWAL		1.879	0.023	0.280	2.172
TOTAL COST OF PROJECT IN LACS =		2.230	0.023	0.280	2.633

1.877 0.018 0.225 2.120

[Signature]
JE
RWD

[Signature]
25/12/21
AE
RWD

[Signature]
2.12.21
EE
RWD

Inspection Report for Flood Damage Work

Date.: 5/4/22

1. Name of PIUs - Executive Engineer, R.W.D., Works, Division,

2. Name of Block - Wingash

3. Name of Road/Bridge - Chardulet to Akha road

A. for Road

1. Damage Location/Chainage 25:763552, 25:800776, 25:766559

2. Damage Length : 85, 810733

3. Nature of Damage : 0.29 km
soil to heavy rain

4. Details of Restoration Works : mud as belts

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length : —

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

5/4/22
J.E.

5/4/22
A.E.

Executive Engineer,
R.W.D. Works Division,
Wingash

Wingash Station
factory

5/4/22
Signature
(Name of Inspector)
E. B. Teshigahara
RWD works division