

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-2

पत्रांक. 203.....

सासाराम 2/दिनांक. 4/03/22

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-2

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018 MR(3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विश्वासभाजन


04/03/22

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-2

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to February 2022

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
s1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	1145.43532	Certified that out of Rs. 1145.43532 lakh of grants-in-aid sanctioned during the years 2018-21 Infavor of EE,RWD works division Sasaram-2 a sum of Rs 1134.29907 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 11.13625 lakh remaining unutilized at the end of the period under report.
Total:			1145.43532	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.

3. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD works.


Executive Engineer
Rural Works Department
Works Div. Sasaram-2

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-2

Registation Format for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-2

Sl no.	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up to date expenditure as per MIS (in Lakh)	Registation done work (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/2020-21 sasaram-02/06	Gorari Sakla Pwrd Road - Hatia	10301002085	Lt-3274/Date- 10.09.20	2.410	92.88400	64.83946	26.92165	RWD/SSM- 2/MR- 63/2020-21 Dt.12.11.2021	11.11.22		2406	25.00	5.00%	0.00000	0.00000	58.35551	
Total															0.00000	0.00000	58.35551	

Executive Engineer
Rural Works Department
Works Division, Sasaram-2

04/10/22

Name of Road : Gorari Sakla PWD Road to Hatia

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	TEGORY ROAD	Latitude	Longitude	Event
03/3/22	7:30:45	88	0.1	240	0	2400	2815	G	25.13998	84.33013	Normal
03/3/22	7:31:0	88	0.1	260	10.1	2600	3015	G	25.13973	84.33114	Normal
03/3/22	7:31:22	88	0.1	130	10.1	1300	1715	G	25.13961	84.3321	Normal
03/3/22	7:31:57	88	0.1	20	10.1	200	615	G	25.13945	84.33306	Normal
03/3/22	7:32:0	88	0.1	200	10.1	2000	2415	G	25.13937	84.33409	Normal
03/3/22	7:32:32	88	0.1	120	10.1	1200	1615	G	25.13925	84.33505	Normal
03/3/22	7:33:0	88	0.1	210	10.1	2100	2515	G	25.13903	84.33601	Normal
03/3/22	7:33:7	88	0.1	270	10.1	2700	3115	G	25.13885	84.337	Normal
03/3/22	7:33:42	88	0.1	260	10.1	2600	3015	G	25.13858	84.33796	Speed Breaker
03/3/22	7:34:0	88	0.1	210	20.2	2100	2515	G	25.13818	84.33877	Normal
03/3/22	7:34:17	88	0.1	260	20.2	2600	3015	G	25.13798	84.33973	Normal
03/3/22	7:34:17	88	0.1	280	20.2	2800	3215	G	25.13774	84.34069	Normal
03/3/22	7:34:17	88	0.1	210	20.2	2100	2515	G	25.13767	84.34162	Normal
03/3/22	7:35:0	88	0.1	190	20.2	1900	2315	G	25.13766	84.34263	Normal
03/3/22	7:35:0	88	0.1	110	20.2	1100	1515	G	25.13749	84.3436	Normal
03/3/22	7:35:28	88	0.1	170	20.2	1700	2115	G	25.13746	84.3446	Normal
03/3/22	7:35:28	88	0.1	270	20.2	2700	3115	G	25.13732	84.34554	Normal
03/3/22	7:36:3	88	0.1	130	10.1	1300	1715	G	25.13716	84.34658	Normal
03/3/22	7:37:14	88	0.1	120	0	1200	1615	G	25.13724	84.34589	Normal
03/3/22	7:37:49	88	0.1	240	20.2	2400	2815	G	25.13741	84.34495	Normal
03/3/22	7:38:0	88	0.1	280	20.2	2800	3215	G	25.13746	84.34397	Normal
03/3/22	7:38:24	88	0.1	280	20.2	2800	3215	G	25.13756	84.34303	Normal
03/3/22	7:38:24	88	0.1	200	20.2	2000	2415	G	25.13772	84.34202	Normal
03/3/22	7:38:24	88	0.1	120	20.2	1200	1615	G	25.13766	84.34108	Normal
Total			2.4								

$Y = 0 * X^2 + 1.000 * X + 415.2$
 $X = 1991$
 $Y = 2406.2$

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

Prepared
03.03.22
EF

04/03/22
EF

Name of Customer: **Sushma Associate Pvt Ltd**
 Name of Work/Road: **Gorai Sakia PWD Road to Hatia Road**
 Lab Job number: **30**
 Date: **3/3/2022**
 Section No: **30**


Test Date: **3/3/2022** Road Name: **Gorai Sakia PWD Road to Hatia**
 Machine No: **391** Road Type: **(R) RURAL ROAD**
 Station No: **10479** Side: **Arakot** Interval: **1000**
 Station E No: **10512**
 Weather: **Normal** UV Range: **385 To 4000** mm/ftm
 Station Location: **25 13973.843** Dist Range: **0 To 0.616** 0.028 * 1000 m
 End Location: **25 13787.843** Elevation: **Y = 0 * X + 2 * 1.000 * X + 415.2**

Print Generate Report and Graph

Redraw Graph

Map View

File: 1 Pump Flag and Report/Request Nov 2020/46. Sushma Associate SSM-2 25.02.22/25020909-Graph.xls.
 Name of Customer: **Sushma Associate Pvt Ltd**, Name of Work/Road: **Gorai Sakia PWD Road to Hatia**, Lab Job



Good
03.03.22
JE

04/03/22
JE