

अभिहित किया जा है कि इस भी पुस्त
मे मशीन के द्वारा प्रमत्त कुल 100 एक सी
पन्ने है यह मा श्री. अमृत कुमार सिंह
सहायक अभियन्ता ग्रामीण कार्य विभाग
कार्य अवर प्रमण्डल 29/06/12 को निर्गत
जाता है।

18/06/12
कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल, मधुबनी
18/06/12

Schedule XLV- Form No.- 134.

_____DIVISIUN

_____SUB-DIVISION

MEASUREMENT BOOK

No. 2610

Name of officer _____

Date of fist entry _____

Date of last entry _____

Name of the work-
 Situation of work-
 Agency by which work is executed-
 Date of measurement-
 No. and date of agreement-
 (These four lines should be repeated at the commencement of
 the measurements relating to each work)

01

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH - MR - 3054 / FDR					
Item no. 10					
name of work: - Temporary -					
Restoration and motorable of					
Road from Sakki South to					
Sakki north under F.O.R. - 2021-22					
from Kharjanti Block					
Agency: - Departmental					
Authority: - E. E. R. W. D. madhubani					
Date of entry: - 08.12.2021					

Item no. 11 - providing and					
filling Brick Bats in ditches					
including cost of Brick					
Bats and labour all complete					
Job as per - - - - - E12					
CH -					
1.050 KM	1 X 4	20 X	1.15 X 0.075 =	0.362 M ³	
to	1 X 2.50 X	1.10 X	0.075 =	0.21 "	
2.55 KM	1 X 1.40 X	1.50 X	0.075 =	0.16 "	
	1 X 1.50 X	1.20 X	0.075 =	0.13 "	
	1 X 1.60 X	1.80 X	0.075 =	0.21 "	
	1 X 6.50 X	1.5 X	0.10 =	0.975 "	
	1 X 10.20 X	1.40 X	0.10 =	1.428 "	
	1 X 3.80 X	0.95 X	0.10 =	0.361 "	
	1 X 5.50 X	1.00 X	0.10 =	0.55 "	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1X4.10X	1.00X	0.10	=	0.41 m ³
	1X5.10X	2.0X	0.125	=	0.140
	1X6.60X	0.85X	0.075	=	0.4211
	1X3.00X	1.20X	0.075	=	0.2711
	1X3.20X	1.10X	0.075	=	0.2611
	1X6.80X	1.90X	0.075	=	0.9694
	1X3.30X	0.95X	0.075	=	0.2311
	1X1.01X	0.60X	0.10	=	0.0611
	4.80X	1.50X	0.10	=	0.7211
	1X1.00X	1.00X	0.10	=	0.0011
	1X6.80X	2.80X	0.10	=	1.9611
	1X9.00X	1.60X	0.10	=	1.4411
	1X10.10X	1.50X	0.10	=	1.5111

	1X10.00X	1.50X	0.075	=	1.1211
	1X6.60X	0.80X	0.10	=	0.5211
	1X3.00X	1.25X	0.075	=	0.2811
	1X5.50X	1.50X	0.10	=	0.8211
	1X25X	3.75X	0.30	=	28.1211
	1X11.50X	1.10X	0.075	=	0.9511
	1X7.20X	1.80X	0.075	=	0.9811
	1X4.20X	1.50X	0.10	=	0.6304
	1X5.10X	1.20X	0.125	=	0.7611
	1X10.50X	1.50X	0.075	=	1.0511
	1X6.50X	1.20X	0.10	=	0.7811
	1X5.00X	0.60X	0.10	=	0.3011
	1X3.80X	1.00X	0.10	=	0.3804
	1X7.50X	1.20X	0.15	=	1.3511
			Total =		52.0912 ³

