

Date:- 04-12-2021

Inspection Report for Flood damage work

(Year 2021-22)

1. Name of PIUs- DHAMDABA

2. Name of Block/Road- DHAMDABA

A. For Road - MILKIYA NAYA TOLA TO MILKIYA MAHABAD

1. Damage Location/Chainage: AT CH -

2. Damage Length: 9.0 Mtr

3. Nature of Damage: -

4. Details of Restoration:

i Material being used in Restoration

: Earthwork, Brick bats

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

: Ch 9.0 Mtr.

B. For Bridge

1. Damage Location/Chainage:

2. Damage Length:

3. Nature of Damage:

4. Details of Restoration:

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

P. Kumar
04-12-21

Signature of JE/AE/EE

04/12/2021
A.E.

Executive Engineer
Rural Works Department
Works Division Dhamsabai (Pune)

संगोपसद

Signature
Executive Engineer
(Name of Executive Engineer)
PUNE

Scanned with CamScanner

Scanned by CamScanner

Scanned with CamScanner

Scanned with CamScanner

Scanned with CamScanner

GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD : MILKIYA NAYA TOLA TO MILKIYA MAIN ROAD
DISTRICT PURNEA
DIVISION DHAMDAHA
BLOCK DHAMDAHA
LENGTH OF ROAD (IN KM) 0.000

Sl. No.	ITEM OF WORK	AMOUNT (LAKHS)
1	EARTH WORK	0.005
2	HUME PIPE	0.000
3	BRICK BAT	1.036
4	SAND BAGS	0.000
5	BAMBOO WORK	0.000
6	STEEL DRUM SHEET	0.000
TOTAL COST OF PROJECT =		1.041
Add G.S.T. @ 12%		0.125
Add Labour Cess @ 1%		0.010
Add Saigniorage Fee @ 10%		0.049
Total Cost of Restoration Work =		1.225

P. Kumar
26-10-21
J.E.
RWD

hmk
28/10/2021
A.E.
RWD

Q 28.10.21
E.E.
RWD

Pratik Technically section for Rs. 122500 (one lac twenty two thousand five hundred) only.

hmk
8.12.21

अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, पूर्णिया

Sum
8.12.2021
A.E.